

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/5/06	06BR0503-01	Southwest Area (sidewalk bridge level)	4/5/06	0.57	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST2-4/5/06	06BR0503-02	Southeast Area (sidewalk bridge level)	4/5/06	0.55	Mercury	EPA 324/1631	BRL	4/7/06	< 27.0	No	No	
TotalHg-ST4-4/5/06	06BR0503-03	Northwest Area (street-level)	4/5/06	0.58	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST5-4/5/06	06BR0503-04	Firehouse #10 (roof level)	4/5/06	0.58	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST10-4/5/06	06BR0503-05	North Side Sidewalk Bridge	4/5/06	0.58	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST11-4/5/06	06BR0503-06	90 Trinity Place (roof level)	4/5/06	0.57	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST12-4/5/06	06BR0503-07	110 Greenwich Street (roof level)	4/5/06	0.57	Mercury	EPA 324/1631	BRL	4/7/06	< 26.0	No	No	
TotalHg-ST13-4/5/06	06BR0503-08	Marriott Hotel, 38th Floor (roof level)	4/5/06	0.55	Mercury	EPA 324/1631	BRL	4/7/06	< 27.0	No	No	
TotalHg-ST14-4/5/06	06BR0503-09	West Face - South end at corner (scaffolding level)	4/5/06	0.54	Mercury	EPA 324/1631	BRL	4/7/06	< 28.0	No	No	
TotalHg-ST15-4/5/06	06BR0503-10	South Face - East end at corner (scaffolding level)	4/5/06	0.54	Mercury	EPA 324/1631	BRL	4/7/06	< 28.0	No	No	
TotalHg-ST16-4/5/06	06BR0503-11	East Face - North end at corner (scaffolding level)	4/5/06	0.54	Mercury	EPA 324/1631	BRL	4/7/06	< 28.0	No	No	
TotalHg-ST17-4/5/06	06BR0503-12	North Face - West end at corner (scaffolding level)	4/5/06	0.53	Mercury	EPA 324/1631	BRL	4/7/06	< 28.0	No	No	
TotalHg-ST1-4/6/06	06BR0514-01	Southwest Area (sidewalk bridge level)	4/6/06	0.57	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST2-4/6/06	06BR0514-02	Southeast Area (sidewalk bridge level)	4/6/06	0.53	Mercury	EPA 324/1631	BRL	4/8/06	< 28.0	No	No	
TotalHg-ST4-4/6/06	06BR0514-03	Northwest Area (street-level)	4/6/06	0.57	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST5-4/6/06	06BR0514-04	Firehouse #10 (roof level)	4/6/06	0.55	Mercury	EPA 324/1631	BRL	4/8/06	< 27.0	No	No	
TotalHg-ST10-4/6/06	06BR0514-05	North Side Sidewalk Bridge	4/6/06	0.57	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST11-4/6/06	06BR0514-06	90 Trinity Place (roof level)	4/6/06	0.58	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST12-4/6/06	06BR0514-07	110 Greenwich Street (roof level)	4/6/06	0.60	Mercury	EPA 324/1631	BRL	4/8/06	< 25.0	No	No	
TotalHg-ST13-4/6/06	06BR0514-08	Marriott Hotel, 38th Floor (roof level)	4/6/06	0.58	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST14-4/6/06	06BR0514-09	West Face - South end at corner (scaffolding level)	4/6/06	0.58	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST15-4/6/06	06BR0514-10	South Face - East end at corner (scaffolding level)	4/6/06	0.58	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST16-4/6/06	06BR0514-11	East Face - North end at corner (scaffolding level)	4/6/06	0.58	Mercury	EPA 324/1631	BRL	4/8/06	< 26.0	No	No	
TotalHg-ST17-4/6/06	06BR0514-12	North Face - West end at corner (scaffolding level)	4/6/06	0.59	Mercury	EPA 324/1631	BRL	4/8/06	< 25.0	No	No	