

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/7/08	0815020-01	Southwest Area (sidewalk bridge level)	4/7/08	0.58	Mercury	EPA 324/1631	BRL	4/9/08	< 26.0	No	No	
TotalHg-ST2-4/7/08	0815020-02	Southeast Area (sidewalk bridge level)	4/7/08	0.57	Mercury	EPA 324/1631	BRL	4/9/08	< 26.0	No	No	
TotalHg-ST4-4/7/08	0815020-03	Northwest Area (street-level)	4/7/08	0.58	Mercury	EPA 324/1631	BRL	4/9/08	< 26.0	No	No	
TotalHg-ST5-4/7/08	0815020-04	Firehouse #10 (roof level)	4/7/08	0.56	Mercury	EPA 324/1631	BRL	4/9/08	< 27.0	No	No	
TotalHg-ST10-4/7/08	0815020-05	North Side Sidewalk Bridge	4/7/08	0.45	Mercury	EPA 324/1631	BRL	4/9/08	< 33.0	No	No	
TotalHg-ST100-4/7/08 FD	0815020-13	Station 10 Field Duplicate	4/7/08	0.54	Mercury	EPA 324/1631	BRL	4/9/08	< 28.0	No	No	
TotalHg-ST11-4/7/08	0815020-06	90 Trinity Place (roof level)	4/7/08	0.56	Mercury	EPA 324/1631	BRL	4/9/08	< 27.0	No	No	
TotalHg-ST12-4/7/08	0815020-07	110 Greenwich Street (roof level)	4/7/08	0.58	Mercury	EPA 324/1631	BRL	4/9/08	< 26.0	No	No	
TotalHg-ST13-4/7/08	0815020-08	Marriott Hotel, 38th Floor (roof level)	4/7/08	0.45	Mercury	EPA 324/1631	BRL	4/9/08	< 33.0	No	No	
TotalHg-ST14-4/7/08	0815020-09	West Face - South end at corner (scaffolding level)	4/7/08	0.56	Mercury	EPA 324/1631	BRL	4/9/08	< 27.0	No	No	
TotalHg-ST15-4/7/08	0815020-10	South Face - East end at corner (scaffolding level)	4/7/08	0.56	Mercury	EPA 324/1631	BRL	4/9/08	< 27.0	No	No	
TotalHg-ST16-4/7/08	0815020-11	East Face - North end at corner (scaffolding level)	4/7/08	0.57	Mercury	EPA 324/1631	BRL	4/9/08	< 26.0	No	No	
TotalHg-ST17-4/7/08	0815020-12	North Face - West end at corner (scaffolding level)	4/7/08	0.60	Mercury	EPA 324/1631	BRL	4/9/08	< 25.0	No	No	
TotalHg-ST1-4/8/08	0815028-01	Southwest Area (sidewalk bridge level)	4/8/08	0.59	Mercury	EPA 324/1631	BRL	4/10/08	< 25.0	No	No	
TotalHg-ST2-4/8/08	0815028-02	Southeast Area (sidewalk bridge level)	4/8/08	0.63	Mercury	EPA 324/1631	BRL	4/10/08	< 24.0	No	No	
TotalHg-ST4-4/8/08	0815028-03	Northwest Area (street-level)	4/8/08	0.55	Mercury	EPA 324/1631	BRL	4/10/08	< 27.0	No	No	
TotalHg-ST5-4/8/08	0815028-04	Firehouse #10 (roof level)	4/8/08	0.57	Mercury	EPA 324/1631	BRL	4/10/08	< 26.0	No	No	
TotalHg-ST10-4/8/08	0815028-05	North Side Sidewalk Bridge	4/8/08	0.58	Mercury	EPA 324/1631	BRL	4/10/08	< 26.0	No	No	
TotalHg-ST11-4/8/08	0815028-06	90 Trinity Place (roof level)	4/8/08	0.56	Mercury	EPA 324/1631	BRL	4/10/08	< 27.0	No	No	
TotalHg-ST12-4/8/08	0815028-07	110 Greenwich Street (roof level)	4/8/08	0.55	Mercury	EPA 324/1631	BRL	4/10/08	< 27.0	No	No	
TotalHg-ST13-4/8/08	0815028-08	Marriott Hotel, 38th Floor (roof level)	4/8/08	0.56	Mercury	EPA 324/1631	BRL	4/10/08	< 27.0	No	No	
TotalHg-ST14-4/8/08	0815028-09	West Face - South end at corner (scaffolding level)	4/8/08	0.57	Mercury	EPA 324/1631	BRL	4/10/08	< 26.0	No	No	
TotalHg-ST15-4/8/08	0815028-10	South Face - East end at corner (scaffolding level)	4/8/08	0.60	Mercury	EPA 324/1631	BRL	4/10/08	< 25.0	No	No	
TotalHg-ST16-4/8/08	0815028-11	East Face - North end at corner (scaffolding level)	4/8/08	0.53	Mercury	EPA 324/1631	BRL	4/10/08	< 28.0	No	No	
TotalHg-ST17-4/8/08	0815028-12	North Face - West end at corner (scaffolding level)	4/8/08	0.59	Mercury	EPA 324/1631	BRL	4/10/08	< 25.0	No	No	