

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-4/12/06	06BR0536-01	Southwest Area (sidewalk bridge level)	4/12/06	0.57	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST2-4/12/06	06BR0536-02	Southeast Area (sidewalk bridge level)	4/12/06	0.57	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST4-4/12/06	06BR0536-03	Northwest Area (street-level)	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST5-4/12/06	06BR0536-04	Firehouse #10 (roof level)	4/12/06	0.57	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST10-4/12/06	06BR0536-05	North Side Sidewalk Bridge	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST100FD-4/12/06	06BR0536-13	Station 10 Field Duplicate	4/12/06	0.59	Mercury	EPA 324/1631	BRL	4/14/06	< 25.0	No	No	
TotalHg-ST11-4/12/06	06BR0536-06	90 Trinity Place (roof level)	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST12-4/12/06	06BR0536-07	110 Greenwich Street (roof level)	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST13-4/12/06	06BR0536-08	Marriott Hotel, 38th Floor (roof level)	4/12/06	0.55	Mercury	EPA 324/1631	BRL	4/14/06	< 27.0	No	No	
TotalHg-ST14-4/12/06	06BR0536-09	West Face - South end at corner (scaffolding level)	4/12/06	0.57	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST15-4/12/06	06BR0536-10	South Face - East end at corner (scaffolding level)	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST16-4/12/06	06BR0536-11	East Face - North end at corner (scaffolding level)	4/12/06	0.58	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST17-4/12/06	06BR0536-12	North Face - West end at corner (scaffolding level)	4/12/06	0.57	Mercury	EPA 324/1631	BRL	4/14/06	< 26.0	No	No	
TotalHg-ST1-4/13/06	06BR0538-01	Southwest Area (sidewalk bridge level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST2-4/13/06	06BR0538-02	Southeast Area (sidewalk bridge level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST4-4/13/06	06BR0538-03	Northwest Area (street-level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST5-4/13/06	06BR0538-04	Firehouse #10 (roof level)	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST10-4/13/06	06BR0538-05	North Side Sidewalk Bridge	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST11-4/13/06	06BR0538-06	90 Trinity Place (roof level)	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST12-4/13/06	06BR0538-07	110 Greenwich Street (roof level)	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST13-4/13/06	06BR0538-08	Marriott Hotel, 38th Floor (roof level)	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST14-4/13/06	06BR0538-09	West Face - South end at corner (scaffolding level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST15-4/13/06	06BR0538-10	South Face - East end at corner (scaffolding level)	4/13/06	0.57	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST16-4/13/06	06BR0538-11	East Face - North end at corner (scaffolding level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	
TotalHg-ST17-4/13/06	06BR0538-12	North Face - West end at corner (scaffolding level)	4/13/06	0.58	Mercury	EPA 324/1631	BRL	4/15/06	< 26.0	No	No	