

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-4/12/08	0816013-01	Southwest Area (sidewalk bridge level)	4/12/08	0.56	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST2-4/12/08	0816013-02	Southeast Area (sidewalk bridge level)	4/12/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST4-4/12/08	0816013-03	Northwest Area (street-level)	4/12/08	0.57	Mercury	EPA 324/1631	BRL	4/15/08	< 26.0	No	No	
TotalHg-ST5-4/12/08	0816013-04	Firehouse #10 (roof level)	4/12/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST10-4/12/08	0816013-05	North Side Sidewalk Bridge	4/12/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST11-4/12/08	0816013-06	90 Trinity Place (roof level)	4/12/08	0.57	Mercury	EPA 324/1631	BRL	4/15/08	< 26.0	No	No	
TotalHg-ST12-4/12/08	0816013-07	110 Greenwich Street (roof level)	4/12/08	0.59	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST13-4/12/08	0816013-08	Marriott Hotel, 38th Floor (roof level)	4/12/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST14-4/12/08	0816013-09	West Face - South end at corner (scaffolding level)	4/12/08	0.58	Mercury	EPA 324/1631	BRL	4/15/08	< 26.0	No	No	
TotalHg-ST15-4/12/08	0816013-10	South Face - East end at corner (scaffolding level)	4/12/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST16-4/12/08	0816013-11	East Face - North end at corner (scaffolding level)	4/12/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST17-4/12/08	0816013-12	North Face - West end at corner (scaffolding level)	4/12/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST1-4/13/08	0816014-01	Southwest Area (sidewalk bridge level)	4/13/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST2-4/13/08	0816014-02	Southeast Area (sidewalk bridge level)	4/13/08	0.56	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST4-4/13/08	0816014-03	Northwest Area (street-level)	4/13/08	0.55	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST5-4/13/08	0816014-04	Firehouse #10 (roof level)	4/13/08	0.59	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST10-4/13/08	0816014-05	North Side Sidewalk Bridge	4/13/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST11-4/13/08	0816014-06	90 Trinity Place (roof level)	4/13/08	0.53	Mercury	EPA 324/1631	BRL	4/15/08	< 28.0	No	No	
TotalHg-ST12-4/13/08	0816014-07	110 Greenwich Street (roof level)	4/13/08	0.54	Mercury	EPA 324/1631	BRL	4/15/08	< 28.0	No	No	
TotalHg-ST13-4/13/08	0816014-08	Marriott Hotel, 38th Floor (roof level)	4/13/08	0.53	Mercury	EPA 324/1631	BRL	4/15/08	< 28.0	No	No	
TotalHg-ST14-4/13/08	0816014-09	West Face - South end at corner (scaffolding level)	4/13/08	0.58	Mercury	EPA 324/1631	BRL	4/15/08	< 26.0	No	No	
TotalHg-ST15-4/13/08	0816014-10	South Face - East end at corner (scaffolding level)	4/13/08	0.56	Mercury	EPA 324/1631	BRL	4/15/08	< 27.0	No	No	
TotalHg-ST16-4/13/08	0816014-11	East Face - North end at corner (scaffolding level)	4/13/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	
TotalHg-ST17-4/13/08	0816014-12	North Face - West end at corner (scaffolding level)	4/13/08	0.60	Mercury	EPA 324/1631	BRL	4/15/08	< 25.0	No	No	