

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300	3,000			
									EPA Site Specific Trigger Levels				
TotalHg-ST1-4/16/08	0816034-01	Southwest Area (sidewalk bridge level)	4/16/08	0.55	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST2-4/16/08	0816034-02	Southeast Area (sidewalk bridge level)	4/16/08	0.55	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST4-4/16/08	0816034-03	Northwest Area (street-level)	4/16/08	0.56	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST5-4/16/08	0816034-04	Firehouse #10 (roof level)	4/16/08	0.56	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST10-4/16/08	0816034-05	North Side Sidewalk Bridge	4/16/08	0.59	Mercury	EPA 324/1631	BRL	4/18/08	< 25.0		No	No	
TotalHg-ST11-4/16/08	0816034-06	90 Trinity Place (roof level)	4/16/08	0.56	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST12-4/16/08	0816034-07	110 Greenwich Street (roof level)	4/16/08	0.53	Mercury	EPA 324/1631	BRL	4/18/08	< 28.0		No	No	
TotalHg-ST13-4/16/08	0816034-08	Marriott Hotel, 38th Floor (roof level)	4/16/08	0.56	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST14-4/16/08	0816034-09	West Face - South end at corner (scaffolding level)	4/16/08	0.58	Mercury	EPA 324/1631	BRL	4/18/08	< 26.0		No	No	
TotalHg-ST15-4/16/08	0816034-10	South Face - East end at corner (scaffolding level)	4/16/08	0.54	Mercury	EPA 324/1631	BRL	4/18/08	< 28.0		No	No	
TotalHg-ST16-4/16/08	0816034-11	East Face - North end at corner (scaffolding level)	4/16/08	0.55	Mercury	EPA 324/1631	BRL	4/18/08	< 27.0		No	No	
TotalHg-ST17-4/16/08	0816034-12	North Face - West end at corner (scaffolding level)	4/16/08	0.57	Mercury	EPA 324/1631	BRL	4/18/08	< 26.0		No	No	
TotalHg-ST1-4/17/08	0816044-01	Southwest Area (sidewalk bridge level)	4/17/08	0.56	Mercury	EPA 324/1631	BRL	4/19/08	< 27.0		No	No	
TotalHg-ST2-4/17/08	0816044-02	Southeast Area (sidewalk bridge level)	4/17/08	0.52	Mercury	EPA 324/1631	BRL	4/19/08	< 29.0		No	No	
TotalHg-ST4-4/17/08	0816044-03	Northwest Area (street-level)	4/17/08	0.57	Mercury	EPA 324/1631	BRL	4/19/08	< 26.0		No	No	
TotalHg-ST5-4/17/08	0816044-04	Firehouse #10 (roof level)	4/17/08	0.56	Mercury	EPA 324/1631	BRL	4/19/08	< 27.0		No	No	
TotalHg-ST10-4/17/08	0816044-05	North Side Sidewalk Bridge	4/17/08	0.58	Mercury	EPA 324/1631	BRL	4/19/08	< 26.0		No	No	
TotalHg-ST11-4/17/08	0816044-06	90 Trinity Place (roof level)	4/17/08	0.53	Mercury	EPA 324/1631	BRL	4/19/08	< 28.0		No	No	
TotalHg-ST12-4/17/08	0816044-07	110 Greenwich Street (roof level)	4/17/08	0.55	Mercury	EPA 324/1631	BRL	4/19/08	< 27.0		No	No	
TotalHg-ST13-4/17/08	0816044-08	Marriott Hotel, 38th Floor (roof level)	4/17/08	0.57	Mercury	EPA 324/1631	BRL	4/19/08	< 26.0		No	No	
TotalHg-ST14-4/17/08	0816044-09	West Face - South end at corner (scaffolding level)	4/17/08	0.53	Mercury	EPA 324/1631	BRL	4/19/08	< 28.0		No	No	
TotalHg-ST15-4/17/08	0816044-10	South Face - East end at corner (scaffolding level)	4/17/08	0.55	Mercury	EPA 324/1631	BRL	4/19/08	< 27.0		No	No	
TotalHg-ST16-4/17/08	0816044-11	East Face - North end at corner (scaffolding level)	4/17/08	0.54	Mercury	EPA 324/1631	BRL	4/19/08	< 28.0		No	No	
TotalHg-ST17-4/17/08	0816044-12	North Face - West end at corner (scaffolding level)	4/17/08	0.56	Mercury	EPA 324/1631	BRL	4/19/08	< 27.0		No	No	
TotalHg-ST1-4/18/08	0817001-01	Southwest Area (sidewalk bridge level)	4/18/08	0.61	Mercury	EPA 324/1631	BRL	4/21/08	< 25.0		No	No	
TotalHg-ST2-4/18/08	0817001-02	Southeast Area (sidewalk bridge level)	4/18/08	0.56	Mercury	EPA 324/1631	BRL	4/21/08	< 27.0		No	No	
TotalHg-ST4-4/18/08	0817001-03	Northwest Area (street-level)	4/18/08	0.57	Mercury	EPA 324/1631	BRL	4/21/08	< 26.0		No	No	
TotalHg-ST5-4/18/08	0817001-04	Firehouse #10 (roof level)	4/18/08	0.58	Mercury	EPA 324/1631	BRL	4/21/08	< 26.0		No	No	
TotalHg-ST10-4/18/08	0817001-05	North Side Sidewalk Bridge	4/18/08	0.63	Mercury	EPA 324/1631	BRL	4/21/08	< 24.0		No	No	
TotalHg-ST11-4/18/08	0817001-06	90 Trinity Place (roof level)	4/18/08	0.54	Mercury	EPA 324/1631	BRL	4/21/08	< 28.0		No	No	
TotalHg-ST12-4/18/08	0817001-07	110 Greenwich Street (roof level)	4/18/08	0.55	Mercury	EPA 324/1631	BRL	4/21/08	< 27.0		No	No	
TotalHg-ST13-4/18/08	0817001-08	Marriott Hotel, 38th Floor (roof level)	4/18/08	0.57	Mercury	EPA 324/1631	BRL	4/21/08	< 26.0		No	No	
TotalHg-ST14-4/18/08	0817001-09	West Face - South end at corner (scaffolding level)	4/18/08	0.54	Mercury	EPA 324/1631	BRL	4/21/08	< 28.0		No	No	
TotalHg-ST15-4/18/08	0817001-10	South Face - East end at corner (scaffolding level)	4/18/08	0.53	Mercury	EPA 324/1631	BRL	4/21/08	< 28.0		No	No	
TotalHg-ST16-4/18/08	0817001-11	East Face - North end at corner (scaffolding level)	4/18/08	0.53	Mercury	EPA 324/1631	BRL	4/21/08	< 28.0		No	No	
TotalHg-ST17-4/18/08	0817001-12	North Face - West end at corner (scaffolding level)	4/18/08	0.55	Mercury	EPA 324/1631	BRL	4/21/08	< 27.0		No	No	