

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-4/16/09	0917001-01	Southwest Area (sidewalk bridge level)	4/16/09	0.60	Mercury	EPA 324/1631	BRL	4/20/09	< 25.0	No	No	
TotalHg-ST2-4/16/09	0917001-02	Southeast Area (sidewalk bridge level)	4/16/09	0.55	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST4-4/16/09	0917001-03	Northwest Area (street-level)	4/16/09	0.57	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST5-4/16/09	0917001-04	Firehouse #10 (roof level)	4/16/09	0.56	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST10-4/16/09	0917001-05	North Side Sidewalk Bridge	4/16/09	0.58	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST100-4/16/09 FD	0917001-13	Station 10 Field Duplicate	4/16/09	0.57	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST11-4/16/09	0917001-06	90 Trinity Place (roof level)	4/16/09	0.56	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST12-4/16/09	0917001-07	110 Greenwich Street (roof level)	4/16/09	0.57	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST13-4/16/09	0917001-08	Marriott Hotel, 38th Floor (roof level)	4/16/09	0.58	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST14-4/16/09	0917001-09	West Face - South end at corner (scaffolding level)	4/16/09	0.56	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST15-4/16/09	0917001-10	South Face - East end at corner (scaffolding level)	4/16/09	0.53	Mercury	EPA 324/1631	BRL	4/20/09	< 28.0	No	No	
TotalHg-ST16-4/16/09	0917001-11	East Face - North end at corner (scaffolding level)	4/16/09	0.59	Mercury	EPA 324/1631	BRL	4/20/09	< 25.0	No	No	
TotalHg-ST17-4/16/09	0917001-12	North Face - West end at corner (scaffolding level)	4/16/09	0.55	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST1-4/17/09	0917002-01	Southwest Area (sidewalk bridge level)	4/17/09	0.59	Mercury	EPA 324/1631	BRL	4/20/09	< 25.0	No	No	
TotalHg-ST2-4/17/09	0917002-02	Southeast Area (sidewalk bridge level)	4/17/09	0.55	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST4-4/17/09	0917002-03	Northwest Area (street-level)	4/17/09	0.53	Mercury	EPA 324/1631	BRL	4/20/09	< 28.0	No	No	
TotalHg-ST5-4/17/09	0917002-04	Firehouse #10 (roof level)	4/17/09	0.59	Mercury	EPA 324/1631	BRL	4/20/09	< 25.0	No	No	
TotalHg-ST10-4/17/09	0917002-05	North Side Sidewalk Bridge	4/17/09	0.55	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST11-4/17/09	0917002-06	90 Trinity Place (roof level)	4/17/09	0.55	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST12-4/17/09	0917002-07	110 Greenwich Street (roof level)	4/17/09	0.57	Mercury	EPA 324/1631	BRL	4/20/09	< 26.0	No	No	
TotalHg-ST13-4/17/09	0917002-08	Marriott Hotel, 38th Floor (roof level)	4/17/09	0.60	Mercury	EPA 324/1631	BRL	4/20/09	< 25.0	No	No	
TotalHg-ST14-4/17/09	0917002-09	West Face - South end at corner (scaffolding level)	4/17/09	0.56	Mercury	EPA 324/1631	BRL	4/20/09	< 27.0	No	No	
TotalHg-ST15-4/17/09	0917002-10	South Face - East end at corner (scaffolding level)	4/17/09	0.53	Mercury	EPA 324/1631	BRL	4/20/09	< 28.0	No	No	
TotalHg-ST16-4/17/09	0917002-11	East Face - North end at corner (scaffolding level)	4/17/09	0.54	Mercury	EPA 324/1631	BRL	4/20/09	< 28.0	No	No	
TotalHg-ST17-4/17/09	0917002-12	North Face - West end at corner (scaffolding level)	4/17/09	0.54	Mercury	EPA 324/1631	BRL	4/20/09	< 28.0	No	No	
TotalHg-ST1-4/18/09	0917003-01	Southwest Area (sidewalk bridge level)	4/18/09	0.58	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	
TotalHg-ST2-4/18/09	0917003-02	Southeast Area (sidewalk bridge level)	4/18/09	0.57	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	
TotalHg-ST4-4/18/09	0917003-03	Northwest Area (street-level)	4/18/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST5-4/18/09	0917003-04	Firehouse #10 (roof level)	4/18/09	0.59	Mercury	EPA 324/1631	BRL	4/21/09	< 25.0	No	No	
TotalHg-ST10-4/18/09	0917003-05	North Side Sidewalk Bridge	4/18/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST11-4/18/09	0917003-06	90 Trinity Place (roof level)	4/18/09	0.56	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST12-4/18/09	0917003-07	110 Greenwich Street (roof level)	4/18/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST13-4/18/09	0917003-08	Marriott Hotel, 38th Floor (roof level)	4/18/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST14-4/18/09	0917003-09	West Face - South end at corner (scaffolding level)	4/18/09	0.58	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	
TotalHg-ST15-4/18/09	0917003-10	South Face - East end at corner (scaffolding level)	4/18/09	0.55	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST16-4/18/09	0917003-11	East Face - North end at corner (scaffolding level)	4/18/09	0.58	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST17-4/18/09	0917003-12	North Face - West end at corner (scaffolding level)	4/18/09	0.57	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	
TotalHg-ST1-4/19/09	0917004-01	Southwest Area (sidewalk bridge level)	4/19/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST2-4/19/09	0917004-02	Southeast Area (sidewalk bridge level)	4/19/09	0.61	Mercury	EPA 324/1631	BRL	4/21/09	< 25.0	No	No	
TotalHg-ST4-4/19/09	0917004-03	Northwest Area (street-level)	4/19/09	0.56	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST5-4/19/09	0917004-04	Firehouse #10 (roof level)	4/19/09	0.60	Mercury	EPA 324/1631	BRL	4/21/09	< 25.0	No	No	
TotalHg-ST10-4/19/09	0917004-05	North Side Sidewalk Bridge	4/19/09	0.59	Mercury	EPA 324/1631	BRL	4/21/09	< 25.0	No	No	
TotalHg-ST11-4/19/09	0917004-06	90 Trinity Place (roof level)	4/19/09	0.56	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST12-4/19/09	0917004-07	110 Greenwich Street (roof level)	4/19/09	0.57	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	
TotalHg-ST13-4/19/09	0917004-08	Marriott Hotel, 38th Floor (roof level)	4/19/09	0.60	Mercury	EPA 324/1631	BRL	4/21/09	< 25.0	No	No	
TotalHg-ST14-4/19/09	0917004-09	West Face - South end at corner (scaffolding level)	4/19/09	0.62	Mercury	EPA 324/1631	BRL	4/21/09	< 24.0	No	No	
TotalHg-ST15-4/19/09	0917004-10	South Face - East end at corner (scaffolding level)	4/19/09	0.54	Mercury	EPA 324/1631	BRL	4/21/09	< 28.0	No	No	
TotalHg-ST16-4/19/09	0917004-11	East Face - North end at corner (scaffolding level)	4/19/09	0.56	Mercury	EPA 324/1631	BRL	4/21/09	< 27.0	No	No	
TotalHg-ST17-4/19/09	0917004-12	North Face - West end at corner (scaffolding level)	4/19/09	0.58	Mercury	EPA 324/1631	BRL	4/21/09	< 26.0	No	No	