

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300				
									EPA Site Specific Trigger Levels				
TotalHg-ST1-4/23/08	0817048-01	Southwest Area (sidewalk bridge level)	4/23/08	0.57	Mercury	EPA 324/1631	BRL	4/25/08	< 26.0		No	No	
TotalHg-ST2-4/23/08	0817048-02	Southeast Area (sidewalk bridge level)	4/23/08	0.59	Mercury	EPA 324/1631	BRL	4/25/08	< 25.0		No	No	
TotalHg-ST4-4/23/08	0817048-03	Northwest Area (street-level)	4/23/08	0.58	Mercury	EPA 324/1631	BRL	4/25/08	< 26.0		No	No	
TotalHg-ST5-4/23/08	0817048-04	Firehouse #10 (roof level)	4/23/08	0.57	Mercury	EPA 324/1631	BRL	4/25/08	< 26.0		No	No	
TotalHg-ST10-4/23/08	0817048-05	North Side Sidewalk Bridge	4/23/08	0.55	Mercury	EPA 324/1631	BRL	4/25/08	< 27.0		No	No	
TotalHg-ST100-4/23/08	0817048-13	Station 10 Field Duplicate	4/23/08	0.57	Mercury	EPA 324/1631	BRL	4/25/08	< 26.0		No	No	
TotalHg-ST11-4/23/08	0817048-06	90 Trinity Place (roof level)	4/23/08	0.55	Mercury	EPA 324/1631	BRL	4/25/08	< 27.0		No	No	
TotalHg-ST12-4/23/08	0817048-07	110 Greenwich Street (roof level)	4/23/08	0.56	Mercury	EPA 324/1631	BRL	4/25/08	< 27.0		No	No	
TotalHg-ST13-4/23/08	0817048-08	Marriott Hotel, 38th Floor (roof level)	4/23/08	0.57	Mercury	EPA 324/1631	BRL	4/25/08	< 26.0		No	No	
TotalHg-ST14-4/23/08	0817048-09	West Face - South end at corner (scaffolding level)	4/23/08	0.59	Mercury	EPA 324/1631	BRL	4/25/08	< 25.0		No	No	
TotalHg-ST15-4/23/08	0817048-10	South Face - East end at corner (scaffolding level)	4/23/08	0.56	Mercury	EPA 324/1631	BRL	4/25/08	< 27.0		No	No	
TotalHg-ST16-4/23/08	0817048-11	East Face - North end at corner (scaffolding level)	4/23/08	0.53	Mercury	EPA 324/1631	BRL	4/25/08	< 28.0		No	No	
TotalHg-ST17-4/23/08	0817048-12	North Face - West end at corner (scaffolding level)	4/23/08	0.55	Mercury	EPA 324/1631	BRL	4/25/08	< 27.0		No	No	
TotalHg-ST1-4/24/08	0817052-01	Southwest Area (sidewalk bridge level)	4/24/08	0.59	Mercury	EPA 324/1631	BRL	4/26/08	< 25.0		No	No	
TotalHg-ST2-4/24/08	0817052-02	Southeast Area (sidewalk bridge level)	4/24/08	0.58	Mercury	EPA 324/1631	BRL	4/26/08	< 26.0		No	No	
TotalHg-ST4-4/24/08	0817052-03	Northwest Area (street-level)	4/24/08	0.59	Mercury	EPA 324/1631	BRL	4/26/08	< 25.0		No	No	
TotalHg-ST5-4/24/08	0817052-04	Firehouse #10 (roof level)	4/24/08	0.54	Mercury	EPA 324/1631	BRL	4/26/08	< 28.0		No	No	
TotalHg-ST10-4/24/08	0817052-05	North Side Sidewalk Bridge	4/24/08	0.52	Mercury	EPA 324/1631	BRL	4/26/08	< 29.0		No	No	
TotalHg-ST11-4/24/08	0817052-06	90 Trinity Place (roof level)	4/24/08	0.54	Mercury	EPA 324/1631	BRL	4/26/08	< 28.0		No	No	
TotalHg-ST12-4/24/08	0817052-07	110 Greenwich Street (roof level)	4/24/08	0.56	Mercury	EPA 324/1631	BRL	4/26/08	< 27.0		No	No	
TotalHg-ST13-4/24/08	0817052-08	Marriott Hotel, 38th Floor (roof level)	4/24/08	0.56	Mercury	EPA 324/1631	BRL	4/26/08	< 27.0		No	No	
TotalHg-ST14-4/24/08	0817052-09	West Face - South end at corner (scaffolding level)	4/24/08	0.56	Mercury	EPA 324/1631	BRL	4/26/08	< 27.0		No	No	
TotalHg-ST15-4/24/08	0817052-10	South Face - East end at corner (scaffolding level)	4/24/08	0.57	Mercury	EPA 324/1631	BRL	4/26/08	< 26.0		No	No	
TotalHg-ST16-4/24/08	0817052-11	East Face - North end at corner (scaffolding level)	4/24/08	0.56	Mercury	EPA 324/1631	BRL	4/26/08	< 27.0		No	No	
TotalHg-ST17-4/24/08	0817052-12	North Face - West end at corner (scaffolding level)	4/24/08	0.60	Mercury	EPA 324/1631	BRL	4/26/08	< 25.0		No	No	
TotalHg-ST1-4/25/08	0818002-01	Southwest Area (sidewalk bridge level)	4/25/08	0.61	Mercury	EPA 324/1631	BRL	4/28/08	< 25.0		No	No	
TotalHg-ST2-4/25/08	0818002-02	Southeast Area (sidewalk bridge level)	4/25/08	0.57	Mercury	EPA 324/1631	BRL	4/28/08	< 26.0		No	No	
TotalHg-ST4-4/25/08	0818002-03	Northwest Area (street-level)	4/25/08	0.58	Mercury	EPA 324/1631	BRL	4/28/08	< 26.0		No	No	
TotalHg-ST5-4/25/08	0818002-04	Firehouse #10 (roof level)	4/25/08	0.55	Mercury	EPA 324/1631	BRL	4/28/08	< 27.0		No	No	
TotalHg-ST10-4/25/08	0818002-05	North Side Sidewalk Bridge	4/25/08	0.54	Mercury	EPA 324/1631	BRL	4/28/08	< 28.0		No	No	
TotalHg-ST11-4/25/08	0818002-06	90 Trinity Place (roof level)	4/25/08	0.59	Mercury	EPA 324/1631	BRL	4/28/08	< 25.0		No	No	
TotalHg-ST12-4/25/08	0818002-07	110 Greenwich Street (roof level)	4/25/08	0.53	Mercury	EPA 324/1631	BRL	4/28/08	< 28.0		No	No	
TotalHg-ST13-4/25/08	0818002-08	Marriott Hotel, 38th Floor (roof level)	4/25/08	0.58	Mercury	EPA 324/1631	BRL	4/28/08	< 26.0		No	No	
TotalHg-ST14-4/25/08	0818002-09	West Face - South end at corner (scaffolding level)	4/25/08	0.52	Mercury	EPA 324/1631	BRL	4/28/08	< 29.0		No	No	
TotalHg-ST15-4/25/08	0818002-10	South Face - East end at corner (scaffolding level)	4/25/08	0.53	Mercury	EPA 324/1631	BRL	4/28/08	< 28.0		No	No	
TotalHg-ST16-4/25/08	0818002-11	East Face - North end at corner (scaffolding level)	4/25/08	0.57	Mercury	EPA 324/1631	BRL	4/28/08	< 26.0		No	No	
TotalHg-ST17-4/25/08	0818002-12	North Face - West end at corner (scaffolding level)	4/25/08	0.55	Mercury	EPA 324/1631	BRL	4/28/08	< 27.0		No	No	