

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-4/26/06	06BR0621-01	Southwest Area (sidewalk bridge level)	4/26/06	0.58	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST2-4/26/06	06BR0621-02	Southeast Area (sidewalk bridge level)	4/26/06	0.58	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST4-4/26/06	06BR0621-03	Northwest Area (street-level)	4/26/06	0.58	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST5-4/26/06	06BR0621-04	Firehouse #10 (roof level)	4/26/06	0.58	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST10-4/26/06	06BR0621-05	North Side Sidewalk Bridge	4/26/06	0.57	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST11-4/26/06	06BR0621-06	90 Trinity Place (roof level)	4/26/06	0.57	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST12-4/26/06	06BR0621-07	110 Greenwich Street (roof level)	4/26/06	0.57	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST13-4/26/06	06BR0621-08	Marriott Hotel, 38th Floor (roof level)	4/26/06	0.58	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST14-4/26/06	06BR0621-09	West Face - South end at corner (scaffolding level)	4/26/06	0.57	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST15-4/26/06	06BR0621-10	South Face - East end at corner (scaffolding level)	4/26/06	0.57	Mercury	EPA 324/1631	BRL	4/28/06	< 26.0	No	No	
TotalHg-ST16-4/26/06	06BR0621-11	East Face - North end at corner (scaffolding level)	4/26/06	0.56	Mercury	EPA 324/1631	BRL	4/28/06	< 27.0	No	No	
TotalHg-ST17-4/26/06	06BR0621-12	North Face - West end at corner (scaffolding level)	4/26/06	0.54	Mercury	EPA 324/1631	BRL	4/28/06	< 28.0	No	No	
TotalHg-ST1-4/27/06	06BR0628-01	Southwest Area (sidewalk bridge level)	4/27/06	0.57	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST2-4/27/06	06BR0628-02	Southeast Area (sidewalk bridge level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST4-4/27/06	06BR0628-03	Northwest Area (street-level)	4/27/06	0.57	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST10-4/27/06	06BR0628-04	North Side Sidewalk Bridge	4/27/06	0.57	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST11-4/27/06	06BR0628-05	90 Trinity Place (roof level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST12-4/27/06	06BR0628-06	110 Greenwich Street (roof level)	4/27/06	0.57	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST13-4/27/06	06BR0628-07	Marriott Hotel, 38th Floor (roof level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST14-4/27/06	06BR0628-08	West Face - South end at corner (scaffolding level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST15-4/27/06	06BR0628-09	South Face - East end at corner (scaffolding level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST16-4/27/06	06BR0628-10	East Face - North end at corner (scaffolding level)	4/27/06	0.58	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	
TotalHg-ST17-4/27/06	06BR0628-11	North Face - West end at corner (scaffolding level)	4/27/06	0.57	Mercury	EPA 324/1631	BRL	4/29/06	< 26.0	No	No	

Note:

1. Mercury sample at Station 5 (Firehouse #10 [roof level]) on April 27, 2006 was not available for analysis on account of pump failure.