

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-4/29/09	0918023-01	Southwest Area (sidewalk bridge level)	4/29/09	0.57	Mercury	EPA 324/1631	BRL	5/1/09	< 26.0	No	No	
TotalHg-ST2-4/29/09	0918023-02	Southeast Area (sidewalk bridge level)	4/29/09	0.54	Mercury	EPA 324/1631	BRL	5/1/09	< 28.0	No	No	
TotalHg-ST4-4/29/09	0918023-03	Northwest Area (street-level)	4/29/09	0.58	Mercury	EPA 324/1631	BRL	5/1/09	< 26.0	No	No	
TotalHg-ST5-4/29/09	0918023-04	Firehouse #10 (roof level)	4/29/09	0.59	Mercury	EPA 324/1631	BRL	5/1/09	< 25.0	No	No	
TotalHg-ST10-4/29/09	0918023-05	North Side Sidewalk Bridge	4/29/09	0.55	Mercury	EPA 324/1631	BRL	5/1/09	< 27.0	No	No	
TotalHg-ST11-4/29/09	0918023-06	90 Trinity Place (roof level)	4/29/09	0.56	Mercury	EPA 324/1631	BRL	5/1/09	< 27.0	No	No	
TotalHg-ST12-4/29/09	0918023-07	110 Greenwich Street (roof level)	4/29/09	0.53	Mercury	EPA 324/1631	BRL	5/1/09	< 28.0	No	No	
TotalHg-ST13-4/29/09	0918023-08	Marriott Hotel, 38th Floor (roof level)	4/29/09	0.57	Mercury	EPA 324/1631	BRL	5/1/09	< 26.0	No	No	
TotalHg-ST14-4/29/09	0918023-09	West Face - South end at corner (scaffolding level)	4/29/09	0.52	Mercury	EPA 324/1631	BRL	5/1/09	< 29.0	No	No	
TotalHg-ST15-4/29/09	0918023-10	South Face - East end at corner (scaffolding level)	4/29/09	0.51	Mercury	EPA 324/1631	BRL	5/1/09	< 29.0	No	No	
TotalHg-ST16-4/29/09	0918023-11	East Face - North end at corner (scaffolding level)	4/29/09	0.54	Mercury	EPA 324/1631	BRL	5/1/09	< 28.0	No	No	
TotalHg-ST17-4/29/09	0918023-12	North Face - West end at corner (scaffolding level)	4/29/09	0.55	Mercury	EPA 324/1631	BRL	5/1/09	< 27.0	No	No	
TotalHg-ST1-4/30/09	0919001-01	Southwest Area (sidewalk bridge level)	4/30/09	0.56	Mercury	EPA 324/1631	BRL	5/2/09	< 27.0	No	No	
TotalHg-ST2-4/30/09	0919001-02	Southeast Area (sidewalk bridge level)	4/30/09	0.60	Mercury	EPA 324/1631	BRL	5/2/09	< 25.0	No	No	
TotalHg-ST4-4/30/09	0919001-03	Northwest Area (street-level)	4/30/09	0.62	Mercury	EPA 324/1631	BRL	5/2/09	< 24.0	No	No	
TotalHg-ST5-4/30/09	0919001-04	Firehouse #10 (roof level)	4/30/09	0.62	Mercury	EPA 324/1631	BRL	5/2/09	< 24.0	No	No	
TotalHg-ST10-4/30/09	0919001-05	North Side Sidewalk Bridge	4/30/09	0.56	Mercury	EPA 324/1631	BRL	5/2/09	< 27.0	No	No	
TotalHg-ST11-4/30/09	0919001-06	90 Trinity Place (roof level)	4/30/09	0.57	Mercury	EPA 324/1631	BRL	5/2/09	< 26.0	No	No	
TotalHg-ST12-4/30/09	0919001-07	110 Greenwich Street (roof level)	4/30/09	0.56	Mercury	EPA 324/1631	BRL	5/2/09	< 27.0	No	No	
TotalHg-ST13-4/30/09	0919001-08	Marriott Hotel, 38th Floor (roof level)	4/30/09	0.60	Mercury	EPA 324/1631	BRL	5/2/09	< 25.0	No	No	
TotalHg-ST14-4/30/09	0919001-09	West Face - South end at corner (scaffolding level)	4/30/09	0.61	Mercury	EPA 324/1631	BRL	5/2/09	< 25.0	No	No	
TotalHg-ST15-4/30/09	0919001-10	South Face - East end at corner (scaffolding level)	4/30/09	0.54	Mercury	EPA 324/1631	BRL	5/2/09	< 28.0	No	No	
TotalHg-ST16-4/30/09	0919001-11	East Face - North end at corner (scaffolding level)	4/30/09	0.55	Mercury	EPA 324/1631	BRL	5/2/09	< 27.0	No	No	
TotalHg-ST17-4/30/09	0919001-12	North Face - West end at corner (scaffolding level)	4/30/09	0.57	Mercury	EPA 324/1631	BRL	5/2/09	< 26.0	No	No	
TotalHg-ST1-5/1/09	0919002-01	Southwest Area (sidewalk bridge level)	5/1/09	0.55	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	
TotalHg-ST2-5/1/09	0919002-02	Southeast Area (sidewalk bridge level)	5/1/09	0.58	Mercury	EPA 324/1631	BRL	5/4/09	< 26.0	No	No	
TotalHg-ST4-5/1/09	0919002-03	Northwest Area (street-level)	5/1/09	0.55	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	
TotalHg-ST5-5/1/09	0919002-04	Firehouse #10 (roof level)	5/1/09	0.58	Mercury	EPA 324/1631	BRL	5/4/09	< 26.0	No	No	
TotalHg-ST10-5/1/09	0919002-05	North Side Sidewalk Bridge	5/1/09	0.57	Mercury	EPA 324/1631	BRL	5/4/09	< 26.0	No	No	
TotalHg-ST11-5/1/09	0919002-06	90 Trinity Place (roof level)	5/1/09	0.60	Mercury	EPA 324/1631	BRL	5/4/09	< 25.0	No	No	
TotalHg-ST12-5/1/09	0919002-07	110 Greenwich Street (roof level)	5/1/09	0.55	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	
TotalHg-ST13-5/1/09	0919002-08	Marriott Hotel, 38th Floor (roof level)	5/1/09	0.57	Mercury	EPA 324/1631	BRL	5/4/09	< 26.0	No	No	
TotalHg-ST14-5/1/09	0919002-09	West Face - South end at corner (scaffolding level)	5/1/09	0.59	Mercury	EPA 324/1631	BRL	5/4/09	< 25.0	No	No	
TotalHg-ST15-5/1/09	0919002-10	South Face - East end at corner (scaffolding level)	5/1/09	0.55	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	
TotalHg-ST16-5/1/09	0919002-11	East Face - North end at corner (scaffolding level)	5/1/09	0.55	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	
TotalHg-ST17-5/1/09	0919002-12	North Face - West end at corner (scaffolding level)	5/1/09	0.56	Mercury	EPA 324/1631	BRL	5/4/09	< 27.0	No	No	