

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-5/2/07	07BR0592-01	Southwest Area (sidewalk bridge level)	5/2/07	0.54	Mercury	EPA 324/1631	BRL	5/4/07	< 28.0	No	No	
TotalHg-ST2-5/2/07	07BR0592-02	Southeast Area (sidewalk bridge level)	5/2/07	0.54	Mercury	EPA 324/1631	BRL	5/4/07	< 28.0	No	No	
TotalHg-ST5-5/2/07	07BR0592-03	Firehouse #10 (roof level)	5/2/07	0.61	Mercury	EPA 324/1631	BRL	5/4/07	< 25.0	No	No	
TotalHg-ST10-5/2/07	07BR0592-04	North Side Sidewalk Bridge	5/2/07	0.58	Mercury	EPA 324/1631	BRL	5/4/07	< 26.0	No	No	
TotalHg-ST11-5/2/07	07BR0592-05	90 Trinity Place (roof level)	5/2/07	0.59	Mercury	EPA 324/1631	BRL	5/4/07	< 25.0	No	No	
TotalHg-ST12-5/2/07	07BR0592-06	110 Greenwich Street (roof level)	5/2/07	0.55	Mercury	EPA 324/1631	BRL	5/4/07	< 27.0	No	No	
TotalHg-ST13-5/2/07	07BR0592-07	Marriott Hotel, 38th Floor (roof level)	5/2/07	0.58	Mercury	EPA 324/1631	BRL	5/4/07	< 26.0	No	No	
TotalHg-ST14-5/2/07	07BR0592-08	West Face - South end at corner (scaffolding level)	5/2/07	0.61	Mercury	EPA 324/1631	BRL	5/4/07	< 25.0	No	No	
TotalHg-ST15-5/2/07	07BR0592-09	South Face - East end at corner (scaffolding level)	5/2/07	0.56	Mercury	EPA 324/1631	BRL	5/4/07	< 27.0	No	No	
TotalHg-ST16-5/2/07	07BR0592-10	East Face - North end at corner (scaffolding level)	5/2/07	0.59	Mercury	EPA 324/1631	BRL	5/4/07	< 25.0	No	No	
TotalHg-ST17-5/2/07	07BR0592-11	North Face - West end at corner (scaffolding level)	5/2/07	0.61	Mercury	EPA 324/1631	BRL	5/4/07	< 25.0	No	No	
TotalHg-ST1-5/3/07	07BR0600-01	Southwest Area (sidewalk bridge level)	5/3/07	0.56	Mercury	EPA 324/1631	BRL	5/5/07	< 27.0	No	No	
TotalHg-ST2-5/3/07	07BR0600-02	Southeast Area (sidewalk bridge level)	5/3/07	0.61	Mercury	EPA 324/1631	BRL	5/5/07	< 25.0	No	No	
TotalHg-ST4-5/3/07	07BR0600-03	Northwest Area (street-level)	5/3/07	0.55	Mercury	EPA 324/1631	BRL	5/5/07	< 27.0	No	No	
TotalHg-ST5-5/3/07	07BR0600-04	Firehouse #10 (roof level)	5/3/07	0.59	Mercury	EPA 324/1631	BRL	5/5/07	< 25.0	No	No	
TotalHg-ST10-5/3/07	07BR0600-05	North Side Sidewalk Bridge	5/3/07	0.60	Mercury	EPA 324/1631	BRL	5/5/07	< 25.0	No	No	
TotalHg-ST11-5/3/07	07BR0600-06	90 Trinity Place (roof level)	5/3/07	0.56	Mercury	EPA 324/1631	BRL	5/5/07	< 27.0	No	No	
TotalHg-ST12-5/3/07	07BR0600-07	110 Greenwich Street (roof level)	5/3/07	0.57	Mercury	EPA 324/1631	BRL	5/5/07	< 26.0	No	No	
TotalHg-ST13-5/3/07	07BR0600-08	Marriott Hotel, 38th Floor (roof level)	5/3/07	0.59	Mercury	EPA 324/1631	BRL	5/5/07	< 25.0	No	No	
TotalHg-ST14-5/3/07	07BR0600-09	West Face - South end at corner (scaffolding level)	5/3/07	0.54	Mercury	EPA 324/1631	BRL	5/5/07	< 28.0	No	No	
TotalHg-ST15-5/3/07	07BR0600-10	South Face - East end at corner (scaffolding level)	5/3/07	0.58	Mercury	EPA 324/1631	BRL	5/5/07	< 26.0	No	No	
TotalHg-ST16-5/3/07	07BR0600-11	East Face - North end at corner (scaffolding level)	5/3/07	0.55	Mercury	EPA 324/1631	BRL	5/5/07	< 27.0	No	No	
TotalHg-ST17-5/3/07	07BR0600-12	North Face - West end at corner (scaffolding level)	5/3/07	0.55	Mercury	EPA 324/1631	BRL	5/5/07	< 27.0	No	No	

Note:

- Mercury sample at Station 4 (Northwest Area [street-level]) on May 2, 2007 was not available for analysis on account of power failure.