

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-5/07/08	0819045-01	Southwest Area (sidewalk bridge level)	5/7/08	0.55	Mercury	EPA 324/1631	BRL	5/9/08	< 27.0	No	No	
TotalHg-ST2-5/07/08	0819045-02	Southeast Area (sidewalk bridge level)	5/7/08	0.60	Mercury	EPA 324/1631	BRL	5/9/08	< 25.0	No	No	
TotalHg-ST4-5/07/08	0819045-03	Northwest Area (street-level)	5/7/08	0.57	Mercury	EPA 324/1631	BRL	5/9/08	< 26.0	No	No	
TotalHg-ST5-5/07/08	0819045-04	Firehouse #10 (roof level)	5/7/08	0.56	Mercury	EPA 324/1631	BRL	5/9/08	< 27.0	No	No	
TotalHg-ST10-5/07/08	0819045-05	North Side Sidewalk Bridge	5/7/08	0.57	Mercury	EPA 324/1631	BRL	5/9/08	< 26.0	No	No	
TotalHg-ST11-5/07/08	0819045-06	90 Trinity Place (roof level)	5/7/08	0.55	Mercury	EPA 324/1631	BRL	5/9/08	< 27.0	No	No	
TotalHg-ST12-5/07/08	0819045-07	110 Greenwich Street (roof level)	5/7/08	0.61	Mercury	EPA 324/1631	BRL	5/9/08	< 25.0	No	No	
TotalHg-ST13-5/07/08	0819045-08	Marriott Hotel, 38th Floor (roof level)	5/7/08	0.58	Mercury	EPA 324/1631	BRL	5/9/08	< 26.0	No	No	
TotalHg-ST14-5/07/08	0819045-09	West Face - South end at corner (scaffolding level)	5/7/08	0.58	Mercury	EPA 324/1631	BRL	5/9/08	< 26.0	No	No	
TotalHg-ST15-5/07/08	0819045-10	South Face - East end at corner (scaffolding level)	5/7/08	0.54	Mercury	EPA 324/1631	BRL	5/9/08	< 28.0	No	No	
TotalHg-ST16-5/07/08	0819045-11	East Face - North end at corner (scaffolding level)	5/7/08	0.59	Mercury	EPA 324/1631	BRL	5/9/08	< 25.0	No	No	
TotalHg-ST17-5/07/08	0819045-12	North Face - West end at corner (scaffolding level)	5/7/08	0.60	Mercury	EPA 324/1631	BRL	5/9/08	< 25.0	No	No	
TotalHg-ST1-5/08/08	0820003-01	Southwest Area (sidewalk bridge level)	5/8/08	0.54	Mercury	EPA 324/1631	BRL	5/10/08	< 28.0	No	No	
TotalHg-ST2-5/08/08	0820003-02	Southeast Area (sidewalk bridge level)	5/8/08	0.61	Mercury	EPA 324/1631	BRL	5/10/08	< 25.0	No	No	
TotalHg-ST4-5/08/08	0820003-03	Northwest Area (street-level)	5/8/08	0.58	Mercury	EPA 324/1631	BRL	5/10/08	< 26.0	No	No	
TotalHg-ST5-5/08/08	0820003-04	Firehouse #10 (roof level)	5/8/08	0.54	Mercury	EPA 324/1631	BRL	5/10/08	< 28.0	No	No	
TotalHg-ST10-5/08/08	0820003-05	North Side Sidewalk Bridge	5/8/08	0.55	Mercury	EPA 324/1631	BRL	5/10/08	< 27.0	No	No	
TotalHg-ST11-5/08/08	0820003-06	90 Trinity Place (roof level)	5/8/08	0.55	Mercury	EPA 324/1631	BRL	5/10/08	< 27.0	No	No	
TotalHg-ST12-5/08/08	0820003-07	110 Greenwich Street (roof level)	5/8/08	0.53	Mercury	EPA 324/1631	BRL	5/10/08	< 28.0	No	No	
TotalHg-ST13-5/08/08	0820003-08	Marriott Hotel, 38th Floor (roof level)	5/8/08	0.57	Mercury	EPA 324/1631	BRL	5/10/08	< 26.0	No	No	
TotalHg-ST14-5/08/08	0820003-09	West Face - South end at corner (scaffolding level)	5/8/08	0.56	Mercury	EPA 324/1631	BRL	5/10/08	< 27.0	No	No	
TotalHg-ST15-5/08/08	0820003-10	South Face - East end at corner (scaffolding level)	5/8/08	0.52	Mercury	EPA 324/1631	BRL	5/10/08	< 29.0	No	No	
TotalHg-ST16-5/08/08	0820003-11	East Face - North end at corner (scaffolding level)	5/8/08	0.57	Mercury	EPA 324/1631	BRL	5/10/08	< 26.0	No	No	
TotalHg-ST17-5/08/08	0820003-12	North Face - West end at corner (scaffolding level)	5/8/08	0.59	Mercury	EPA 324/1631	BRL	5/10/08	< 25.0	No	No	