

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-5/10/06	06BR0686-01	Southwest Area (sidewalk bridge level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST2-5/10/06	06BR0686-02	Southeast Area (sidewalk bridge level)	5/10/06	0.57	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST4-5/10/06	06BR0686-03	Northwest Area (street-level)	5/10/06	0.57	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST5-5/10/06	06BR0686-04	Firehouse #10 (roof level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST10-5/10/06	06BR0686-05	North Side Sidewalk Bridge	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST11-5/10/06	06BR0686-06	90 Trinity Place (roof level)	5/10/06	0.57	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST12-5/10/06	06BR0686-07	110 Greenwich Street (roof level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST13-5/10/06	06BR0686-08	Marriott Hotel, 38th Floor (roof level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST14-5/10/06	06BR0686-09	West Face - South end at corner (scaffolding level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST15-5/10/06	06BR0686-10	South Face - East end at corner (scaffolding level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST16-5/10/06	06BR0686-11	East Face - North end at corner (scaffolding level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST17-5/10/06	06BR0686-12	North Face - West end at corner (scaffolding level)	5/10/06	0.58	Mercury	EPA 324/1631	BRL	5/12/06	< 26.0	No	No	
TotalHg-ST1-5/11/06	06BR0690-01	Southwest Area (sidewalk bridge level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST2-5/11/06	06BR0690-02	Southeast Area (sidewalk bridge level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST4-5/11/06	06BR0690-03	Northwest Area (street-level)	5/11/06	0.57	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST5-5/11/06	06BR0690-04	Firehouse #10 (roof level)	5/11/06	0.56	Mercury	EPA 324/1631	BRL	5/13/06	< 27.0	No	No	
TotalHg-ST10-5/11/06	06BR0690-05	North Side Sidewalk Bridge	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST11-5/11/06	06BR0690-06	90 Trinity Place (roof level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST12-5/11/06	06BR0690-07	110 Greenwich Street (roof level)	5/11/06	0.60	Mercury	EPA 324/1631	BRL	5/13/06	< 25.0	No	No	
TotalHg-ST13-5/11/06	06BR0690-08	Marriott Hotel, 38th Floor (roof level)	5/11/06	0.59	Mercury	EPA 324/1631	BRL	5/13/06	< 25.0	No	No	
TotalHg-ST14-5/11/06	06BR0690-09	West Face - South end at corner (scaffolding level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST15-5/11/06	06BR0690-10	South Face - East end at corner (scaffolding level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST16-5/11/06	06BR0690-11	East Face - North end at corner (scaffolding level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	
TotalHg-ST17-5/11/06	06BR0690-12	North Face - West end at corner (scaffolding level)	5/11/06	0.58	Mercury	EPA 324/1631	BRL	5/13/06	< 26.0	No	No	