

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-5/11/07	07BR0649-01	Southwest Area (sidewalk bridge level)	5/11/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST2-5/11/07	07BR0649-02	Southeast Area (sidewalk bridge level)	5/11/07	0.60	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST4-5/11/07	07BR0649-03	Northwest Area (street-level)	5/11/07	0.54	Mercury	EPA 324/1631	BRL	5/15/07	< 28.0	No	No	
TotalHg-ST5-5/11/07	07BR0649-04	Firehouse #10 (roof level)	5/11/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST10-5/11/07	07BR0649-05	North Side Sidewalk Bridge	5/11/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST11-5/11/07	07BR0649-06	90 Trinity Place (roof level)	5/11/07	0.60	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST12-5/11/07	07BR0649-07	110 Greenwich Street (roof level)	5/11/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST13-5/11/07	07BR0649-08	Marriott Hotel, 38th Floor (roof level)	5/11/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST14-5/11/07	07BR0649-09	West Face - South end at corner (scaffolding level)	5/11/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST15-5/11/07	07BR0649-10	South Face - East end at corner (scaffolding level)	5/11/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST16-5/11/07	07BR0649-11	East Face - North end at corner (scaffolding level)	5/11/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST17-5/11/07	07BR0649-12	North Face - West end at corner (scaffolding level)	5/11/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST1-5/12/07	07BR0650-01	Southwest Area (sidewalk bridge level)	5/12/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST2-5/12/07	07BR0650-02	Southeast Area (sidewalk bridge level)	5/12/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST4-5/12/07	07BR0650-03	Northwest Area (street-level)	5/12/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST5-5/12/07	07BR0650-04	Firehouse #10 (roof level)	5/12/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST10-5/12/07	07BR0650-05	North Side Sidewalk Bridge	5/12/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST11-5/12/07	07BR0650-06	90 Trinity Place (roof level)	5/12/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST12-5/12/07	07BR0650-07	110 Greenwich Street (roof level)	5/12/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST13-5/12/07	07BR0650-08	Marriott Hotel, 38th Floor (roof level)	5/12/07	0.63	Mercury	EPA 324/1631	BRL	5/15/07	< 24.0	No	No	
TotalHg-ST14-5/12/07	07BR0650-09	West Face - South end at corner (scaffolding level)	5/12/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST15-5/12/07	07BR0650-10	South Face - East end at corner (scaffolding level)	5/12/07	0.54	Mercury	EPA 324/1631	BRL	5/15/07	< 28.0	No	No	
TotalHg-ST16-5/12/07	07BR0650-11	East Face - North end at corner (scaffolding level)	5/12/07	0.58	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST17-5/12/07	07BR0650-12	North Face - West end at corner (scaffolding level)	5/12/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	33.0	No	No	
TotalHg-ST1-5/13/07	07BR0651-01	Southwest Area (sidewalk bridge level)	5/13/07	0.55	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST2-5/13/07	07BR0651-02	Southeast Area (sidewalk bridge level)	5/13/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST4-5/13/07	07BR0651-03	Northwest Area (street-level)	5/13/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST5-5/13/07	07BR0651-04	Firehouse #10 (roof level)	5/13/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST10-5/13/07	07BR0651-05	North Side Sidewalk Bridge	5/13/07	0.61	Mercury	EPA 324/1631	BRL	5/15/07	< 25.0	No	No	
TotalHg-ST11-5/13/07	07BR0651-06	90 Trinity Place (roof level)	5/13/07	0.56	Mercury	EPA 324/1631	BRL	5/15/07	< 27.0	No	No	
TotalHg-ST12-5/13/07	07BR0651-07	110 Greenwich Street (roof level)	5/13/07	0.54	Mercury	EPA 324/1631	BRL	5/15/07	< 28.0	No	No	
TotalHg-ST13-5/13/07	07BR0651-08	Marriott Hotel, 38th Floor (roof level)	5/13/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST14-5/13/07	07BR0651-09	West Face - South end at corner (scaffolding level)	5/13/07	0.57	Mercury	EPA 324/1631	BRL	5/15/07	< 26.0	No	No	
TotalHg-ST15-5/13/07	07BR0651-10	South Face - East end at corner (scaffolding level)	5/13/07	0.63	Mercury	EPA 324/1631	BRL	5/15/07	< 24.0	No	No	
TotalHg-ST16-5/13/07	07BR0651-11	East Face - North end at corner (scaffolding level)	5/13/07	0.63	Mercury	EPA 324/1631	BRL	5/15/07	< 24.0	No	No	
TotalHg-ST17-5/13/07	07BR0651-12	North Face - West end at corner (scaffolding level)	5/13/07	0.59	Mercury	EPA 324/1631	BRL	5/15/07	29.0	No	No	