

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-5/16/07	07BR0675-01	Southwest Area (sidewalk bridge level)	5/16/07	0.58	Mercury	EPA 324/1631	BRL	5/18/07	< 26.0	No	No	
TotalHg-ST2-5/16/07	07BR0675-02	Southeast Area (sidewalk bridge level)	5/16/07	0.58	Mercury	EPA 324/1631	BRL	5/18/07	< 26.0	No	No	
TotalHg-ST4-5/16/07	07BR0675-03	Northwest Area (street-level)	5/16/07	0.57	Mercury	EPA 324/1631	BRL	5/18/07	< 26.0	No	No	
TotalHg-ST5-5/16/07	07BR0675-04	Firehouse #10 (roof level)	5/16/07	0.54	Mercury	EPA 324/1631	BRL	5/18/07	< 28.0	No	No	
TotalHg-ST10-5/16/07	07BR0675-05	North Side Sidewalk Bridge	5/16/07	0.59	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST11-5/16/07	07BR0675-06	90 Trinity Place (roof level)	5/16/07	0.60	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST12-5/16/07	07BR0675-07	110 Greenwich Street (roof level)	5/16/07	0.60	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST13-5/16/07	07BR0675-08	Marriott Hotel, 38th Floor (roof level)	5/16/07	0.64	Mercury	EPA 324/1631	BRL	5/18/07	< 23.0	No	No	
TotalHg-ST14-5/16/07	07BR0675-09	West Face - South end at corner (scaffolding level)	5/16/07	0.60	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST15-5/16/07	07BR0675-10	South Face - East end at corner (scaffolding level)	5/16/07	0.58	Mercury	EPA 324/1631	BRL	5/18/07	< 26.0	No	No	
TotalHg-ST16-5/16/07	07BR0675-11	East Face - North end at corner (scaffolding level)	5/16/07	0.59	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST17-5/16/07	07BR0675-12	North Face - West end at corner (scaffolding level)	5/16/07	0.60	Mercury	EPA 324/1631	BRL	5/18/07	< 25.0	No	No	
TotalHg-ST1-5/17/07	07BR0682-01	Southwest Area (sidewalk bridge level)	5/17/07	0.61	Mercury	EPA 324/1631	BRL	5/19/07	< 25.0	No	No	
TotalHg-ST2-5/17/07	07BR0682-02	Southeast Area (sidewalk bridge level)	5/17/07	0.58	Mercury	EPA 324/1631	BRL	5/19/07	< 26.0	No	No	
TotalHg-ST4-5/17/07	07BR0682-03	Northwest Area (street-level)	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	
TotalHg-ST5-5/17/07	07BR0682-04	Firehouse #10 (roof level)	5/17/07	0.61	Mercury	EPA 324/1631	BRL	5/19/07	< 25.0	No	No	
TotalHg-ST10-5/17/07	07BR0682-05	North Side Sidewalk Bridge	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	
TotalHg-ST11-5/17/07	07BR0682-06	90 Trinity Place (roof level)	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	
TotalHg-ST12-5/17/07	07BR0682-07	110 Greenwich Street (roof level)	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	
TotalHg-ST13-5/17/07	07BR0682-08	Marriott Hotel, 38th Floor (roof level)	5/17/07	0.54	Mercury	EPA 324/1631	BRL	5/19/07	< 28.0	No	No	
TotalHg-ST14-5/17/07	07BR0682-09	West Face - South end at corner (scaffolding level)	5/17/07	0.54	Mercury	EPA 324/1631	BRL	5/19/07	< 28.0	No	No	
TotalHg-ST15-5/17/07	07BR0682-10	South Face - East end at corner (scaffolding level)	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	
TotalHg-ST16-5/17/07	07BR0682-11	East Face - North end at corner (scaffolding level)	5/17/07	0.58	Mercury	EPA 324/1631	BRL	5/19/07	< 26.0	No	No	
TotalHg-ST17-5/17/07	07BR0682-12	North Face - West end at corner (scaffolding level)	5/17/07	0.56	Mercury	EPA 324/1631	BRL	5/19/07	< 27.0	No	No	