

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-5/17/08	0821008-01	Southwest Area (sidewalk bridge level)	5/17/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST2-5/17/08	0821008-02	Southeast Area (sidewalk bridge level)	5/17/08	0.54	Mercury	EPA 324/1631	BRL	5/20/08	< 28.0	No	No	
TotalHg-ST4-5/17/08	0821008-03	Northwest Area (street-level)	5/17/08	0.53	Mercury	EPA 324/1631	BRL	5/20/08	< 28.0	No	No	
TotalHg-ST5-5/17/08	0821008-04	Firehouse #10 (roof level)	5/17/08	0.60	Mercury	EPA 324/1631	BRL	5/20/08	< 25.0	No	No	
TotalHg-ST10-5/17/08	0821008-05	North Side Sidewalk Bridge	5/17/08	0.55	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST11-5/17/08	0821008-06	90 Trinity Place (roof level)	5/17/08	0.58	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST12-5/17/08	0821008-07	110 Greenwich Street (roof level)	5/17/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST13-5/17/08	0821008-08	Marriott Hotel, 38th Floor (roof level)	5/17/08	0.57	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST14-5/17/08	0821008-09	West Face - South end at corner (scaffolding level)	5/17/08	0.54	Mercury	EPA 324/1631	BRL	5/20/08	< 28.0	No	No	
TotalHg-ST15-5/17/08	0821008-10	South Face - East end at corner (scaffolding level)	5/17/08	0.53	Mercury	EPA 324/1631	BRL	5/20/08	< 28.0	No	No	
TotalHg-ST16-5/17/08	0821008-11	East Face - North end at corner (scaffolding level)	5/17/08	0.60	Mercury	EPA 324/1631	BRL	5/20/08	< 25.0	No	No	
TotalHg-ST17-5/17/08	0821008-12	North Face - West end at corner (scaffolding level)	5/17/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST1-5/18/08	0821009-01	Southwest Area (sidewalk bridge level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST2-5/18/08	0821009-02	Southeast Area (sidewalk bridge level)	5/18/08	0.58	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST4-5/18/08	0821009-03	Northwest Area (street-level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST5-5/18/08	0821009-04	Firehouse #10 (roof level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST10-5/18/08	0821009-05	North Side Sidewalk Bridge	5/18/08	0.57	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST11-5/18/08	0821009-06	90 Trinity Place (roof level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST12-5/18/08	0821009-07	110 Greenwich Street (roof level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST13-5/18/08	0821009-08	Marriott Hotel, 38th Floor (roof level)	5/18/08	0.56	Mercury	EPA 324/1631	BRL	5/20/08	< 27.0	No	No	
TotalHg-ST14-5/18/08	0821009-09	West Face - South end at corner (scaffolding level)	5/18/08	0.57	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST15-5/18/08	0821009-10	South Face - East end at corner (scaffolding level)	5/18/08	0.60	Mercury	EPA 324/1631	BRL	5/20/08	< 25.0	No	No	
TotalHg-ST16-5/18/08	0821009-11	East Face - North end at corner (scaffolding level)	5/18/08	0.57	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	
TotalHg-ST17-5/18/08	0821009-12	North Face - West end at corner (scaffolding level)	5/18/08	0.57	Mercury	EPA 324/1631	BRL	5/20/08	< 26.0	No	No	