

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/19/06	06BR0751-01	Southwest Area (sidewalk bridge level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST2-5/19/06	06BR0751-02	Southeast Area (sidewalk bridge level)	5/19/06	0.56	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST4-5/19/06	06BR0751-03	Northwest Area (street-level)	5/19/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST5-5/19/06	06BR0751-04	Firehouse #10 (roof level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST10-5/19/06	06BR0751-05	North Side Sidewalk Bridge	5/19/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST11-5/19/06	06BR0751-06	90 Trinity Place (roof level)	5/19/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST12-5/19/06	06BR0751-07	110 Greenwich Street (roof level)	5/19/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST13-5/19/06	06BR0751-08	Marriott Hotel, 38th Floor (roof level)	5/19/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST14-5/19/06	06BR0751-09	West Face - South end at corner (scaffolding level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST15-5/19/06	06BR0751-10	South Face - East end at corner (scaffolding level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST16-5/19/06	06BR0751-11	East Face - North end at corner (scaffolding level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST17-5/19/06	06BR0751-12	North Face - West end at corner (scaffolding level)	5/19/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST1-5/20/06	06BR0752-01	Southwest Area (sidewalk bridge level)	5/20/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST2-5/20/06	06BR0752-02	Southeast Area (sidewalk bridge level)	5/20/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST4-5/20/06	06BR0752-03	Northwest Area (street-level)	5/20/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST5-5/20/06	06BR0752-04	Firehouse #10 (roof level)	5/20/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST10-5/20/06	06BR0752-05	North Side Sidewalk Bridge	5/20/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST11-5/20/06	06BR0752-06	90 Trinity Place (roof level)	5/20/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST12-5/20/06	06BR0752-07	110 Greenwich Street (roof level)	5/20/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST13-5/20/06	06BR0752-08	Marriott Hotel, 38th Floor (roof level)	5/20/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST14-5/20/06	06BR0752-09	West Face - South end at corner (scaffolding level)	5/20/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST15-5/20/06	06BR0752-10	South Face - East end at corner (scaffolding level)	5/20/06	0.56	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST16-5/20/06	06BR0752-11	East Face - North end at corner (scaffolding level)	5/20/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST17-5/20/06	06BR0752-12	North Face - West end at corner (scaffolding level)	5/20/06	0.56	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST1-5/21/06	06BR0753-01	Southwest Area (sidewalk bridge level)	5/21/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST2-5/21/06	06BR0753-02	Southeast Area (sidewalk bridge level)	5/21/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST4-5/21/06	06BR0753-03	Northwest Area (street-level)	5/21/06	0.6	Mercury	EPA 324/1631	BRL	5/23/06	< 25.0	No	No	
TotalHg-ST5-5/21/06	06BR0753-04	Firehouse #10 (roof level)	5/21/06	0.57	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST10-5/21/06	06BR0753-05	North Side Sidewalk Bridge	5/21/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST11-5/21/06	06BR0753-06	90 Trinity Place (roof level)	5/21/06	0.55	Mercury	EPA 324/1631	BRL	5/23/06	< 27.0	No	No	
TotalHg-ST12-5/21/06	06BR0753-07	110 Greenwich Street (roof level)	5/21/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST13-5/21/06	06BR0753-08	Marriott Hotel, 38th Floor (roof level)	5/21/06	0.58	Mercury	EPA 324/1631	BRL	5/23/06	< 26.0	No	No	
TotalHg-ST14-5/21/06	06BR0753-09	West Face - South end at corner (scaffolding level)	5/21/06	0.6	Mercury	EPA 324/1631	BRL	5/23/06	< 25.0	No	No	
TotalHg-ST15-5/21/06	06BR0753-10	South Face - East end at corner (scaffolding level)	5/21/06	0.6	Mercury	EPA 324/1631	BRL	5/23/06	< 25.0	No	No	
TotalHg-ST16-5/21/06	06BR0753-11	East Face - North end at corner (scaffolding level)	5/21/06	0.6	Mercury	EPA 324/1631	BRL	5/23/06	< 25.0	No	No	
TotalHg-ST17-5/21/06	06BR0753-12	North Face - West end at corner (scaffolding level)	5/21/06	0.6	Mercury	EPA 324/1631	BRL	5/23/06	< 25.0	No	No	