

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-6/3/09	0923020-01	Southwest Area (sidewalk bridge level)	6/3/09	0.57	Mercury	EPA 324/1631	BRL	6/5/09	< 26.0	No	No	
TotalHg-ST2-6/3/09	0923020-02	Southeast Area (sidewalk bridge level)	6/3/09	0.57	Mercury	EPA 324/1631	BRL	6/5/09	< 26.0	No	No	
TotalHg-ST4-6/3/09	0923020-03	Northwest Area (street-level)	6/3/09	0.55	Mercury	EPA 324/1631	BRL	6/5/09	< 27.0	No	No	
TotalHg-ST5-6/3/09	0923020-04	Firehouse #10 (roof level)	6/3/09	0.57	Mercury	EPA 324/1631	BRL	6/5/09	< 26.0	No	No	
TotalHg-ST10-6/3/09	0923020-05	North Side Sidewalk Bridge	6/3/09	0.53	Mercury	EPA 324/1631	BRL	6/5/09	< 28.0	No	No	
TotalHg-ST11-6/3/09	0923020-06	90 Trinity Place (roof level)	6/3/09	0.57	Mercury	EPA 324/1631	BRL	6/5/09	< 26.0	No	No	
TotalHg-ST12-6/3/09	0923020-07	110 Greenwich Street (roof level)	6/3/09	0.58	Mercury	EPA 324/1631	BRL	6/5/09	< 26.0	No	No	
TotalHg-ST13-6/3/09	0923020-08	Marriott Hotel, 38th Floor (roof level)	6/3/09	0.55	Mercury	EPA 324/1631	BRL	6/5/09	< 27.0	No	No	
TotalHg-ST1-6/4/09	0923027-01	Southwest Area (sidewalk bridge level)	6/4/09	0.58	Mercury	EPA 324/1631	BRL	6/6/09	< 26.0	No	No	
TotalHg-ST2-6/4/09	0923027-02	Southeast Area (sidewalk bridge level)	6/4/09	0.57	Mercury	EPA 324/1631	BRL	6/6/09	< 26.0	No	No	
TotalHg-ST4-6/4/09	0923027-03	Northwest Area (street-level)	6/4/09	0.59	Mercury	EPA 324/1631	BRL	6/6/09	< 25.0	No	No	
TotalHg-ST5-6/4/09	0923027-04	Firehouse #10 (roof level)	6/4/09	0.57	Mercury	EPA 324/1631	BRL	6/6/09	< 26.0	No	No	
TotalHg-ST10-6/4/09	0923027-05	North Side Sidewalk Bridge	6/4/09	0.54	Mercury	EPA 324/1631	BRL	6/6/09	< 28.0	No	No	
TotalHg-ST11-6/4/09	0923027-06	90 Trinity Place (roof level)	6/4/09	0.56	Mercury	EPA 324/1631	BRL	6/6/09	< 27.0	No	No	
TotalHg-ST12-6/4/09	0923027-07	110 Greenwich Street (roof level)	6/4/09	0.54	Mercury	EPA 324/1631	BRL	6/6/09	< 28.0	No	No	
TotalHg-ST13-6/4/09	0923027-08	Marriott Hotel, 38th Floor (roof level)	6/4/09	0.56	Mercury	EPA 324/1631	BRL	6/6/09	< 27.0	No	No	
TotalHg-ST1-6/5/09	0924001-01	Southwest Area (sidewalk bridge level)	6/5/09	0.54	Mercury	EPA 324/1631	BRL	6/8/09	< 28.0	No	No	
TotalHg-ST2-6/5/09	0924001-02	Southeast Area (sidewalk bridge level)	6/5/09	0.55	Mercury	EPA 324/1631	BRL	6/8/09	< 27.0	No	No	
TotalHg-ST4-6/5/09	0924001-03	Northwest Area (street-level)	6/5/09	0.55	Mercury	EPA 324/1631	BRL	6/8/09	< 27.0	No	No	
TotalHg-ST5-6/5/09	0924001-04	Firehouse #10 (roof level)	6/5/09	0.58	Mercury	EPA 324/1631	BRL	6/8/09	< 26.0	No	No	
TotalHg-ST10-6/5/09	0924001-05	North Side Sidewalk Bridge	6/5/09	0.55	Mercury	EPA 324/1631	BRL	6/8/09	< 27.0	No	No	
TotalHg-ST100-6/5/09 FD	0924001-10	Station 10 Field Duplicate	6/5/09	0.56	Mercury	EPA 324/1631	BRL	6/8/09	< 27.0	No	No	
TotalHg-ST11-6/5/09	0924001-06	90 Trinity Place (roof level)	6/5/09	0.54	Mercury	EPA 324/1631	BRL	6/8/09	< 28.0	No	No	
TotalHg-ST12-6/5/09	0924001-07	110 Greenwich Street (roof level)	6/5/09	0.55	Mercury	EPA 324/1631	BRL	6/8/09	< 27.0	No	No	
TotalHg-ST13-6/5/09	0924001-08	Marriott Hotel, 38th Floor (roof level)	6/5/09	0.57	Mercury	EPA 324/1631	BRL	6/8/09	< 26.0	No	No	
TotalHg-ST1-6/6/09	0924003-01	Southwest Area (sidewalk bridge level)	6/6/09	0.58	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST2-6/6/09	0924003-02	Southeast Area (sidewalk bridge level)	6/6/09	0.57	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST4-6/6/09	0924003-03	Northwest Area (street-level)	6/6/09	0.58	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST5-6/6/09	0924003-04	Firehouse #10 (roof level)	6/6/09	0.58	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST10-6/6/09	0924003-05	North Side Sidewalk Bridge	6/6/09	0.57	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST11-6/6/09	0924003-06	90 Trinity Place (roof level)	6/6/09	0.55	Mercury	EPA 324/1631	BRL	6/9/09	< 27.0	No	No	
TotalHg-ST12-6/6/09	0924003-07	110 Greenwich Street (roof level)	6/6/09	0.55	Mercury	EPA 324/1631	BRL	6/9/09	< 27.0	No	No	
TotalHg-ST13-6/6/09	0924003-08	Marriott Hotel, 38th Floor (roof level)	6/6/09	0.57	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST1-6/7/09	0924004-01	Southwest Area (sidewalk bridge level)	6/7/09	0.55	Mercury	EPA 324/1631	BRL	6/9/09	< 27.0	No	No	
TotalHg-ST2-6/7/09	0924004-02	Southeast Area (sidewalk bridge level)	6/7/09	0.57	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST4-6/7/09	0924004-03	Northwest Area (street-level)	6/7/09	0.58	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST5-6/7/09	0924004-04	Firehouse #10 (roof level)	6/7/09	0.54	Mercury	EPA 324/1631	BRL	6/9/09	< 28.0	No	No	
TotalHg-ST10-6/7/09	0924004-05	North Side Sidewalk Bridge	6/7/09	0.55	Mercury	EPA 324/1631	BRL	6/9/09	< 27.0	No	No	
TotalHg-ST11-6/7/09	0924004-06	90 Trinity Place (roof level)	6/7/09	0.58	Mercury	EPA 324/1631	BRL	6/9/09	< 26.0	No	No	
TotalHg-ST12-6/7/09	0924004-07	110 Greenwich Street (roof level)	6/7/09	0.54	Mercury	EPA 324/1631	BRL	6/9/09	< 28.0	No	No	
TotalHg-ST13-6/7/09	0924004-08	Marriott Hotel, 38th Floor (roof level)	6/7/09	0.52	Mercury	EPA 324/1631	BRL	6/9/09	< 29.0	No	No	