

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-6/18/08	0825043-01	Southwest Area (sidewalk bridge level)	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST2-6/18/08	0825043-02	Southeast Area (sidewalk bridge level)	6/18/08	0.61	Mercury	EPA 324/1631	BRL	6/20/08	< 25.0	No	No	
TotalHg-ST4-6/18/08	0825043-03	Northwest Area (street-level)	6/18/08	0.59	Mercury	EPA 324/1631	BRL	6/20/08	< 25.0	No	No	
TotalHg-ST5-6/18/08	0825043-04	Firehouse #10 (roof level)	6/18/08	0.58	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST10-6/18/08	0825043-05	North Side Sidewalk Bridge	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST11-6/18/08	0825043-06	90 Trinity Place (roof level)	6/18/08	0.59	Mercury	EPA 324/1631	BRL	6/20/08	< 25.0	No	No	
TotalHg-ST12-6/18/08	0825043-07	110 Greenwich Street (roof level)	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST13-6/18/08	0825043-08	Marriott Hotel, 38th Floor (roof level)	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST14-6/18/08	0825043-09	West Face - South end at corner (scaffolding level)	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST15-6/18/08	0825043-10	South Face - East end at corner (scaffolding level)	6/18/08	0.54	Mercury	EPA 324/1631	BRL	6/20/08	< 28.0	No	No	
TotalHg-ST16-6/18/08	0825043-11	East Face - North end at corner (scaffolding level)	6/18/08	0.57	Mercury	EPA 324/1631	BRL	6/20/08	< 26.0	No	No	
TotalHg-ST17-6/18/08	0825043-12	North Face - West end at corner (scaffolding level)	6/18/08	0.59	Mercury	EPA 324/1631	BRL	6/20/08	< 25.0	No	No	
TotalHg-ST1-6/19/08	0825051-01	Southwest Area (sidewalk bridge level)	6/19/08	0.53	Mercury	EPA 324/1631	BRL	6/21/08	< 28.0	No	No	
TotalHg-ST2-6/19/08	0825051-02	Southeast Area (sidewalk bridge level)	6/19/08	0.59	Mercury	EPA 324/1631	BRL	6/21/08	< 25.0	No	No	
TotalHg-ST4-6/19/08	0825051-03	Northwest Area (street-level)	6/19/08	0.57	Mercury	EPA 324/1631	BRL	6/21/08	< 26.0	No	No	
TotalHg-ST5-6/19/08	0825051-04	Firehouse #10 (roof level)	6/19/08	0.55	Mercury	EPA 324/1631	BRL	6/21/08	< 27.0	No	No	
TotalHg-ST10-6/19/08	0825051-05	North Side Sidewalk Bridge	6/19/08	0.56	Mercury	EPA 324/1631	BRL	6/21/08	< 27.0	No	No	
TotalHg-ST11-6/19/08	0825051-06	90 Trinity Place (roof level)	6/19/08	0.57	Mercury	EPA 324/1631	BRL	6/21/08	< 26.0	No	No	
TotalHg-ST12-6/19/08	0825051-07	110 Greenwich Street (roof level)	6/19/08	0.56	Mercury	EPA 324/1631	BRL	6/21/08	< 27.0	No	No	
TotalHg-ST13-6/19/08	0825051-08	Marriott Hotel, 38th Floor (roof level)	6/19/08	0.56	Mercury	EPA 324/1631	BRL	6/21/08	< 27.0	No	No	
TotalHg-ST14-6/19/08	0825051-09	West Face - South end at corner (scaffolding level)	6/19/08	0.58	Mercury	EPA 324/1631	BRL	6/21/08	< 26.0	No	No	
TotalHg-ST15-6/19/08	0825051-10	South Face - East end at corner (scaffolding level)	6/19/08	0.58	Mercury	EPA 324/1631	BRL	6/21/08	< 26.0	No	No	
TotalHg-ST16-6/19/08	0825051-11	East Face - North end at corner (scaffolding level)	6/19/08	0.55	Mercury	EPA 324/1631	BRL	6/21/08	< 27.0	No	No	
TotalHg-ST17-6/19/08	0825051-12	North Face - West end at corner (scaffolding level)	6/19/08	0.54	Mercury	EPA 324/1631	BRL	6/21/08	< 28.0	No	No	
TotalHg-ST1-6/20/08	0826001-01	Southwest Area (sidewalk bridge level)	6/20/08	0.57	Mercury	EPA 324/1631	BRL	6/23/08	< 26.0	No	No	
TotalHg-ST2-6/20/08	0826001-02	Southeast Area (sidewalk bridge level)	6/20/08	0.57	Mercury	EPA 324/1631	BRL	6/23/08	< 26.0	No	No	
TotalHg-ST4-6/20/08	0826001-03	Northwest Area (street-level)	6/20/08	0.60	Mercury	EPA 324/1631	BRL	6/23/08	< 25.0	No	No	
TotalHg-ST5-6/20/08	0826001-04	Firehouse #10 (roof level)	6/20/08	0.60	Mercury	EPA 324/1631	BRL	6/23/08	< 25.0	No	No	
TotalHg-ST10-6/20/08	0826001-05	North Side Sidewalk Bridge	6/20/08	0.58	Mercury	EPA 324/1631	BRL	6/23/08	< 26.0	No	No	
TotalHg-ST11-6/20/08	0826001-06	90 Trinity Place (roof level)	6/20/08	0.57	Mercury	EPA 324/1631	BRL	6/23/08	< 26.0	No	No	
TotalHg-ST12-6/20/08	0826001-07	110 Greenwich Street (roof level)	6/20/08	0.54	Mercury	EPA 324/1631	BRL	6/23/08	< 28.0	No	No	
TotalHg-ST13-6/20/08	0826001-08	Marriott Hotel, 38th Floor (roof level)	6/20/08	0.58	Mercury	EPA 324/1631	BRL	6/23/08	< 26.0	No	No	
TotalHg-ST14-6/20/08	0826001-09	West Face - South end at corner (scaffolding level)	6/20/08	0.54	Mercury	EPA 324/1631	BRL	6/23/08	< 28.0	No	No	
TotalHg-ST15-6/20/08	0826001-10	South Face - East end at corner (scaffolding level)	6/20/08	0.52	Mercury	EPA 324/1631	BRL	6/23/08	< 29.0	No	No	
TotalHg-ST16-6/20/08	0826001-11	East Face - North end at corner (scaffolding level)	6/20/08	0.52	Mercury	EPA 324/1631	BRL	6/23/08	< 29.0	No	No	
TotalHg-ST17-6/20/08	0826001-12	North Face - West end at corner (scaffolding level)	6/20/08	0.52	Mercury	EPA 324/1631	BRL	6/23/08	< 29.0	No	No	