

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
									<b>3,000</b>			
TotalHg-ST1-6/22/07	07BR0893-01	Southwest Area (sidewalk bridge level)	6/22/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST2-6/22/07	07BR0893-02	Southeast Area (sidewalk bridge level)	6/22/07	0.62	Mercury	EPA 324/1631	BRL	6/26/07	< 24.0	No	No	
TotalHg-ST4-6/22/07	07BR0893-03	Northwest Area (street-level)	6/22/07	0.52	Mercury	EPA 324/1631	BRL	6/26/07	< 29.0	No	No	
TotalHg-ST5-6/22/07	07BR0893-04	Firehouse #10 (roof level)	6/22/07	0.56	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST10-6/22/07	07BR0893-05	North Side Sidewalk Bridge	6/22/07	0.56	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST11-6/22/07	07BR0893-06	90 Trinity Place (roof level)	6/22/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST12-6/22/07	07BR0893-07	110 Greenwich Street (roof level)	6/22/07	0.57	Mercury	EPA 324/1631	BRL	6/26/07	< 26.0	No	No	
TotalHg-ST13-6/22/07	07BR0893-08	Marriott Hotel, 38th Floor (roof level)	6/22/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST14-6/22/07	07BR0893-09	West Face - South end at corner (scaffolding level)	6/22/07	0.54	Mercury	EPA 324/1631	BRL	6/26/07	< 28.0	No	No	
TotalHg-ST15-6/22/07	07BR0893-10	South Face - East end at corner (scaffolding level)	6/22/07	0.55	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST16-6/22/07	07BR0893-11	East Face - North end at corner (scaffolding level)	6/22/07	0.57	Mercury	EPA 324/1631	BRL	6/26/07	< 26.0	No	No	
TotalHg-ST17-6/22/07	07BR0893-12	North Face - West end at corner (scaffolding level)	6/22/07	0.54	Mercury	EPA 324/1631	BRL	6/26/07	< 28.0	No	No	
TotalHg-ST1-6/23/07	07BR0894-01	Southwest Area (sidewalk bridge level)	6/23/07	0.58	Mercury	EPA 324/1631	BRL	6/26/07	< 26.0	No	No	
TotalHg-ST2-6/23/07	07BR0894-02	Southeast Area (sidewalk bridge level)	6/23/07	0.55	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST4-6/23/07	07BR0894-03	Northwest Area (street-level)	6/23/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST5-6/23/07	07BR0894-04	Firehouse #10 (roof level)	6/23/07	0.61	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST10-6/23/07	07BR0894-05	North Side Sidewalk Bridge	6/23/07	0.58	Mercury	EPA 324/1631	BRL	6/26/07	< 26.0	No	No	
TotalHg-ST11-6/23/07	07BR0894-06	90 Trinity Place (roof level)	6/23/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST12-6/23/07	07BR0894-07	110 Greenwich Street (roof level)	6/23/07	0.58	Mercury	EPA 324/1631	BRL	6/26/07	< 26.0	No	No	
TotalHg-ST13-6/23/07	07BR0894-08	Marriott Hotel, 38th Floor (roof level)	6/23/07	0.61	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST14-6/23/07	07BR0894-09	West Face - South end at corner (scaffolding level)	6/23/07	0.48	Mercury	EPA 324/1631	BRL	6/26/07	< 31.0	No	No	
TotalHg-ST15-6/23/07	07BR0894-10	South Face - East end at corner (scaffolding level)	6/23/07	0.50	Mercury	EPA 324/1631	BRL	6/26/07	< 30.0	No	No	
TotalHg-ST16-6/23/07	07BR0894-11	East Face - North end at corner (scaffolding level)	6/23/07	0.50	Mercury	EPA 324/1631	BRL	6/26/07	< 30.0	No	No	
TotalHg-ST17-6/23/07	07BR0894-12	North Face - West end at corner (scaffolding level)	6/23/07	0.48	Mercury	EPA 324/1631	BRL	6/26/07	< 31.0	No	No	
TotalHg-ST1-6/24/07	07BR0896-01	Southwest Area (sidewalk bridge level)	6/24/07	0.56	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST2-6/24/07	07BR0896-02	Southeast Area (sidewalk bridge level)	6/24/07	0.55	Mercury	EPA 324/1631	BRL	6/26/07	30.0	No	No	
TotalHg-ST4-6/24/07	07BR0896-03	Northwest Area (street-level)	6/24/07	0.54	Mercury	EPA 324/1631	BRL	6/26/07	< 28.0	No	No	
TotalHg-ST5-6/24/07	07BR0896-04	Firehouse #10 (roof level)	6/24/07	0.56	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	
TotalHg-ST10-6/24/07	07BR0896-05	North Side Sidewalk Bridge	6/24/07	0.54	Mercury	EPA 324/1631	BRL	6/26/07	< 28.0	No	No	
TotalHg-ST11-6/24/07	07BR0896-06	90 Trinity Place (roof level)	6/24/07	0.59	Mercury	EPA 324/1631	BRL	6/26/07	< 25.0	No	No	
TotalHg-ST12-6/24/07	07BR0896-07	110 Greenwich Street (roof level)	6/24/07	0.53	Mercury	EPA 324/1631	BRL	6/26/07	< 28.0	No	No	
TotalHg-ST13-6/24/07	07BR0896-08	Marriott Hotel, 38th Floor (roof level)	6/24/07	0.55	Mercury	EPA 324/1631	BRL	6/26/07	< 27.0	No	No	

Note:

1. The Mercury readings at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on June 24, 2007 were not available. These stations were offline for relocation to the 15th floor scaffolding from the 20th floor scaffolding.