

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-6/24/09	0926027-01	Southwest Area (sidewalk bridge level)	6/24/09	0.52	Mercury	EPA 324/1631	BRL	6/26/09	< 28.9	No	No	
TotalHg-ST2-6/24/09	0926027-02	Southeast Area (sidewalk bridge level)	6/24/09	0.57	Mercury	EPA 324/1631	BRL	6/26/09	< 26.3	No	No	
TotalHg-ST4-6/24/09	0926027-03	Northwest Area (street-level)	6/24/09	0.53	Mercury	EPA 324/1631	BRL	6/26/09	< 28.3	No	No	
TotalHg-ST5-6/24/09	0926027-04	Firehouse #10 (roof level)	6/24/09	0.56	Mercury	EPA 324/1631	BRL	6/26/09	< 26.8	No	No	
TotalHg-ST10-6/24/09	0926027-05	North Side Sidewalk Bridge	6/24/09	0.55	Mercury	EPA 324/1631	BRL	6/26/09	< 27.3	No	No	
TotalHg-ST11-6/24/09	0926027-06	90 Trinity Place (roof level)	6/24/09	0.59	Mercury	EPA 324/1631	BRL	6/26/09	< 25.4	No	No	
TotalHg-ST12-6/24/09	0926027-07	110 Greenwich Street (roof level)	6/24/09	0.61	Mercury	EPA 324/1631	BRL	6/26/09	< 24.6	No	No	
TotalHg-ST13-6/24/09	0926027-08	Marriott Hotel, 38th Floor (roof level)	6/24/09	0.56	Mercury	EPA 324/1631	BRL	6/26/09	< 26.8	No	No	
TotalHg-ST1-6/25/09	0926031-01	Southwest Area (sidewalk bridge level)	6/25/09	0.54	Mercury	EPA 324/1631	BRL	6/27/09	< 28.0	No	No	
TotalHg-ST2-6/25/09	0926031-02	Southeast Area (sidewalk bridge level)	6/25/09	0.56	Mercury	EPA 324/1631	BRL	6/27/09	< 27.0	No	No	
TotalHg-ST4-6/25/09	0926031-03	Northwest Area (street-level)	6/25/09	0.58	Mercury	EPA 324/1631	BRL	6/27/09	< 26.0	No	No	
TotalHg-ST5-6/25/09	0926031-04	Firehouse #10 (roof level)	6/25/09	0.56	Mercury	EPA 324/1631	BRL	6/27/09	< 27.0	No	No	
TotalHg-ST10-6/25/09	0926031-05	North Side Sidewalk Bridge	6/25/09	0.55	Mercury	EPA 324/1631	BRL	6/27/09	< 27.0	No	No	
TotalHg-ST11-6/25/09	0926031-06	90 Trinity Place (roof level)	6/25/09	0.59	Mercury	EPA 324/1631	BRL	6/27/09	< 25.0	No	No	
TotalHg-ST12-6/25/09	0926031-07	110 Greenwich Street (roof level)	6/25/09	0.59	Mercury	EPA 324/1631	BRL	6/27/09	< 25.0	No	No	
TotalHg-ST13-6/25/09	0926031-08	Marriott Hotel, 38th Floor (roof level)	6/25/09	0.54	Mercury	EPA 324/1631	BRL	6/27/09	< 28.0	No	No	
TotalHg-ST1-6/26/09	0927001-01	Southwest Area (sidewalk bridge level)	6/26/09	0.58	Mercury	EPA 324/1631	BRL	6/29/09	< 26.0	No	No	
TotalHg-ST2-6/26/09	0927001-02	Southeast Area (sidewalk bridge level)	6/26/09	0.59	Mercury	EPA 324/1631	BRL	6/29/09	< 25.0	No	No	
TotalHg-ST4-6/26/09	0927001-03	Northwest Area (street-level)	6/26/09	0.55	Mercury	EPA 324/1631	BRL	6/29/09	< 27.0	No	No	
TotalHg-ST5-6/26/09	0927001-04	Firehouse #10 (roof level)	6/26/09	0.58	Mercury	EPA 324/1631	BRL	6/29/09	< 26.0	No	No	
TotalHg-ST10-6/26/09	0927001-05	North Side Sidewalk Bridge	6/26/09	0.52	Mercury	EPA 324/1631	BRL	6/29/09	< 29.0	No	No	
TotalHg-ST11-6/26/09	0927001-06	90 Trinity Place (roof level)	6/26/09	0.57	Mercury	EPA 324/1631	BRL	6/29/09	< 26.0	No	No	
TotalHg-ST12-6/26/09	0927001-07	110 Greenwich Street (roof level)	6/26/09	0.56	Mercury	EPA 324/1631	BRL	6/29/09	< 27.0	No	No	
TotalHg-ST13-6/26/09	0927001-08	Marriott Hotel, 38th Floor (roof level)	6/26/09	0.56	Mercury	EPA 324/1631	BRL	6/29/09	< 27.0	No	No	
TotalHg-ST1-6/27/09	0927003-01	Southwest Area (sidewalk bridge level)	6/27/09	0.56	Mercury	EPA 324/1631	BRL	6/30/09	< 26.8	No	No	
TotalHg-ST2-6/27/09	0927003-02	Southeast Area (sidewalk bridge level)	6/27/09	0.57	Mercury	EPA 324/1631	BRL	6/30/09	< 26.3	No	No	
TotalHg-ST4-6/27/09	0927003-03	Northwest Area (street-level)	6/27/09	0.57	Mercury	EPA 324/1631	BRL	6/30/09	< 26.3	No	No	
TotalHg-ST5-6/27/09	0927003-04	Firehouse #10 (roof level)	6/27/09	0.58	Mercury	EPA 324/1631	BRL	6/30/09	< 25.9	No	No	
TotalHg-ST10-6/27/09	0927003-05	North Side Sidewalk Bridge	6/27/09	0.54	Mercury	EPA 324/1631	BRL	6/30/09	< 27.8	No	No	
TotalHg-ST11-6/27/09	0927003-06	90 Trinity Place (roof level)	6/27/09	0.57	Mercury	EPA 324/1631	BRL	6/30/09	< 26.3	No	No	
TotalHg-ST12-6/27/09	0927003-07	110 Greenwich Street (roof level)	6/27/09	0.58	Mercury	EPA 324/1631	BRL	6/30/09	< 25.9	No	No	
TotalHg-ST13-6/27/09	0927003-08	Marriott Hotel, 38th Floor (roof level)	6/27/09	0.56	Mercury	EPA 324/1631	BRL	6/30/09	< 26.8	No	No	
TotalHg-ST1-6/28/09	0927004-01	Southwest Area (sidewalk bridge level)	6/28/09	0.56	Mercury	EPA 324/1631	BRL	6/30/09	< 26.8	No	No	
TotalHg-ST2-6/28/09	0927004-02	Southeast Area (sidewalk bridge level)	6/28/09	0.59	Mercury	EPA 324/1631	BRL	6/30/09	< 25.4	No	No	
TotalHg-ST4-6/28/09	0927004-03	Northwest Area (street-level)	6/28/09	0.55	Mercury	EPA 324/1631	BRL	6/30/09	< 27.3	No	No	
TotalHg-ST5-6/28/09	0927004-04	Firehouse #10 (roof level)	6/28/09	0.57	Mercury	EPA 324/1631	BRL	6/30/09	< 26.3	No	No	
TotalHg-ST10-6/28/09	0927004-05	North Side Sidewalk Bridge	6/28/09	0.56	Mercury	EPA 324/1631	BRL	6/30/09	< 26.8	No	No	
TotalHg-ST11-6/28/09	0927004-06	90 Trinity Place (roof level)	6/28/09	0.57	Mercury	EPA 324/1631	BRL	6/30/09	< 26.3	No	No	
TotalHg-ST12-6/28/09	0927004-07	110 Greenwich Street (roof level)	6/28/09	0.58	Mercury	EPA 324/1631	BRL	6/30/09	< 25.9	No	No	
TotalHg-ST13-6/28/09	0927004-08	Marriott Hotel, 38th Floor (roof level)	6/28/09	0.55	Mercury	EPA 324/1631	BRL	6/30/09	< 27.3	No	No	