

| TRC Field Sample No. | Sample No.  | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
|                      |             |   |                       |                                 |         |                   |     |                         | 300                                   |                                   |  |          |
|                      |             |   |                       |                                 |         |                   |     |                         | 3,000                                 |                                   |  |          |
| TotalHg-ST1-6/30/06  | 06BR1012-01 | Southwest Area (sidewalk bridge level)              | 6/30/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-6/30/06  | 06BR1012-02 | Southeast Area (sidewalk bridge level)              | 6/30/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST5-6/30/06  | 06BR1012-03 | Firehouse #10 (roof level)                          | 6/30/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-6/30/06 | 06BR1012-04 | North Side Sidewalk Bridge                          | 6/30/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST11-6/30/06 | 06BR1012-05 | 90 Trinity Place (roof level)                       | 6/30/06               | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST12-6/30/06 | 06BR1012-06 | 110 Greenwich Street (roof level)                   | 6/30/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST13-6/30/06 | 06BR1012-07 | Marriott Hotel, 38th Floor (roof level)             | 6/30/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST14-6/30/06 | 06BR1012-08 | West Face - South end at corner (scaffolding level) | 6/30/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST15-6/30/06 | 06BR1012-09 | South Face - East end at corner (scaffolding level) | 6/30/06               | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST16-6/30/06 | 06BR1012-10 | East Face - North end at corner (scaffolding level) | 6/30/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST17-6/30/06 | 06BR1012-11 | North Face - West end at corner (scaffolding level) | 6/30/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST1-7/1/06   | 06BR1013-01 | Southwest Area (sidewalk bridge level)              | 7/1/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-7/1/06   | 06BR1013-02 | Southeast Area (sidewalk bridge level)              | 7/1/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST4-7/1/06   | 06BR1013-03 | Northwest Area (street-level)                       | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST5-7/1/06   | 06BR1013-04 | Firehouse #10 (roof level)                          | 7/1/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-7/1/06  | 06BR1013-05 | North Side Sidewalk Bridge                          | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST11-7/1/06  | 06BR1013-06 | 90 Trinity Place (roof level)                       | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST12-7/1/06  | 06BR1013-07 | 110 Greenwich Street (roof level)                   | 7/1/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST13-7/1/06  | 06BR1013-08 | Marriott Hotel, 38th Floor (roof level)             | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST14-7/1/06  | 06BR1013-09 | West Face - South end at corner (scaffolding level) | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST15-7/1/06  | 06BR1013-10 | South Face - East end at corner (scaffolding level) | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST16-7/1/06  | 06BR1013-11 | East Face - North end at corner (scaffolding level) | 7/1/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST17-7/1/06  | 06BR1013-12 | North Face - West end at corner (scaffolding level) | 7/1/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST1-7/2/06   | 06BR1014-01 | Southwest Area (sidewalk bridge level)              | 7/2/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-7/2/06   | 06BR1014-02 | Southeast Area (sidewalk bridge level)              | 7/2/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST4-7/2/06   | 06BR1014-03 | Northwest Area (street-level)                       | 7/2/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST5-7/2/06   | 06BR1014-04 | Firehouse #10 (roof level)                          | 7/2/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-7/2/06  | 06BR1014-05 | North Side Sidewalk Bridge                          | 7/2/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST11-7/2/06  | 06BR1014-06 | 90 Trinity Place (roof level)                       | 7/2/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST12-7/2/06  | 06BR1014-07 | 110 Greenwich Street (roof level)                   | 7/2/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST13-7/2/06  | 06BR1014-08 | Marriott Hotel, 38th Floor (roof level)             | 7/2/06                | 0.60                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST14-7/2/06  | 06BR1014-09 | West Face - South end at corner (scaffolding level) | 7/2/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST15-7/2/06  | 06BR1014-10 | South Face - East end at corner (scaffolding level) | 7/2/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST16-7/2/06  | 06BR1014-11 | East Face - North end at corner (scaffolding level) | 7/2/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST17-7/2/06  | 06BR1014-12 | North Face - West end at corner (scaffolding level) | 7/2/06                | 0.60                            | Mercury | EPA 324/1631      | BRL | 7/5/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST1-7/3/06   | 06BR1018-01 | Southwest Area (sidewalk bridge level)              | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST2-7/3/06   | 06BR1018-02 | Southeast Area (sidewalk bridge level)              | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST4-7/3/06   | 06BR1018-03 | Northwest Area (street-level)                       | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST5-7/3/06   | 06BR1018-04 | Firehouse #10 (roof level)                          | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST10-7/3/06  | 06BR1018-05 | North Side Sidewalk Bridge                          | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST11-7/3/06  | 06BR1018-06 | 90 Trinity Place (roof level)                       | 7/3/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST12-7/3/06  | 06BR1018-07 | 110 Greenwich Street (roof level)                   | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST13-7/3/06  | 06BR1018-08 | Marriott Hotel, 38th Floor (roof level)             | 7/3/06                | 0.54                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST14-7/3/06  | 06BR1018-09 | West Face - South end at corner (scaffolding level) | 7/3/06                | 0.54                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST15-7/3/06  | 06BR1018-10 | South Face - East end at corner (scaffolding level) | 7/3/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST16-7/3/06  | 06BR1018-11 | East Face - North end at corner (scaffolding level) | 7/3/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST17-7/3/06  | 06BR1018-12 | North Face - West end at corner (scaffolding level) | 7/3/06                | 0.55                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST1-7/4/06   | 06BR1019-01 | Southwest Area (sidewalk bridge level)              | 7/4/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST2-7/4/06   | 06BR1019-02 | Southeast Area (sidewalk bridge level)              | 7/4/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST4-7/4/06   | 06BR1019-03 | Northwest Area (street-level)                       | 7/4/06                | 0.57                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST5-7/4/06   | 06BR1019-04 | Firehouse #10 (roof level)                          | 7/4/06                | 0.60                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST10-7/4/06  | 06BR1019-05 | North Side Sidewalk Bridge                          | 7/4/06                | 0.58                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST11-7/4/06  | 06BR1019-06 | 90 Trinity Place (roof level)                       | 7/4/06                | 0.56                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST12-7/4/06  | 06BR1019-07 | 110 Greenwich Street (roof level)                   | 7/4/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST13-7/4/06  | 06BR1019-08 | Marriott Hotel, 38th Floor (roof level)             | 7/4/06                | 0.59                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST14-7/4/06  | 06BR1019-09 | West Face - South end at corner (scaffolding level) | 7/4/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST15-7/4/06  | 06BR1019-10 | South Face - East end at corner (scaffolding level) | 7/4/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST16-7/4/06  | 06BR1019-11 | East Face - North end at corner (scaffolding level) | 7/4/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST17-7/4/06  | 06BR1019-12 | North Face - West end at corner (scaffolding level) | 7/4/06                | 0.61                            | Mercury | EPA 324/1631      | BRL | 7/6/06                  | < 25.0                                | No                                | No                                       |          |

Note:

1. Mercury sample at Station 4 (Northwest Area (street level)) on June 30, 2006 was not available for analysis on account of media damage.