

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-7/14/07	07BR1010-01	Southwest Area (sidewalk bridge level)	7/14/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST2-7/14/07	07BR1010-02	Southeast Area (sidewalk bridge level)	7/14/07	0.56	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST5-7/14/07	07BR1010-03	Firehouse #10 (roof level)	7/14/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST10-7/14/07	07BR1010-04	North Side Sidewalk Bridge	7/14/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST11-7/14/07	07BR1010-05	90 Trinity Place (roof level)	7/14/07	0.55	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST13-7/14/07	07BR1010-06	Marriott Hotel, 38th Floor (roof level)	7/14/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST14-7/14/07	07BR1010-07	West Face - South end at corner (scaffolding level)	7/14/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST15-7/14/07	07BR1010-08	South Face - East end at corner (scaffolding level)	7/14/07	0.55	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST16-7/14/07	07BR1010-09	East Face - North end at corner (scaffolding level)	7/14/07	0.56	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST17-7/14/07	07BR1010-10	North Face - West end at corner (scaffolding level)	7/14/07	0.56	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST1-7/15/07	07BR1011-01	Southwest Area (sidewalk bridge level)	7/15/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST2-7/15/07	07BR1011-02	Southeast Area (sidewalk bridge level)	7/15/07	0.55	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST5-7/15/07	07BR1011-03	Firehouse #10 (roof level)	7/15/07	0.57	Mercury	EPA 324/1631	BRL	7/17/07	< 26.0	No	No	
TotalHg-ST10-7/15/07	07BR1011-04	North Side Sidewalk Bridge	7/15/07	0.55	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST11-7/15/07	07BR1011-05	90 Trinity Place (roof level)	7/15/07	0.53	Mercury	EPA 324/1631	BRL	7/17/07	< 28.0	No	No	
TotalHg-ST13-7/15/07	07BR1011-06	Marriott Hotel, 38th Floor (roof level)	7/15/07	0.55	Mercury	EPA 324/1631	BRL	7/17/07	< 27.0	No	No	
TotalHg-ST14-7/15/07	07BR1011-07	West Face - South end at corner (scaffolding level)	7/15/07	0.59	Mercury	EPA 324/1631	BRL	7/17/07	< 25.0	No	No	
TotalHg-ST15-7/15/07	07BR1011-08	South Face - East end at corner (scaffolding level)	7/15/07	0.59	Mercury	EPA 324/1631	BRL	7/17/07	< 25.0	No	No	
TotalHg-ST16-7/15/07	07BR1011-09	East Face - North end at corner (scaffolding level)	7/15/07	0.62	Mercury	EPA 324/1631	BRL	7/17/07	< 24.0	No	No	
TotalHg-ST17-7/15/07	07BR1011-10	North Face - West end at corner (scaffolding level)	7/15/07	0.54	Mercury	EPA 324/1631	BRL	7/17/07	< 28.0	No	No	

Note:

- Mercury samples at Station 4 (Northwest Area [street-level]) on July 14 and 15, 2007 were not available for analysis on account of power failure.
- Mercury samples at Station 12 (110 Greenwich Street (roof level)) on July 14 and 15, 2007 were not available for analysis. The station was not accessible and the samples could not be collected.