

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									300	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/5/09	0932030-01	Southwest Area (sidewalk bridge level)	8/5/09	0.52	Mercury	EPA 324/1631	BRL	8/7/09	< 28.9	No	No	
TotalHg-ST2-8/5/09	0932030-02	Southeast Area (sidewalk bridge level)	8/5/09	0.54	Mercury	EPA 324/1631	BRL	8/7/09	< 27.8	No	No	
TotalHg-ST4-8/5/09	0932030-03	Northwest Area (street-level)	8/5/09	0.52	Mercury	EPA 324/1631	BRL	8/7/09	< 28.9	No	No	
TotalHg-ST5-8/5/09	0932030-04	Firehouse #10 (roof level)	8/5/09	0.53	Mercury	EPA 324/1631	BRL	8/7/09	< 28.3	No	No	
TotalHg-ST10-8/5/09	0932030-05	North Side Sidewalk Bridge	8/5/09	0.54	Mercury	EPA 324/1631	BRL	8/7/09	< 27.8	No	No	
TotalHg-ST11-8/5/09	0932030-06	90 Trinity Place (roof level)	8/5/09	0.57	Mercury	EPA 324/1631	BRL	8/7/09	< 26.3	No	No	
TotalHg-ST12-8/5/09	0932030-07	110 Greenwich Street (roof level)	8/5/09	0.55	Mercury	EPA 324/1631	BRL	8/7/09	< 27.3	No	No	
TotalHg-ST13-8/5/09	0932030-08	Marriott Hotel, 38th Floor (roof level)	8/5/09	0.53	Mercury	EPA 324/1631	BRL	8/7/09	< 28.3	No	No	
TotalHg-ST1-8/6/09	0933001-01	Southwest Area (sidewalk bridge level)	8/6/09	0.56	Mercury	EPA 324/1631	BRL	8/8/09	< 26.8	No	No	
TotalHg-ST2-8/6/09	0933001-02	Southeast Area (sidewalk bridge level)	8/6/09	0.57	Mercury	EPA 324/1631	BRL	8/8/09	< 26.3	No	No	
TotalHg-ST4-8/6/09	0933001-03	Northwest Area (street-level)	8/6/09	0.58	Mercury	EPA 324/1631	BRL	8/8/09	< 25.9	No	No	
TotalHg-ST5-8/6/09	0933001-04	Firehouse #10 (roof level)	8/6/09	0.61	Mercury	EPA 324/1631	BRL	8/8/09	< 24.6	No	No	
TotalHg-ST10-8/6/09	0933001-05	North Side Sidewalk Bridge	8/6/09	0.53	Mercury	EPA 324/1631	BRL	8/8/09	< 28.3	No	No	
TotalHg-ST11-8/6/09	0933001-06	90 Trinity Place (roof level)	8/6/09	0.57	Mercury	EPA 324/1631	BRL	8/8/09	< 26.3	No	No	
TotalHg-ST12-8/6/09	0933001-07	110 Greenwich Street (roof level)	8/6/09	0.55	Mercury	EPA 324/1631	BRL	8/8/09	< 27.3	No	No	
TotalHg-ST13-8/6/09	0933001-08	Marriott Hotel, 38th Floor (roof level)	8/6/09	0.56	Mercury	EPA 324/1631	BRL	8/8/09	< 26.8	No	No	
TotalHg-ST1-8/7/09	0933002-01	Southwest Area (sidewalk bridge level)	8/7/09	0.53	Mercury	EPA 324/1631	BRL	8/10/09	< 28.3	No	No	
TotalHg-ST2-8/7/09	0933002-02	Southeast Area (sidewalk bridge level)	8/7/09	0.57	Mercury	EPA 324/1631	BRL	8/10/09	< 26.3	No	No	
TotalHg-ST4-8/7/09	0933002-03	Northwest Area (street-level)	8/7/09	0.57	Mercury	EPA 324/1631	BRL	8/10/09	< 26.3	No	No	
TotalHg-ST5-8/7/09	0933002-04	Firehouse #10 (roof level)	8/7/09	0.58	Mercury	EPA 324/1631	BRL	8/10/09	< 25.9	No	No	
TotalHg-ST10-8/7/09	0933002-05	North Side Sidewalk Bridge	8/7/09	0.52	Mercury	EPA 324/1631	BRL	8/10/09	< 28.9	No	No	
TotalHg-ST11-8/7/09	0933002-06	90 Trinity Place (roof level)	8/7/09	0.56	Mercury	EPA 324/1631	BRL	8/10/09	< 26.8	No	No	
TotalHg-ST12-8/7/09	0933002-07	110 Greenwich Street (roof level)	8/7/09	0.57	Mercury	EPA 324/1631	BRL	8/10/09	< 26.3	No	No	
TotalHg-ST13-8/7/09	0933002-08	Marriott Hotel, 38th Floor (roof level)	8/7/09	0.57	Mercury	EPA 324/1631	BRL	8/10/09	< 26.3	No	No	