

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-8/6/08	0832048-01	Southwest Area (sidewalk bridge level)	8/6/08	0.56	Mercury	EPA 324/1631	BRL	8/8/08	< 27.0	No	No	
TotalHg-ST2-8/6/08	0832048-02	Southeast Area (sidewalk bridge level)	8/6/08	0.58	Mercury	EPA 324/1631	BRL	8/8/08	< 26.0	No	No	
TotalHg-ST4-8/6/08	0832048-03	Northwest Area (street-level)	8/6/08	0.55	Mercury	EPA 324/1631	BRL	8/8/08	< 27.0	No	No	
TotalHg-ST5-8/6/08	0832048-04	Firehouse #10 (roof level)	8/6/08	0.56	Mercury	EPA 324/1631	BRL	8/8/08	< 27.0	No	No	
TotalHg-ST10-8/6/08	0832048-05	North Side Sidewalk Bridge	8/6/08	0.58	Mercury	EPA 324/1631	BRL	8/8/08	< 26.0	No	No	
TotalHg-ST11-8/6/08	0832048-06	90 Trinity Place (roof level)	8/6/08	0.56	Mercury	EPA 324/1631	BRL	8/8/08	< 27.0	No	No	
TotalHg-ST12-8/6/08	0832048-07	110 Greenwich Street (roof level)	8/6/08	0.56	Mercury	EPA 324/1631	BRL	8/8/08	< 27.0	No	No	
TotalHg-ST13-8/6/08	0832048-08	Marriott Hotel, 38th Floor (roof level)	8/6/08	0.58	Mercury	EPA 324/1631	BRL	8/8/08	< 26.0	No	No	
TotalHg-ST14-8/6/08	0832048-09	West Face - South end at corner (scaffolding level)	8/6/08	0.54	Mercury	EPA 324/1631	BRL	8/8/08	< 28.0	No	No	
TotalHg-ST15-8/6/08	0832048-10	South Face - East end at corner (scaffolding level)	8/6/08	0.52	Mercury	EPA 324/1631	BRL	8/8/08	< 29.0	No	No	
TotalHg-ST16-8/6/08	0832048-11	East Face - North end at corner (scaffolding level)	8/6/08	0.57	Mercury	EPA 324/1631	BRL	8/8/08	< 26.0	No	No	
TotalHg-ST17-8/6/08	0832048-12	North Face - West end at corner (scaffolding level)	8/6/08	0.54	Mercury	EPA 324/1631	BRL	8/8/08	< 28.0	No	No	
TotalHg-ST1-8/7/08	0833001-01	Southwest Area (sidewalk bridge level)	8/7/08	0.55	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST2-8/7/08	0833001-02	Southeast Area (sidewalk bridge level)	8/7/08	0.53	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST4-8/7/08	0833001-03	Northwest Area (street-level)	8/7/08	0.53	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST5-8/7/08	0833001-04	Firehouse #10 (roof level)	8/7/08	0.58	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST10-8/7/08	0833001-05	North Side Sidewalk Bridge	8/7/08	0.55	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST11-8/7/08	0833001-06	90 Trinity Place (roof level)	8/7/08	0.58	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST12-8/7/08	0833001-07	110 Greenwich Street (roof level)	8/7/08	0.56	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST13-8/7/08	0833001-08	Marriott Hotel, 38th Floor (roof level)	8/7/08	0.53	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST14-8/7/08	0833001-09	West Face - South end at corner (scaffolding level)	8/7/08	0.56	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST15-8/7/08	0833001-10	South Face - East end at corner (scaffolding level)	8/7/08	0.55	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST16-8/7/08	0833001-11	East Face - North end at corner (scaffolding level)	8/7/08	0.57	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST17-8/7/08	0833001-12	North Face - West end at corner (scaffolding level)	8/7/08	0.58	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST1-8/8/08	0833002-01	Southwest Area (sidewalk bridge level)	8/8/08	0.60	Mercury	EPA 324/1631	BRL	8/11/08	< 25.0	No	No	
TotalHg-ST2-8/8/08	0833002-02	Southeast Area (sidewalk bridge level)	8/8/08	0.59	Mercury	EPA 324/1631	BRL	8/11/08	< 25.0	No	No	
TotalHg-ST4-8/8/08	0833002-03	Northwest Area (street-level)	8/8/08	0.61	Mercury	EPA 324/1631	BRL	8/11/08	< 25.0	No	No	
TotalHg-ST5-8/8/08	0833002-04	Firehouse #10 (roof level)	8/8/08	0.58	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST10-8/8/08	0833002-05	North Side Sidewalk Bridge	8/8/08	0.59	Mercury	EPA 324/1631	BRL	8/11/08	< 25.0	No	No	
TotalHg-ST11-8/8/08	0833002-06	90 Trinity Place (roof level)	8/8/08	0.55	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST12-8/8/08	0833002-07	110 Greenwich Street (roof level)	8/8/08	0.54	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST13-8/8/08	0833002-08	Marriott Hotel, 38th Floor (roof level)	8/8/08	0.57	Mercury	EPA 324/1631	BRL	8/11/08	< 26.0	No	No	
TotalHg-ST14-8/8/08	0833002-09	West Face - South end at corner (scaffolding level)	8/8/08	0.56	Mercury	EPA 324/1631	BRL	8/11/08	< 27.0	No	No	
TotalHg-ST15-8/8/08	0833002-10	South Face - East end at corner (scaffolding level)	8/8/08	0.53	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST16-8/8/08	0833002-11	East Face - North end at corner (scaffolding level)	8/8/08	0.54	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	
TotalHg-ST17-8/8/08	0833002-12	North Face - West end at corner (scaffolding level)	8/8/08	0.53	Mercury	EPA 324/1631	BRL	8/11/08	< 28.0	No	No	