

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/11/06	06BR1248-01	Southwest Area (sidewalk bridge level)	8/11/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST2-8/11/06	06BR1248-02	Southeast Area (sidewalk bridge level)	8/11/06	0.58	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST4-8/11/06	06BR1248-03	Northwest Area (street-level)	8/11/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST5-8/11/06	06BR1248-04	Firehouse #10 (roof level)	8/11/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST6-8/11/06	06BR1249-01	Southwest Area (roof level)	8/11/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST7-8/11/06	06BR1249-02	Southeast Area (roof level)	8/11/06	0.63	Mercury	EPA 324/1631	BRL	8/15/06	< 24.0	No	No	
TotalHg-ST8-8/11/06	06BR1249-03	Northeast Area (roof level)	8/11/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST9-8/11/06	06BR1249-04	Northwest Area (roof level)	8/11/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST10-8/11/06	06BR1248-05	North Side Sidewalk Bridge	8/11/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST11-8/11/06	06BR1248-06	90 Trinity Place (roof level)	8/11/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST12-8/11/06	06BR1248-07	110 Greenwich Street (roof level)	8/11/06	0.53	Mercury	EPA 324/1631	BRL	8/15/06	< 28.0	No	No	
TotalHg-ST13-8/11/06	06BR1248-08	Marriott Hotel, 38th Floor (roof level)	8/11/06	0.60	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST14-8/11/06	06BR1248-09	West Face - South end at corner (scaffolding level)	8/11/06	0.58	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST15-8/11/06	06BR1248-10	South Face - East end at corner (scaffolding level)	8/11/06	0.58	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST16-8/11/06	06BR1248-11	East Face - North end at corner (scaffolding level)	8/11/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST17-8/11/06	06BR1248-12	North Face - West end at corner (scaffolding level)	8/11/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST1-8/12/06	06BR1250-01	Southwest Area (sidewalk bridge level)	8/12/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST2-8/12/06	06BR1250-02	Southeast Area (sidewalk bridge level)	8/12/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST4-8/12/06	06BR1250-03	Northwest Area (street-level)	8/12/06	0.54	Mercury	EPA 324/1631	BRL	8/15/06	< 28.0	No	No	
TotalHg-ST5-8/12/06	06BR1250-04	Firehouse #10 (roof level)	8/12/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST6-8/12/06	06BR1251-01	Southwest Area (roof level)	8/12/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST7-8/12/06	06BR1251-02	Southeast Area (roof level)	8/12/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST8-8/12/06	06BR1251-03	Northeast Area (roof level)	8/12/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST9-8/12/06	06BR1251-04	Northwest Area (roof level)	8/12/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST10-8/12/06	06BR1250-05	North Side Sidewalk Bridge	8/12/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST11-8/12/06	06BR1250-06	90 Trinity Place (roof level)	8/12/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST12-8/12/06	06BR1250-07	110 Greenwich Street (roof level)	8/12/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST13-8/12/06	06BR1250-08	Marriott Hotel, 38th Floor (roof level)	8/12/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST14-8/12/06	06BR1250-09	West Face - South end at corner (scaffolding level)	8/12/06	0.52	Mercury	EPA 324/1631	BRL	8/15/06	< 29.0	No	No	
TotalHg-ST15-8/12/06	06BR1250-10	South Face - East end at corner (scaffolding level)	8/12/06	0.53	Mercury	EPA 324/1631	BRL	8/15/06	< 28.0	No	No	
TotalHg-ST16-8/12/06	06BR1250-11	East Face - North end at corner (scaffolding level)	8/12/06	0.52	Mercury	EPA 324/1631	BRL	8/15/06	< 29.0	No	No	
TotalHg-ST17-8/12/06	06BR1250-12	North Face - West end at corner (scaffolding level)	8/12/06	0.53	Mercury	EPA 324/1631	BRL	8/15/06	< 28.0	No	No	
TotalHg-ST1-8/13/06	06BR1252-01	Southwest Area (sidewalk bridge level)	8/13/06	0.58	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST2-8/13/06	06BR1252-02	Southeast Area (sidewalk bridge level)	8/13/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST4-8/13/06	06BR1252-03	Northwest Area (street-level)	8/13/06	0.60	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST5-8/13/06	06BR1252-04	Firehouse #10 (roof level)	8/13/06	0.60	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST6-8/13/06	06BR1253-01	Southwest Area (roof level)	8/13/06	0.57	Mercury	EPA 324/1631	BRL	8/15/06	< 26.0	No	No	
TotalHg-ST7-8/13/06	06BR1253-02	Southeast Area (roof level)	8/13/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST8-8/13/06	06BR1253-03	Northeast Area (roof level)	8/13/06	0.55	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST9-8/13/06	06BR1253-04	Northwest Area (roof level)	8/13/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST10-8/13/06	06BR1252-05	North Side Sidewalk Bridge	8/13/06	0.62	Mercury	EPA 324/1631	BRL	8/15/06	< 24.0	No	No	
TotalHg-ST11-8/13/06	06BR1252-06	90 Trinity Place (roof level)	8/13/06	0.56	Mercury	EPA 324/1631	BRL	8/15/06	< 27.0	No	No	
TotalHg-ST12-8/13/06	06BR1252-07	110 Greenwich Street (roof level)	8/13/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST13-8/13/06	06BR1252-08	Marriott Hotel, 38th Floor (roof level)	8/13/06	0.59	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST14-8/13/06	06BR1252-09	West Face - South end at corner (scaffolding level)	8/13/06	0.61	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST15-8/13/06	06BR1252-10	South Face - East end at corner (scaffolding level)	8/13/06	0.67	Mercury	EPA 324/1631	BRL	8/15/06	< 22.0	No	No	
TotalHg-ST16-8/13/06	06BR1252-11	East Face - North end at corner (scaffolding level)	8/13/06	0.61	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	
TotalHg-ST17-8/13/06	06BR1252-12	North Face - West end at corner (scaffolding level)	8/13/06	0.60	Mercury	EPA 324/1631	BRL	8/15/06	< 25.0	No	No	