

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/23/08	0835006-01	Southwest Area (sidewalk bridge level)	8/23/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST2-8/23/08	0835006-02	Southeast Area (sidewalk bridge level)	8/23/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST4-8/23/08	0835006-03	Northwest Area (street-level)	8/23/08	0.56	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST5-8/23/08	0835006-04	Firehouse #10 (roof level)	8/23/08	0.59	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST10-8/23/08	0835006-05	North Side Sidewalk Bridge	8/23/08	0.58	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST11-8/23/08	0835006-06	90 Trinity Place (roof level)	8/23/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST12-8/23/08	0835006-07	110 Greenwich Street (roof level)	8/23/08	0.59	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST13-8/23/08	0835006-08	Marriott Hotel, 38th Floor (roof level)	8/23/08	0.60	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST14-8/23/08	0835006-09	West Face - South end at corner (scaffolding level)	8/23/08	0.56	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST15-8/23/08	0835006-10	South Face - East end at corner (scaffolding level)	8/23/08	0.55	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST16-8/23/08	0835006-11	East Face - North end at corner (scaffolding level)	8/23/08	0.62	Mercury	EPA 324/1631	BRL	8/26/08	< 24.0	No	No	
TotalHg-ST17-8/23/08	0835006-12	North Face - West end at corner (scaffolding level)	8/23/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST1-8/24/08	0835008-01	Southwest Area (sidewalk bridge level)	8/24/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST2-8/24/08	0835008-02	Southeast Area (sidewalk bridge level)	8/24/08	0.60	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST4-8/24/08	0835008-03	Northwest Area (street-level)	8/24/08	0.53	Mercury	EPA 324/1631	BRL	8/26/08	< 28.0	No	No	
TotalHg-ST5-8/24/08	0835008-04	Firehouse #10 (roof level)	8/24/08	0.54	Mercury	EPA 324/1631	BRL	8/26/08	< 28.0	No	No	
TotalHg-ST10-8/24/08	0835008-05	North Side Sidewalk Bridge	8/24/08	0.56	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST11-8/24/08	0835008-06	90 Trinity Place (roof level)	8/24/08	0.55	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST12-8/24/08	0835008-07	110 Greenwich Street (roof level)	8/24/08	0.57	Mercury	EPA 324/1631	BRL	8/26/08	< 26.0	No	No	
TotalHg-ST13-8/24/08	0835008-08	Marriott Hotel, 38th Floor (roof level)	8/24/08	0.55	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST14-8/24/08	0835008-09	West Face - South end at corner (scaffolding level)	8/24/08	0.60	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST15-8/24/08	0835008-10	South Face - East end at corner (scaffolding level)	8/24/08	0.56	Mercury	EPA 324/1631	BRL	8/26/08	< 27.0	No	No	
TotalHg-ST16-8/24/08	0835008-11	East Face - North end at corner (scaffolding level)	8/24/08	0.62	Mercury	EPA 324/1631	BRL	8/26/08	< 24.0	No	No	
TotalHg-ST17-8/24/08	0835008-12	North Face - West end at corner (scaffolding level)	8/24/08	0.59	Mercury	EPA 324/1631	BRL	8/26/08	< 25.0	No	No	
TotalHg-ST1-8/25/08	0835027-01	Southwest Area (sidewalk bridge level)	8/25/08	0.55	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST2-8/25/08	0835027-02	Southeast Area (sidewalk bridge level)	8/25/08	0.56	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST4-8/25/08	0835027-03	Northwest Area (street-level)	8/25/08	0.58	Mercury	EPA 324/1631	BRL	8/27/08	< 26.0	No	No	
TotalHg-ST5-8/25/08	0835027-04	Firehouse #10 (roof level)	8/25/08	0.56	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST10-8/25/08	0835027-05	North Side Sidewalk Bridge	8/25/08	0.57	Mercury	EPA 324/1631	BRL	8/27/08	< 26.0	No	No	
TotalHg-ST11-8/25/08	0835027-06	90 Trinity Place (roof level)	8/25/08	0.58	Mercury	EPA 324/1631	BRL	8/27/08	< 26.0	No	No	
TotalHg-ST12-8/25/08	0835027-07	110 Greenwich Street (roof level)	8/25/08	0.56	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST13-8/25/08	0835027-08	Marriott Hotel, 38th Floor (roof level)	8/25/08	0.58	Mercury	EPA 324/1631	BRL	8/27/08	< 26.0	No	No	
TotalHg-ST14-8/25/08	0835027-09	West Face - South end at corner (scaffolding level)	8/25/08	0.56	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST15-8/25/08	0835027-10	South Face - East end at corner (scaffolding level)	8/25/08	0.55	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST16-8/25/08	0835027-11	East Face - North end at corner (scaffolding level)	8/25/08	0.55	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	
TotalHg-ST17-8/25/08	0835027-12	North Face - West end at corner (scaffolding level)	8/25/08	0.55	Mercury	EPA 324/1631	BRL	8/27/08	< 27.0	No	No	