

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/27/08	0836001-01	Southwest Area (sidewalk bridge level)	8/27/08	0.58	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST2-8/27/08	0836001-02	Southeast Area (sidewalk bridge level)	8/27/08	0.59	Mercury	EPA 324/1631	BRL	9/2/08	< 25.0	No	No	
TotalHg-ST4-8/27/08	0836001-03	Northwest Area (street-level)	8/27/08	0.57	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST5-8/27/08	0836001-04	Firehouse #10 (roof level)	8/27/08	0.58	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST10-8/27/08	0836001-05	North Side Sidewalk Bridge	8/27/08	0.57	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST11-8/27/08	0836001-06	90 Trinity Place (roof level)	8/27/08	0.56	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST12-8/27/08	0836001-07	110 Greenwich Street (roof level)	8/27/08	0.55	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST13-8/27/08	0836001-08	Marriott Hotel, 38th Floor (roof level)	8/27/08	0.54	Mercury	EPA 324/1631	BRL	9/2/08	< 28.0	No	No	
TotalHg-ST14-8/27/08	0836001-09	West Face - South end at corner (scaffolding level)	8/27/08	0.56	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST15-8/27/08	0836001-10	South Face - East end at corner (scaffolding level)	8/27/08	0.54	Mercury	EPA 324/1631	BRL	9/2/08	< 28.0	No	No	
TotalHg-ST16-8/27/08	0836001-11	East Face - North end at corner (scaffolding level)	8/27/08	0.54	Mercury	EPA 324/1631	BRL	9/2/08	< 28.0	No	No	
TotalHg-ST17-8/27/08	0836001-12	North Face - West end at corner (scaffolding level)	8/27/08	0.56	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST1-8/28/08	0835057-01	Southwest Area (sidewalk bridge level)	8/28/08	0.57	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST2-8/28/08	0835057-02	Southeast Area (sidewalk bridge level)	8/28/08	0.58	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST4-8/28/08	0835057-03	Northwest Area (street-level)	8/28/08	0.56	Mercury	EPA 324/1631	BRL	8/30/08	< 27.0	No	No	
TotalHg-ST5-8/28/08	0835057-04	Firehouse #10 (roof level)	8/28/08	0.57	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST10-8/28/08	0835057-05	North Side Sidewalk Bridge	8/28/08	0.57	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST100-8/28/08	0835057-13	Station 10 Field Duplicate	8/28/08	0.59	Mercury	EPA 324/1631	BRL	8/30/08	< 25.0	No	No	
TotalHg-ST11-8/28/08	0835057-06	90 Trinity Place (roof level)	8/28/08	0.55	Mercury	EPA 324/1631	BRL	8/30/08	< 27.0	No	No	
TotalHg-ST12-8/28/08	0835057-07	110 Greenwich Street (roof level)	8/28/08	0.57	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST13-8/28/08	0835057-08	Marriott Hotel, 38th Floor (roof level)	8/28/08	0.56	Mercury	EPA 324/1631	BRL	8/30/08	< 27.0	No	No	
TotalHg-ST14-8/28/08	0835057-09	West Face - South end at corner (scaffolding level)	8/28/08	0.56	Mercury	EPA 324/1631	BRL	8/30/08	< 27.0	No	No	
TotalHg-ST15-8/28/08	0835057-10	South Face - East end at corner (scaffolding level)	8/28/08	0.57	Mercury	EPA 324/1631	BRL	8/30/08	< 26.0	No	No	
TotalHg-ST16-8/28/08	0835057-11	East Face - North end at corner (scaffolding level)	8/28/08	0.56	Mercury	EPA 324/1631	BRL	8/30/08	< 27.0	No	No	
TotalHg-ST17-8/28/08	0835057-12	North Face - West end at corner (scaffolding level)	8/28/08	0.59	Mercury	EPA 324/1631	BRL	8/30/08	< 25.0	No	No	
TotalHg-ST1-8/29/08	0836002-01	Southwest Area (sidewalk bridge level)	8/29/08	0.57	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST2-8/29/08	0836002-02	Southeast Area (sidewalk bridge level)	8/29/08	0.61	Mercury	EPA 324/1631	BRL	9/2/08	< 25.0	No	No	
TotalHg-ST4-8/29/08	0836002-03	Northwest Area (street-level)	8/29/08	0.55	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST5-8/29/08	0836002-04	Firehouse #10 (roof level)	8/29/08	0.58	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST10-8/29/08	0836002-05	North Side Sidewalk Bridge	8/29/08	0.56	Mercury	EPA 324/1631	BRL	9/2/08	< 27.0	No	No	
TotalHg-ST11-8/29/08	0836002-06	90 Trinity Place (roof level)	8/29/08	0.59	Mercury	EPA 324/1631	BRL	9/2/08	< 25.0	No	No	
TotalHg-ST12-8/29/08	0836002-07	110 Greenwich Street (roof level)	8/29/08	0.57	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST13-8/29/08	0836002-08	Marriott Hotel, 38th Floor (roof level)	8/29/08	0.58	Mercury	EPA 324/1631	BRL	9/2/08	< 26.0	No	No	
TotalHg-ST14-8/29/08	0836002-09	West Face - South end at corner (scaffolding level)	8/29/08	0.51	Mercury	EPA 324/1631	BRL	9/2/08	< 29.0	No	No	
TotalHg-ST15-8/29/08	0836002-10	South Face - East end at corner (scaffolding level)	8/29/08	0.52	Mercury	EPA 324/1631	BRL	9/2/08	< 29.0	No	No	
TotalHg-ST16-8/29/08	0836002-11	East Face - North end at corner (scaffolding level)	8/29/08	0.54	Mercury	EPA 324/1631	BRL	9/2/08	< 28.0	No	No	
TotalHg-ST17-8/29/08	0836002-12	North Face - West end at corner (scaffolding level)	8/29/08	0.52	Mercury	EPA 324/1631	BRL	9/2/08	< 29.0	No	No	