

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-9/01/09	0936018-01	Southwest Area (sidewalk bridge level)	9/1/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 27.3	No	No	
TotalHg-ST2-9/01/09	0936018-02	Southeast Area (sidewalk bridge level)	9/1/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 27.3	No	No	
TotalHg-ST4-9/01/09	0936018-03	Northwest Area (street-level)	9/1/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 27.3	No	No	
TotalHg-ST5-9/01/09	0936018-04	Firehouse #10 (roof level)	9/1/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 26.8	No	No	
TotalHg-ST10-9/01/09	0936018-05	North Side Sidewalk Bridge	9/1/09	0.53	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 28.3	No	No	
TotalHg-ST11-9/01/09	0936018-06	90 Trinity Place (roof level)	9/1/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 27.3	No	No	
TotalHg-ST12-9/01/09	0936018-07	110 Greenwich Street (roof level)	9/1/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 26.8	No	No	
TotalHg-ST13-9/01/09	0936018-08	Marriott Hotel, 38th Floor (roof level)	9/1/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/3/09	< 27.3	No	No	
TotalHg-ST1-9/02/09	0936024-01	Southwest Area (sidewalk bridge level)	9/2/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 27.3	No	No	
TotalHg-ST2-9/02/09	0936024-02	Southeast Area (sidewalk bridge level)	9/2/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 27.3	No	No	
TotalHg-ST4-9/02/09	0936024-03	Northwest Area (street-level)	9/2/09	0.62	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 24.2	No	No	
TotalHg-ST5-9/02/09	0936024-04	Firehouse #10 (roof level)	9/2/09	0.52	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 28.9	No	No	
TotalHg-ST10-9/02/09	0936024-05	North Side Sidewalk Bridge	9/2/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 27.3	No	No	
TotalHg-ST11-9/02/09	0936024-06	90 Trinity Place (roof level)	9/2/09	0.59	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 25.4	No	No	
TotalHg-ST12-9/02/09	0936024-07	110 Greenwich Street (roof level)	9/2/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 26.8	No	No	
TotalHg-ST13-9/02/09	0936024-08	Marriott Hotel, 38th Floor (roof level)	9/2/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/4/09	< 26.8	No	No	
TotalHg-ST1-9/03/09	0936027-01	Southwest Area (sidewalk bridge level)	9/3/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 26.3	No	No	
TotalHg-ST2-9/03/09	0936027-02	Southeast Area (sidewalk bridge level)	9/3/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 27.8	No	No	
TotalHg-ST4-9/03/09	0936027-03	Northwest Area (street-level)	9/3/09	0.60	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 25.0	No	No	
TotalHg-ST5-9/03/09	0936027-04	Firehouse #10 (roof level)	9/3/09	0.60	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 25.0	No	No	
TotalHg-ST10-9/03/09	0936027-05	North Side Sidewalk Bridge	9/3/09	0.61	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 24.6	No	No	
TotalHg-ST11-9/03/09	0936027-06	90 Trinity Place (roof level)	9/3/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 26.8	No	No	
TotalHg-ST12-9/03/09	0936027-07	110 Greenwich Street (roof level)	9/3/09	0.58	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 25.9	No	No	
TotalHg-ST13-9/03/09	0936027-08	Marriott Hotel, 38th Floor (roof level)	9/3/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/5/09	< 27.3	No	No	