

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-9/30/05	05BR1480-1	Southwest Area (street-level)	9/30/2005	0.6	Mercury	EPA 324/1631	BRL	10/4/2005	< 25.0	No	No	
TotalHg-ST2-9/30/05	05BR1480-2	Southeast Area (street-level)	9/30/2005	0.6	Mercury	EPA 324/1631	BRL	10/4/2005	< 25.0	No	No	
TotalHg-ST4-9/30/05	05BR1480-4	Northwest Area (street-level)	9/30/2005	0.59	Mercury	EPA 324/1631	BRL	10/4/2005	< 25.4	No	No	
TotalHg-ST5-9/30/05	05BR1480-5	Firehouse #10 (roof level)	9/30/2005	N/A	Mercury	EPA 324/1631	BRL	10/4/2005	< 15.0	No	No	Actual volume collected is unknown due to pump failure; reported result in the units of ng.
TotalHg-ST10-9/30/05	05BR1480-3	North Side Sidewalk Bridge	9/30/2005	0.59	Mercury	EPA 324/1631	BRL	10/4/2005	< 25.4	No	No	
TotalHg-ST1-10/1/05	05BR1480-7	Southwest Area (street-level)	10/1/2005	0.57	Mercury	EPA 324/1631	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST2-10/1/05	05BR1480-8	Southeast Area (street-level)	10/1/2005	0.57	Mercury	EPA 324/1631	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST4-10/1/05	05BR1480-10	Northwest Area (street-level)	10/1/2005	0.57	Mercury	EPA 324/1631	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST5-10/1/05	05BR1480-11	Firehouse #10 (roof level)	10/1/2005	0.65	Mercury	EPA 324/1631	BRL	10/4/2005	< 23.1	No	No	
TotalHg-ST10-10/1/05	05BR1480-9	North Side Sidewalk Bridge	10/1/2005	0.57	Mercury	EPA 324/1631	BRL	10/4/2005	< 26.3	No	No	
TotalHg-ST1-10/2/05	05BR1480-13	Southwest Area (street-level)	10/2/2005	0.54	Mercury	EPA 324/1631	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST2-10/2/05	05BR1480-14	Southeast Area (street-level)	10/2/2005	0.54	Mercury	EPA 324/1631	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST4-10/2/05	05BR1480-16	Northwest Area (street-level)	10/2/2005	0.54	Mercury	EPA 324/1631	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST5-10/2/05	05BR1480-17	Firehouse #10 (roof level)	10/2/2005	0.50	Mercury	EPA 324/1631	BRL	10/4/2005	< 30.0	No	No	
TotalHg-ST10-10/2/05	05BR1480-15	North Side Sidewalk Bridge	10/2/2005	0.54	Mercury	EPA 324/1631	BRL	10/4/2005	< 27.8	No	No	
TotalHg-ST1-10/3/05	05BR1488-1	Southwest Area (street-level)	10/3/2005	0.57	Mercury	EPA 324/1631	BRL	10/5/2005	< 26.3	No	No	
TotalHg-ST2-10/3/05	05BR1488-2	Southeast Area (street-level)	10/3/2005	0.57	Mercury	EPA 324/1631	BRL	10/5/2005	< 26.3	No	No	
TotalHg-ST4-10/3/05	05BR1488-3	Northwest Area (street-level)	10/3/2005	0.56	Mercury	EPA 324/1631	BRL	10/5/2005	< 26.8	No	No	
TotalHg-ST5-10/3/05	05BR1488-4	Firehouse #10 (roof level)	10/3/2005	0.56	Mercury	EPA 324/1631	BRL	10/5/2005	< 26.8	No	No	
TotalHg-ST10-10/3/05	05BR1488-5	North Side Sidewalk Bridge	10/3/2005	0.56	Mercury	EPA 324/1631	BRL	10/5/2005	< 26.8	No	No	