

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-10/2/06	06BR1577-01	Southwest Area (sidewalk bridge level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST2-10/2/06	06BR1577-02	Southeast Area (sidewalk bridge level)	10/2/06	0.59	Mercury	EPA 324/1631	BRL	10/4/06	< 25.0	No	No	
TotalHg-ST4-10/2/06	06BR1577-03	Northwest Area (street-level)	10/2/06	0.54	Mercury	EPA 324/1631	BRL	10/4/06	< 28.0	No	No	
TotalHg-ST5-10/2/06	06BR1577-04	Firehouse #10 (roof level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST10-10/2/06	06BR1577-05	North Side Sidewalk Bridge	10/2/06	0.55	Mercury	EPA 324/1631	BRL	10/4/06	< 27.0	No	No	
TotalHg-ST11-10/2/06	06BR1577-06	90 Trinity Place (roof level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST12-10/2/06	06BR1577-07	110 Greenwich Street (roof level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST13-10/2/06	06BR1577-08	Marriott Hotel, 38th Floor (roof level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST14-10/2/06	06BR1577-09	West Face - South end at corner (scaffolding level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST15-10/2/06	06BR1577-10	South Face - East end at corner (scaffolding level)	10/2/06	0.56	Mercury	EPA 324/1631	BRL	10/4/06	< 27.0	No	No	
TotalHg-ST16-10/2/06	06BR1577-11	East Face - North end at corner (scaffolding level)	10/2/06	0.58	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST17-10/2/06	06BR1577-12	North Face - West end at corner (scaffolding level)	10/2/06	0.57	Mercury	EPA 324/1631	BRL	10/4/06	< 26.0	No	No	
TotalHg-ST1-10/3/06	06BR1593-01	Southwest Area (sidewalk bridge level)	10/3/06	0.54	Mercury	EPA 324/1631	BRL	10/5/06	< 28.0	No	No	
TotalHg-ST2-10/3/06	06BR1593-02	Southeast Area (sidewalk bridge level)	10/3/06	0.60	Mercury	EPA 324/1631	BRL	10/5/06	< 25.0	No	No	
TotalHg-ST4-10/3/06	06BR1593-03	Northwest Area (street-level)	10/3/06	0.57	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST5-10/3/06	06BR1593-04	Firehouse #10 (roof level)	10/3/06	0.57	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST10-10/3/06	06BR1593-05	North Side Sidewalk Bridge	10/3/06	0.57	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST11-10/3/06	06BR1593-06	90 Trinity Place (roof level)	10/3/06	0.57	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST12-10/3/06	06BR1593-07	110 Greenwich Street (roof level)	10/3/06	0.59	Mercury	EPA 324/1631	BRL	10/5/06	< 25.0	No	No	
TotalHg-ST13-10/3/06	06BR1593-08	Marriott Hotel, 38th Floor (roof level)	10/3/06	0.61	Mercury	EPA 324/1631	BRL	10/5/06	< 25.0	No	No	
TotalHg-ST14-10/3/06	06BR1593-09	West Face - South end at corner (scaffolding level)	10/3/06	0.60	Mercury	EPA 324/1631	BRL	10/5/06	< 25.0	No	No	
TotalHg-ST15-10/3/06	06BR1593-10	South Face - East end at corner (scaffolding level)	10/3/06	0.58	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST16-10/3/06	06BR1593-11	East Face - North end at corner (scaffolding level)	10/3/06	0.57	Mercury	EPA 324/1631	BRL	10/5/06	< 26.0	No	No	
TotalHg-ST17-10/3/06	06BR1593-12	North Face - West end at corner (scaffolding level)	10/3/06	0.59	Mercury	EPA 324/1631	BRL	10/5/06	< 25.0	No	No	