

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300				
									EPA Site Specific Trigger Levels				
									3,000				
TotalHg-ST1-10/14/09	0942031-01	Southwest Area (sidewalk bridge level)	10/14/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 25.4		No	No	
TotalHg-ST2-10/14/09	0942031-02	Southeast Area (sidewalk bridge level)	10/14/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 26.3		No	No	
TotalHg-ST4-10/14/09	0942031-03	Northwest Area (street-level)	10/14/09	0.58	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 25.9		No	No	
TotalHg-ST5-10/14/09	0942031-04	Firehouse #10 (roof level)	10/14/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 26.8		No	No	
TotalHg-ST10-10/14/09	0942031-05	North Side Sidewalk Bridge	10/14/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 26.3		No	No	
TotalHg-ST11-10/14/09	0942031-06	90 Trinity Place (roof level)	10/14/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 26.3		No	No	
TotalHg-ST12-10/14/09	0942031-07	110 Greenwich Street (roof level)	10/14/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 27.8		No	No	
TotalHg-ST13-10/14/09	0942031-08	Marriott Hotel, 38th Floor (roof level)	10/14/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/16/09	< 26.3		No	No	
TotalHg-ST1-10/15/09	0942043-01	Southwest Area (sidewalk bridge level)	10/15/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 27.8		No	No	
TotalHg-ST2-10/15/09	0942043-02	Southeast Area (sidewalk bridge level)	10/15/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 26.8		No	No	
TotalHg-ST4-10/15/09	0942043-03	Northwest Area (street-level)	10/15/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 25.4		No	No	
TotalHg-ST5-10/15/09	0942043-04	Firehouse #10 (roof level)	10/15/09	0.54	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 27.8		No	No	
TotalHg-ST10-10/15/09	0942043-05	North Side Sidewalk Bridge	10/15/09	0.53	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 28.3		No	No	
TotalHg-ST11-10/15/09	0942043-06	90 Trinity Place (roof level)	10/15/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 26.3		No	No	
TotalHg-ST12-10/15/09	0942043-07	110 Greenwich Street (roof level)	10/15/09	0.58	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 25.9		No	No	
TotalHg-ST13-10/15/09	0942043-08	Marriott Hotel, 38th Floor (roof level)	10/15/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/17/09	< 26.8		No	No	
TotalHg-ST1-10/16/09	0943001-01	Southwest Area (sidewalk bridge level)	10/16/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 26.8		No	No	
TotalHg-ST2-10/16/09	0943001-02	Southeast Area (sidewalk bridge level)	10/16/09	0.53	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 28.3		No	No	
TotalHg-ST4-10/16/09	0943001-03	Northwest Area (street-level)	10/16/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 25.4		No	No	
TotalHg-ST5-10/16/09	0943001-04	Firehouse #10 (roof level)	10/16/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 26.3		No	No	
TotalHg-ST10-10/16/09	0943001-05	North Side Sidewalk Bridge	10/16/09	0.59	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 25.4		No	No	
TotalHg-ST11-10/16/09	0943001-06	90 Trinity Place (roof level)	10/16/09	0.56	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 26.8		No	No	
TotalHg-ST12-10/16/09	0943001-07	110 Greenwich Street (roof level)	10/16/09	0.57	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 26.3		No	No	
TotalHg-ST13-10/16/09	0943001-08	Marriott Hotel, 38th Floor (roof level)	10/16/09	0.58	Mercury	EPA 324/1631 Auto	BRL	10/19/09	< 25.9		No	No	