

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-10/19/07	0743003-01	Southwest Area (sidewalk bridge level)	10/19/07	0.55	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST2-10/19/07	0743003-02	Southeast Area (sidewalk bridge level)	10/19/07	0.52	Mercury	EPA 324/1631	BRL	10/23/07	< 29.0	No	No	
TotalHg-ST4-10/19/07	0743003-03	Northwest Area (street-level)	10/19/07	0.57	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST5-10/19/07	0743003-04	Firehouse #10 (roof level)	10/19/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST10-10/19/07	0743003-05	North Side Sidewalk Bridge	10/19/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST11-10/19/07	0743003-06	90 Trinity Place (roof level)	10/19/07	0.57	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST12-10/19/07	0743003-07	110 Greenwich Street (roof level)	10/19/07	0.57	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST13-10/19/07	0743003-08	Marriott Hotel, 38th Floor (roof level)	10/19/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST14-10/19/07	0743003-09	West Face - South end at corner (scaffolding level)	10/19/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST15-10/19/07	0743003-10	South Face - East end at corner (scaffolding level)	10/19/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST16-10/19/07	0743003-11	East Face - North end at corner (scaffolding level)	10/19/07	0.51	Mercury	EPA 324/1631	BRL	10/23/07	< 29.0	No	No	
TotalHg-ST17-10/19/07	0743003-12	North Face - West end at corner (scaffolding level)	10/19/07	0.53	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST1-10/20/07	0743004-01	Southwest Area (sidewalk bridge level)	10/20/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST2-10/20/07	0743004-02	Southeast Area (sidewalk bridge level)	10/20/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST4-10/20/07	0743004-03	Northwest Area (street-level)	10/20/07	0.63	Mercury	EPA 324/1631	BRL	10/23/07	< 24.0	No	No	
TotalHg-ST5-10/20/07	0743004-04	Firehouse #10 (roof level)	10/20/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST10-10/20/07	0743004-05	North Side Sidewalk Bridge	10/20/07	0.58	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST11-10/20/07	0743004-06	90 Trinity Place (roof level)	10/20/07	0.57	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST12-10/20/07	0743004-07	110 Greenwich Street (roof level)	10/20/07	0.59	Mercury	EPA 324/1631	BRL	10/23/07	< 25.0	No	No	
TotalHg-ST13-10/20/07	0743004-08	Marriott Hotel, 38th Floor (roof level)	10/20/07	0.58	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST14-10/20/07	0743004-09	West Face - South end at corner (scaffolding level)	10/20/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST15-10/20/07	0743004-10	South Face - East end at corner (scaffolding level)	10/20/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST16-10/20/07	0743004-11	East Face - North end at corner (scaffolding level)	10/20/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST17-10/20/07	0743004-12	North Face - West end at corner (scaffolding level)	10/20/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST1-10/21/07	0743005-01	Southwest Area (sidewalk bridge level)	10/21/07	0.56	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST2-10/21/07	0743005-02	Southeast Area (sidewalk bridge level)	10/21/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST4-10/21/07	0743005-03	Northwest Area (street-level)	10/21/07	0.58	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST5-10/21/07	0743005-04	Firehouse #10 (roof level)	10/21/07	0.55	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST10-10/21/07	0743005-05	North Side Sidewalk Bridge	10/21/07	0.55	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST11-10/21/07	0743005-06	90 Trinity Place (roof level)	10/21/07	0.54	Mercury	EPA 324/1631	BRL	10/23/07	< 28.0	No	No	
TotalHg-ST12-10/21/07	0743005-07	110 Greenwich Street (roof level)	10/21/07	0.55	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST13-10/21/07	0743005-08	Marriott Hotel, 38th Floor (roof level)	10/21/07	0.55	Mercury	EPA 324/1631	BRL	10/23/07	< 27.0	No	No	
TotalHg-ST14-10/21/07	0743005-09	West Face - South end at corner (scaffolding level)	10/21/07	0.59	Mercury	EPA 324/1631	BRL	10/23/07	< 25.0	No	No	
TotalHg-ST15-10/21/07	0743005-10	South Face - East end at corner (scaffolding level)	10/21/07	0.58	Mercury	EPA 324/1631	BRL	10/23/07	< 26.0	No	No	
TotalHg-ST16-10/21/07	0743005-11	East Face - North end at corner (scaffolding level)	10/21/07	0.59	Mercury	EPA 324/1631	BRL	10/23/07	< 25.0	No	No	
TotalHg-ST17-10/21/07	0743005-12	North Face - West end at corner (scaffolding level)	10/21/07	0.62	Mercury	EPA 324/1631	BRL	10/23/07	< 24.0	No	No	