

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-10/27/08	0844018-01	Southwest Area (sidewalk bridge level)	10/27/08	0.56	Mercury	EPA 324/1631	BRL	10/29/08	< 27.0	No	No	
TotalHg-ST2-10/27/08	0844018-02	Southeast Area (sidewalk bridge level)	10/27/08	0.56	Mercury	EPA 324/1631	BRL	10/29/08	< 27.0	No	No	
TotalHg-ST4-10/27/08	0844018-03	Northwest Area (street-level)	10/27/08	0.54	Mercury	EPA 324/1631	BRL	10/29/08	< 28.0	No	No	
TotalHg-ST5-10/27/08	0844018-04	Firehouse #10 (roof level)	10/27/08	0.59	Mercury	EPA 324/1631	BRL	10/29/08	< 25.0	No	No	
TotalHg-ST10-10/27/08	0844018-05	North Side Sidewalk Bridge	10/27/08	0.56	Mercury	EPA 324/1631	BRL	10/29/08	< 27.0	No	No	
TotalHg-ST100-10/27/08 FD	0844018-13	Station 10 Field Duplicate	10/27/08	0.54	Mercury	EPA 324/1631	BRL	10/29/08	< 28.0	No	No	
TotalHg-ST11-10/27/08	0844018-06	90 Trinity Place (roof level)	10/27/08	0.54	Mercury	EPA 324/1631	BRL	10/29/08	< 28.0	No	No	
TotalHg-ST12-10/27/08	0844018-07	110 Greenwich Street (roof level)	10/27/08	0.55	Mercury	EPA 324/1631	BRL	10/29/08	< 27.0	No	No	
TotalHg-ST13-10/27/08	0844018-08	Marriott Hotel, 38th Floor (roof level)	10/27/08	0.55	Mercury	EPA 324/1631	BRL	10/29/08	< 27.0	No	No	
TotalHg-ST14-10/27/08	0844018-09	West Face - South end at corner (scaffolding level)	10/27/08	0.58	Mercury	EPA 324/1631	BRL	10/29/08	< 26.0	No	No	
TotalHg-ST15-10/27/08	0844018-10	South Face - East end at corner (scaffolding level)	10/27/08	0.64	Mercury	EPA 324/1631	BRL	10/29/08	< 23.0	No	No	
TotalHg-ST16-10/27/08	0844018-11	East Face - North end at corner (scaffolding level)	10/27/08	0.61	Mercury	EPA 324/1631	BRL	10/29/08	< 25.0	No	No	
TotalHg-ST17-10/27/08	0844018-12	North Face - West end at corner (scaffolding level)	10/27/08	0.59	Mercury	EPA 324/1631	BRL	10/29/08	< 25.0	No	No	
TotalHg-ST1-10/28/08	0844026-01	Southwest Area (sidewalk bridge level)	10/28/08	0.57	Mercury	EPA 324/1631	BRL	10/30/08	< 26.0	No	No	
TotalHg-ST2-10/28/08	0844026-02	Southeast Area (sidewalk bridge level)	10/28/08	0.62	Mercury	EPA 324/1631	BRL	10/30/08	< 24.0	No	No	
TotalHg-ST4-10/28/08	0844026-03	Northwest Area (street-level)	10/28/08	0.60	Mercury	EPA 324/1631	BRL	10/30/08	< 25.0	No	No	
TotalHg-ST5-10/28/08	0844026-04	Firehouse #10 (roof level)	10/28/08	0.59	Mercury	EPA 324/1631	BRL	10/30/08	< 25.0	No	No	
TotalHg-ST10-10/28/08	0844026-05	North Side Sidewalk Bridge	10/28/08	0.54	Mercury	EPA 324/1631	BRL	10/30/08	< 28.0	No	No	
TotalHg-ST11-10/28/08	0844026-06	90 Trinity Place (roof level)	10/28/08	0.57	Mercury	EPA 324/1631	BRL	10/30/08	< 26.0	No	No	
TotalHg-ST12-10/28/08	0844026-07	110 Greenwich Street (roof level)	10/28/08	0.57	Mercury	EPA 324/1631	BRL	10/30/08	< 26.0	No	No	
TotalHg-ST13-10/28/08	0844026-08	Marriott Hotel, 38th Floor (roof level)	10/28/08	0.56	Mercury	EPA 324/1631	BRL	10/30/08	< 27.0	No	No	
TotalHg-ST14-10/28/08	0844026-09	West Face - South end at corner (scaffolding level)	10/28/08	0.55	Mercury	EPA 324/1631	BRL	10/30/08	< 27.0	No	No	
TotalHg-ST15-10/28/08	0844026-10	South Face - East end at corner (scaffolding level)	10/28/08	0.50	Mercury	EPA 324/1631	BRL	10/30/08	< 30.0	No	No	
TotalHg-ST16-10/28/08	0844026-11	East Face - North end at corner (scaffolding level)	10/28/08	0.49	Mercury	EPA 324/1631	BRL	10/30/08	< 31.0	No	No	
TotalHg-ST17-10/28/08	0844026-12	North Face - West end at corner (scaffolding level)	10/28/08	0.49	Mercury	EPA 324/1631	BRL	10/30/08	< 31.0	No	No	