

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-10/31/07	0744015-01	Southwest Area (sidewalk bridge level)	10/31/07	0.56	Mercury	EPA 324/1631	BRL	11/2/07	< 27.0	No	No	
TotalHg-ST2-10/31/07	0744015-02	Southeast Area (sidewalk bridge level)	10/31/07	0.55	Mercury	EPA 324/1631	BRL	11/2/07	< 27.0	No	No	
TotalHg-ST4-10/31/07	0744015-03	Northwest Area (street-level)	10/31/07	0.59	Mercury	EPA 324/1631	BRL	11/2/07	< 25.0	No	No	
TotalHg-ST5-10/31/07	0744015-04	Firehouse #10 (roof level)	10/31/07	0.55	Mercury	EPA 324/1631	BRL	11/2/07	< 27.0	No	No	
TotalHg-ST10-10/31/07	0744015-05	North Side Sidewalk Bridge	10/31/07	0.58	Mercury	EPA 324/1631	BRL	11/2/07	< 26.0	No	No	
TotalHg-ST11-10/31/07	0744015-06	90 Trinity Place (roof level)	10/31/07	0.57	Mercury	EPA 324/1631	BRL	11/2/07	< 26.0	No	No	
TotalHg-ST12-10/31/07	0744015-07	110 Greenwich Street (roof level)	10/31/07	0.58	Mercury	EPA 324/1631	BRL	11/2/07	< 26.0	No	No	
TotalHg-ST13-10/31/07	0744015-08	Marriott Hotel, 38th Floor (roof level)	10/31/07	0.58	Mercury	EPA 324/1631	BRL	11/2/07	< 26.0	No	No	
TotalHg-ST14-10/31/07	0744015-09	West Face - South end at corner (scaffolding level)	10/31/07	0.56	Mercury	EPA 324/1631	BRL	11/2/07	< 27.0	No	No	
TotalHg-ST15-10/31/07	0744015-10	South Face - East end at corner (scaffolding level)	10/31/07	0.57	Mercury	EPA 324/1631	BRL	11/2/07	< 26.0	No	No	
TotalHg-ST16-10/31/07	0744015-11	East Face - North end at corner (scaffolding level)	10/31/07	0.56	Mercury	EPA 324/1631	BRL	11/2/07	< 27.0	No	No	
TotalHg-ST17-10/31/07	0744015-12	North Face - West end at corner (scaffolding level)	10/31/07	0.54	Mercury	EPA 324/1631	BRL	11/2/07	< 28.0	No	No	
TotalHg-ST1-11/01/07	0745002-01	Southwest Area (sidewalk bridge level)	11/1/07	0.56	Mercury	EPA 324/1631	BRL	11/3/07	< 27.0	No	No	
TotalHg-ST2-11/01/07	0745002-02	Southeast Area (sidewalk bridge level)	11/1/07	0.54	Mercury	EPA 324/1631	BRL	11/3/07	< 28.0	No	No	
TotalHg-ST4-11/01/07	0745002-03	Northwest Area (street-level)	11/1/07	0.58	Mercury	EPA 324/1631	BRL	11/3/07	< 26.0	No	No	
TotalHg-ST5-11/01/07	0745002-04	Firehouse #10 (roof level)	11/1/07	0.58	Mercury	EPA 324/1631	BRL	11/3/07	< 26.0	No	No	
TotalHg-ST10-11/01/07	0745002-05	North Side Sidewalk Bridge	11/1/07	0.58	Mercury	EPA 324/1631	BRL	11/3/07	< 26.0	No	No	
TotalHg-ST11-11/01/07	0745002-06	90 Trinity Place (roof level)	11/1/07	0.55	Mercury	EPA 324/1631	BRL	11/3/07	< 27.0	No	No	
TotalHg-ST12-11/01/07	0745002-07	110 Greenwich Street (roof level)	11/1/07	0.55	Mercury	EPA 324/1631	BRL	11/3/07	< 27.0	No	No	
TotalHg-ST13-11/01/07	0745002-08	Marriott Hotel, 38th Floor (roof level)	11/1/07	0.55	Mercury	EPA 324/1631	BRL	11/3/07	< 27.0	No	No	
TotalHg-ST14-11/01/07	0745002-09	West Face - South end at corner (scaffolding level)	11/1/07	0.53	Mercury	EPA 324/1631	BRL	11/3/07	< 28.0	No	No	
TotalHg-ST15-11/01/07	0745002-10	South Face - East end at corner (scaffolding level)	11/1/07	0.58	Mercury	EPA 324/1631	BRL	11/3/07	< 26.0	No	No	
TotalHg-ST16-11/01/07	0745002-11	East Face - North end at corner (scaffolding level)	11/1/07	0.56	Mercury	EPA 324/1631	BRL	11/3/07	< 27.0	No	No	
TotalHg-ST17-11/01/07	0745002-12	North Face - West end at corner (scaffolding level)	11/1/07	0.53	Mercury	EPA 324/1631	BRL	11/3/07	< 28.0	No	No	