

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-11/1/08	0845004-01	Southwest Area (sidewalk bridge level)	11/1/08	0.60	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST2-11/1/08	0845004-02	Southeast Area (sidewalk bridge level)	11/1/08	0.59	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST4-11/1/08	0845004-03	Northwest Area (street-level)	11/1/08	0.59	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST5-11/1/08	0845004-04	Firehouse #10 (roof level)	11/1/08	0.61	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST10-11/1/08	0845004-05	North Side Sidewalk Bridge	11/1/08	0.58	Mercury	EPA 324/1631	BRL	11/4/08	< 26.0	No	No	
TotalHg-ST11-11/1/08	0845004-06	90 Trinity Place (roof level)	11/1/08	0.58	Mercury	EPA 324/1631	BRL	11/4/08	< 26.0	No	No	
TotalHg-ST12-11/1/08	0845004-07	110 Greenwich Street (roof level)	11/1/08	0.56	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST13-11/1/08	0845004-08	Marriott Hotel, 38th Floor (roof level)	11/1/08	0.57	Mercury	EPA 324/1631	BRL	11/4/08	< 26.0	No	No	
TotalHg-ST14-11/1/08	0845004-09	West Face - South end at corner (scaffolding level)	11/1/08	0.61	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST15-11/1/08	0845004-10	South Face - East end at corner (scaffolding level)	11/1/08	0.56	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST16-11/1/08	0845004-11	East Face - North end at corner (scaffolding level)	11/1/08	0.55	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST17-11/1/08	0845004-12	North Face - West end at corner (scaffolding level)	11/1/08	0.60	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST1-11/2/08	0845005-01	Southwest Area (sidewalk bridge level)	11/2/08	0.56	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST2-11/2/08	0845005-02	Southeast Area (sidewalk bridge level)	11/2/08	0.60	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST4-11/2/08	0845005-03	Northwest Area (street-level)	11/2/08	0.54	Mercury	EPA 324/1631	BRL	11/4/08	< 28.0	No	No	
TotalHg-ST5-11/2/08	0845005-04	Firehouse #10 (roof level)	11/2/08	0.55	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST10-11/2/08	0845005-05	North Side Sidewalk Bridge	11/2/08	0.56	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	
TotalHg-ST11-11/2/08	0845005-06	90 Trinity Place (roof level)	11/2/08	0.59	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST12-11/2/08	0845005-07	110 Greenwich Street (roof level)	11/2/08	0.57	Mercury	EPA 324/1631	BRL	11/4/08	< 26.0	No	No	
TotalHg-ST13-11/2/08	0845005-08	Marriott Hotel, 38th Floor (roof level)	11/2/08	0.52	Mercury	EPA 324/1631	BRL	11/4/08	< 29.0	No	No	
TotalHg-ST14-11/2/08	0845005-09	West Face - South end at corner (scaffolding level)	11/2/08	0.58	Mercury	EPA 324/1631	BRL	11/4/08	< 26.0	No	No	
TotalHg-ST15-11/2/08	0845005-10	South Face - East end at corner (scaffolding level)	11/2/08	0.60	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST16-11/2/08	0845005-11	East Face - North end at corner (scaffolding level)	11/2/08	0.61	Mercury	EPA 324/1631	BRL	11/4/08	< 25.0	No	No	
TotalHg-ST17-11/2/08	0845005-12	North Face - West end at corner (scaffolding level)	11/2/08	0.56	Mercury	EPA 324/1631	BRL	11/4/08	< 27.0	No	No	