

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-11/3/08	0845024-01	Southwest Area (sidewalk bridge level)	11/3/08	0.53	Mercury	EPA 324/1631	BRL	11/6/08	< 28.0	No	No	
TotalHg-ST2-11/3/08	0845024-02	Southeast Area (sidewalk bridge level)	11/3/08	0.58	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST4-11/3/08	0845024-03	Northwest Area (street-level)	11/3/08	0.63	Mercury	EPA 324/1631	BRL	11/6/08	< 24.0	No	No	
TotalHg-ST5-11/3/08	0845024-04	Firehouse #10 (roof level)	11/3/08	0.57	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST10-11/3/08	0845024-05	North Side Sidewalk Bridge	11/3/08	0.56	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST11-11/3/08	0845024-06	90 Trinity Place (roof level)	11/3/08	0.56	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST12-11/3/08	0845024-07	110 Greenwich Street (roof level)	11/3/08	0.59	Mercury	EPA 324/1631	BRL	11/6/08	< 25.0	No	No	
TotalHg-ST13-11/3/08	0845024-08	Marriott Hotel, 38th Floor (roof level)	11/3/08	0.59	Mercury	EPA 324/1631	BRL	11/6/08	< 25.0	No	No	
TotalHg-ST14-11/3/08	0845024-09	West Face - South end at corner (scaffolding level)	11/3/08	0.61	Mercury	EPA 324/1631	BRL	11/6/08	< 25.0	No	No	
TotalHg-ST15-11/3/08	0845024-10	South Face - East end at corner (scaffolding level)	11/3/08	0.55	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST16-11/3/08	0845024-11	East Face - North end at corner (scaffolding level)	11/3/08	0.60	Mercury	EPA 324/1631	BRL	11/6/08	< 25.0	No	No	
TotalHg-ST17-11/3/08	0845024-12	North Face - West end at corner (scaffolding level)	11/3/08	0.57	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST1-11/4/08	0845025-01	Southwest Area (sidewalk bridge level)	11/4/08	0.54	Mercury	EPA 324/1631	BRL	11/6/08	< 28.0	No	No	
TotalHg-ST2-11/4/08	0845025-02	Southeast Area (sidewalk bridge level)	11/4/08	0.58	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST4-11/4/08	0845025-03	Northwest Area (street-level)	11/4/08	0.54	Mercury	EPA 324/1631	BRL	11/6/08	< 28.0	No	No	
TotalHg-ST5-11/4/08	0845025-04	Firehouse #10 (roof level)	11/4/08	0.58	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST10-11/4/08	0845025-05	North Side Sidewalk Bridge	11/4/08	0.59	Mercury	EPA 324/1631	BRL	11/6/08	< 25.0	No	No	
TotalHg-ST11-11/4/08	0845025-06	90 Trinity Place (roof level)	11/4/08	0.55	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST12-11/4/08	0845025-07	110 Greenwich Street (roof level)	11/4/08	0.57	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST13-11/4/08	0845025-08	Marriott Hotel, 38th Floor (roof level)	11/4/08	0.56	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST14-11/4/08	0845025-09	West Face - South end at corner (scaffolding level)	11/4/08	0.57	Mercury	EPA 324/1631	BRL	11/6/08	< 26.0	No	No	
TotalHg-ST15-11/4/08	0845025-10	South Face - East end at corner (scaffolding level)	11/4/08	0.54	Mercury	EPA 324/1631	BRL	11/6/08	< 28.0	No	No	
TotalHg-ST16-11/4/08	0845025-11	East Face - North end at corner (scaffolding level)	11/4/08	0.55	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST17-11/4/08	0845025-12	North Face - West end at corner (scaffolding level)	11/4/08	0.55	Mercury	EPA 324/1631	BRL	11/6/08	< 27.0	No	No	
TotalHg-ST1-11/5/08	0845035-01	Southwest Area (sidewalk bridge level)	11/5/08	0.55	Mercury	EPA 324/1631	BRL	11/7/08	< 27.0	No	No	
TotalHg-ST2-11/5/08	0845035-02	Southeast Area (sidewalk bridge level)	11/5/08	0.60	Mercury	EPA 324/1631	BRL	11/7/08	< 25.0	No	No	
TotalHg-ST4-11/5/08	0845035-03	Northwest Area (street-level)	11/5/08	0.60	Mercury	EPA 324/1631	BRL	11/7/08	< 25.0	No	No	
TotalHg-ST5-11/5/08	0845035-04	Firehouse #10 (roof level)	11/5/08	0.58	Mercury	EPA 324/1631	BRL	11/7/08	< 26.0	No	No	
TotalHg-ST10-11/5/08	0845035-05	North Side Sidewalk Bridge	11/5/08	0.58	Mercury	EPA 324/1631	BRL	11/7/08	< 26.0	No	No	
TotalHg-ST11-11/5/08	0845035-06	90 Trinity Place (roof level)	11/5/08	0.57	Mercury	EPA 324/1631	BRL	11/7/08	< 26.0	No	No	
TotalHg-ST12-11/5/08	0845035-07	110 Greenwich Street (roof level)	11/5/08	0.54	Mercury	EPA 324/1631	BRL	11/7/08	< 28.0	No	No	
TotalHg-ST13-11/5/08	0845035-08	Marriott Hotel, 38th Floor (roof level)	11/5/08	0.55	Mercury	EPA 324/1631	BRL	11/7/08	< 27.0	No	No	
TotalHg-ST14-11/5/08	0845035-09	West Face - South end at corner (scaffolding level)	11/5/08	0.56	Mercury	EPA 324/1631	BRL	11/7/08	< 27.0	No	No	
TotalHg-ST15-11/5/08	0845035-10	South Face - East end at corner (scaffolding level)	11/5/08	0.54	Mercury	EPA 324/1631	BRL	11/7/08	< 28.0	No	No	
TotalHg-ST16-11/5/08	0845035-11	East Face - North end at corner (scaffolding level)	11/5/08	0.56	Mercury	EPA 324/1631	BRL	11/7/08	< 27.0	No	No	
TotalHg-ST17-11/5/08	0845035-12	North Face - West end at corner (scaffolding level)	11/5/08	0.57	Mercury	EPA 324/1631	BRL	11/7/08	< 26.0	No	No	