

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-11/12/08	0846044-01	Southwest Area (sidewalk bridge level)	11/12/08	0.54	Mercury	EPA 324/1631	BRL	11/14/08	< 28.0	No	No	
TotalHg-ST2-11/12/08	0846044-02	Southeast Area (sidewalk bridge level)	11/12/08	0.60	Mercury	EPA 324/1631	BRL	11/14/08	< 25.0	No	No	
TotalHg-ST4-11/12/08	0846044-03	Northwest Area (street-level)	11/12/08	0.52	Mercury	EPA 324/1631	BRL	11/14/08	< 29.0	No	No	
TotalHg-ST5-11/12/08	0846044-04	Firehouse #10 (roof level)	11/12/08	0.59	Mercury	EPA 324/1631	BRL	11/14/08	< 25.0	No	No	
TotalHg-ST10-11/12/08	0846044-05	North Side Sidewalk Bridge	11/12/08	0.57	Mercury	EPA 324/1631	BRL	11/14/08	< 26.0	No	No	
TotalHg-ST100-11/12/08 FD	0846044-13	Station 10 Field Duplicate	11/12/08	0.56	Mercury	EPA 324/1631	BRL	11/14/08	< 27.0	No	No	
TotalHg-ST11-11/12/08	0846044-06	90 Trinity Place (roof level)	11/12/08	0.55	Mercury	EPA 324/1631	BRL	11/14/08	< 27.0	No	No	
TotalHg-ST12-11/12/08	0846044-07	110 Greenwich Street (roof level)	11/12/08	0.56	Mercury	EPA 324/1631	BRL	11/14/08	< 27.0	No	No	
TotalHg-ST13-11/12/08	0846044-08	Marriott Hotel, 38th Floor (roof level)	11/12/08	0.56	Mercury	EPA 324/1631	BRL	11/14/08	< 27.0	No	No	
TotalHg-ST14-11/12/08	0846044-09	West Face - South end at corner (scaffolding level)	11/12/08	0.62	Mercury	EPA 324/1631	BRL	11/14/08	< 24.0	No	No	
TotalHg-ST15-11/12/08	0846044-10	South Face - East end at corner (scaffolding level)	11/12/08	0.53	Mercury	EPA 324/1631	BRL	11/14/08	< 28.0	No	No	
TotalHg-ST16-11/12/08	0846044-11	East Face - North end at corner (scaffolding level)	11/12/08	0.54	Mercury	EPA 324/1631	BRL	11/14/08	< 28.0	No	No	
TotalHg-ST17-11/12/08	0846044-12	North Face - West end at corner (scaffolding level)	11/12/08	0.54	Mercury	EPA 324/1631	BRL	11/14/08	< 28.0	No	No	
TotalHg-ST1-11/13/08	0846056-01	Southwest Area (sidewalk bridge level)	11/13/08	0.65	Mercury	EPA 324/1631	BRL	11/15/08	< 23.0	No	No	
TotalHg-ST2-11/13/08	0846056-02	Southeast Area (sidewalk bridge level)	11/13/08	0.52	Mercury	EPA 324/1631	BRL	11/15/08	< 29.0	No	No	
TotalHg-ST4-11/13/08	0846056-03	Northwest Area (street-level)	11/13/08	0.64	Mercury	EPA 324/1631	BRL	11/15/08	< 23.0	No	No	
TotalHg-ST5-11/13/08	0846056-04	Firehouse #10 (roof level)	11/13/08	0.59	Mercury	EPA 324/1631	BRL	11/15/08	< 25.0	No	No	
TotalHg-ST10-11/13/08	0846056-05	North Side Sidewalk Bridge	11/13/08	0.57	Mercury	EPA 324/1631	BRL	11/15/08	< 26.0	No	No	
TotalHg-ST11-11/13/08	0846056-06	90 Trinity Place (roof level)	11/13/08	0.57	Mercury	EPA 324/1631	BRL	11/15/08	< 26.0	No	No	
TotalHg-ST12-11/13/08	0846056-07	110 Greenwich Street (roof level)	11/13/08	0.59	Mercury	EPA 324/1631	BRL	11/15/08	< 25.0	No	No	
TotalHg-ST13-11/13/08	0846056-08	Marriott Hotel, 38th Floor (roof level)	11/13/08	0.55	Mercury	EPA 324/1631	BRL	11/15/08	< 27.0	No	No	
TotalHg-ST14-11/13/08	0846056-09	West Face - South end at corner (scaffolding level)	11/13/08	0.56	Mercury	EPA 324/1631	BRL	11/15/08	< 27.0	No	No	
TotalHg-ST15-11/13/08	0846056-10	South Face - East end at corner (scaffolding level)	11/13/08	0.53	Mercury	EPA 324/1631	BRL	11/15/08	< 28.0	No	No	
TotalHg-ST16-11/13/08	0846056-11	East Face - North end at corner (scaffolding level)	11/13/08	0.55	Mercury	EPA 324/1631	BRL	11/15/08	< 27.0	No	No	
TotalHg-ST17-11/13/08	0846056-12	North Face - West end at corner (scaffolding level)	11/13/08	0.54	Mercury	EPA 324/1631	BRL	11/15/08	< 28.0	No	No	
TotalHg-ST1-11/14/08	0847001-01	Southwest Area (sidewalk bridge level)	11/14/08	0.59	Mercury	EPA 324/1631	BRL	11/17/08	< 25.0	No	No	
TotalHg-ST2-11/14/08	0847001-02	Southeast Area (sidewalk bridge level)	11/14/08	0.61	Mercury	EPA 324/1631	BRL	11/17/08	< 25.0	No	No	
TotalHg-ST4-11/14/08	0847001-03	Northwest Area (street-level)	11/14/08	0.57	Mercury	EPA 324/1631	BRL	11/17/08	< 26.0	No	No	
TotalHg-ST5-11/14/08	0847001-04	Firehouse #10 (roof level)	11/14/08	0.55	Mercury	EPA 324/1631	BRL	11/17/08	< 27.0	No	No	
TotalHg-ST10-11/14/08	0847001-05	North Side Sidewalk Bridge	11/14/08	0.58	Mercury	EPA 324/1631	BRL	11/17/08	< 26.0	No	No	
TotalHg-ST11-11/14/08	0847001-06	90 Trinity Place (roof level)	11/14/08	0.56	Mercury	EPA 324/1631	BRL	11/17/08	< 27.0	No	No	
TotalHg-ST12-11/14/08	0847001-07	110 Greenwich Street (roof level)	11/14/08	0.57	Mercury	EPA 324/1631	BRL	11/17/08	< 26.0	No	No	
TotalHg-ST13-11/14/08	0847001-08	Marriott Hotel, 38th Floor (roof level)	11/14/08	0.60	Mercury	EPA 324/1631	BRL	11/17/08	< 25.0	No	No	
TotalHg-ST14-11/14/08	0847001-09	West Face - South end at corner (scaffolding level)	11/14/08	0.56	Mercury	EPA 324/1631	BRL	11/17/08	< 27.0	No	No	
TotalHg-ST15-11/14/08	0847001-10	South Face - East end at corner (scaffolding level)	11/14/08	0.52	Mercury	EPA 324/1631	BRL	11/17/08	< 29.0	No	No	
TotalHg-ST16-11/14/08	0847001-11	East Face - North end at corner (scaffolding level)	11/14/08	0.53	Mercury	EPA 324/1631	BRL	11/17/08	< 28.0	No	No	
TotalHg-ST17-11/14/08	0847001-12	North Face - West end at corner (scaffolding level)	11/14/08	0.55	Mercury	EPA 324/1631	BRL	11/17/08	< 27.0	No	No	