

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments	
									300				
Target Air Quality Levels													
EPA Site Specific Trigger Levels									3,000				
TotalHg-ST1-11/18/05	05BR1761-1	Southwest Area (sidewalk bridge level)	11/18/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST2-11/18/05	05BR1761-2	Southeast Area (sidewalk bridge level)	11/18/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST4-11/18/05	05BR1761-3	Northwest Area (street-level)	11/18/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST5-11/18/05	05BR1761-4	Firehouse #10 (roof level)	11/18/05	0.53	Mercury	EPA 324/1631	BRL	11/22/05	< 28.0	No	No		
TotalHg-ST10-11/18/05	05BR1761-5	North Side Sidewalk Bridge	11/18/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST11-11/18/05	05BR1761-6	90 Trinity Place (roof level)	11/18/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST12-11/18/05	05BR1761-7	110 Greenwich Street (roof level)	11/18/05	0.54	Mercury	EPA 324/1631	BRL	11/22/05	< 28.0	No	No		
TotalHg-ST13-11/18/05	05BR1761-8	Marriott Hotel, 38th Floor (roof level)	11/18/05	0.55	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST14-11/18/05	05BR1761-9	West Face - South end at corner (scaffolding level)	11/18/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST15-11/18/05	05BR1761-10	South Face - East end at corner (scaffolding level)	11/18/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST16-11/18/05	05BR1761-11	East Face - North end at corner (scaffolding level)	11/18/05	0.60	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST17-11/18/05	05BR1761-12	North Face - West end at corner (scaffolding level)	11/18/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST1-11/19/05	05BR1762-1	Southwest Area (sidewalk bridge level)	11/19/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST2-11/19/05	05BR1762-2	Southeast Area (sidewalk bridge level)	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST4-11/19/05	05BR1762-3	Northwest Area (street-level)	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST5-11/19/05	05BR1762-4	Firehouse #10 (roof level)	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST10-11/19/05	05BR1762-5	North Side Sidewalk Bridge	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST11-11/19/05	05BR1762-6	90 Trinity Place (roof level)	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST12-11/19/05	05BR1762-7	110 Greenwich Street (roof level)	11/19/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST13-11/19/05	05BR1762-8	Marriott Hotel, 38th Floor (roof level)	11/19/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST14-11/19/05	05BR1762-9	West Face - South end at corner (scaffolding level)	11/19/05	0.58	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST15-11/19/05	05BR1762-10	South Face - East end at corner (scaffolding level)	11/19/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST16-11/19/05	05BR1762-11	East Face - North end at corner (scaffolding level)	11/19/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST17-11/19/05	05BR1762-12	North Face - West end at corner (scaffolding level)	11/19/05	0.59	Mercury	EPA 324/1631	BRL	11/22/05	< 25.0	No	No		
TotalHg-ST1-11/20/05	05BR1763-1	Southwest Area (sidewalk bridge level)	11/20/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No	Mercury sample at Station 12 on November 20, 2005 was not available for analysis on account of pump	
TotalHg-ST2-11/20/05	05BR1763-2	Southeast Area (sidewalk bridge level)	11/20/05	0.55	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST4-11/20/05	05BR1763-3	Northwest Area (street-level)	11/20/05	0.56	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST5-11/20/05	05BR1763-4	Firehouse #10 (roof level)	11/20/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST10-11/20/05	05BR1763-5	North Side Sidewalk Bridge	11/20/05	0.56	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST11-11/20/05	05BR1763-6	90 Trinity Place (roof level)	11/20/05	0.56	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST13-11/20/05	05BR1763-7	Marriott Hotel, 38th Floor (roof level)	11/20/05	0.57	Mercury	EPA 324/1631	BRL	11/22/05	< 26.0	No	No		
TotalHg-ST14-11/20/05	05BR1763-8	West Face - South end at corner (scaffolding level)	11/20/05	0.53	Mercury	EPA 324/1631	BRL	11/22/05	< 28.0	No	No		
TotalHg-ST15-11/20/05	05BR1763-9	South Face - East end at corner (scaffolding level)	11/20/05	0.56	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST16-11/20/05	05BR1763-10	East Face - North end at corner (scaffolding level)	11/20/05	0.55	Mercury	EPA 324/1631	BRL	11/22/05	< 27.0	No	No		
TotalHg-ST17-11/20/05	05BR1763-11	North Face - West end at corner (scaffolding level)	11/20/05	0.53	Mercury	EPA 324/1631	BRL	11/22/05	< 28.0	No	No		
TotalHg-ST1-11/21/05	05BR1769-1	Southwest Area (sidewalk bridge level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST2-11/21/05	05BR1769-2	Southeast Area (sidewalk bridge level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST4-11/21/05	05BR1769-3	Northwest Area (street-level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST5-11/21/05	05BR1769-4	Firehouse #10 (roof level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST10-11/21/05	05BR1769-5	North Side Sidewalk Bridge	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST11-11/21/05	05BR1769-6	90 Trinity Place (roof level)	11/21/05	0.57	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST12-11/21/05	05BR1769-7	110 Greenwich Street (roof level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST13-11/21/05	05BR1769-8	Marriott Hotel, 38th Floor (roof level)	11/21/05	0.57	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST14-11/21/05	05BR1769-9	West Face - South end at corner (scaffolding level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST15-11/21/05	05BR1769-10	South Face - East end at corner (scaffolding level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST16-11/21/05	05BR1769-11	East Face - North end at corner (scaffolding level)	11/21/05	0.58	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		
TotalHg-ST17-11/21/05	05BR1769-12	North Face - West end at corner (scaffolding level)	11/21/05	0.57	Mercury	EPA 324/1631	BRL	11/23/05	< 26.0	No	No		