

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels									3.000			
TotalHg-ST11-11/27/07	0748024-01	Southwest Area (sidewalk bridge level)	11/27/07	0.56	Mercury	EPA 324/1631	BRL	11/29/07	< 27.0	No	No	
TotalHg-ST12-11/27/07	0748024-02	Southeast Area (sidewalk bridge level)	11/27/07	0.56	Mercury	EPA 324/1631	BRL	11/29/07	< 27.0	No	No	
TotalHg-ST4-11/27/07	0748024-03	Northwest Area (street-level)	11/27/07	0.60	Mercury	EPA 324/1631	BRL	11/29/07	< 25.0	No	No	
TotalHg-ST5-11/27/07	0748024-04	Firehouse #10 (roof level)	11/27/07	0.54	Mercury	EPA 324/1631	BRL	11/29/07	< 28.0	No	No	
TotalHg-ST10-11/27/07	0748024-05	North Side Sidewalk Bridge	11/27/07	0.56	Mercury	EPA 324/1631	BRL	11/29/07	< 27.0	No	No	
TotalHg-ST11-11/27/07	0748024-06	90 Trinity Place (roof level)	11/27/07	0.57	Mercury	EPA 324/1631	BRL	11/29/07	< 26.0	No	No	
TotalHg-ST12-11/27/07	0748024-07	110 Greenwich Street (roof level)	11/27/07	0.57	Mercury	EPA 324/1631	BRL	11/29/07	< 26.0	No	No	
TotalHg-ST13-11/27/07	0748024-08	Marriott Hotel, 38th Floor (roof level)	11/27/07	0.58	Mercury	EPA 324/1631	BRL	11/29/07	< 26.0	No	No	
TotalHg-ST14-11/27/07	0748024-09	West Face - South end at corner (scaffolding level)	11/27/07	0.55	Mercury	EPA 324/1631	BRL	11/29/07	< 27.0	No	No	
TotalHg-ST15-11/27/07	0748024-10	South Face - East end at corner (scaffolding level)	11/27/07	0.58	Mercury	EPA 324/1631	BRL	11/29/07	< 26.0	No	No	
TotalHg-ST16-11/27/07	0748024-11	East Face - North end at corner (scaffolding level)	11/27/07	0.53	Mercury	EPA 324/1631	BRL	11/29/07	< 28.0	No	No	
TotalHg-ST17-11/27/07	0748024-12	North Face - West end at corner (scaffolding level)	11/27/07	0.59	Mercury	EPA 324/1631	BRL	11/29/07	< 25.0	No	No	
TotalHg-ST1-11/28/07	0748027-01	Southwest Area (sidewalk bridge level)	11/28/07	0.55	Mercury	EPA 324/1631	BRL	11/30/07	< 27.0	No	No	
TotalHg-ST2-11/28/07	0748027-02	Southeast Area (sidewalk bridge level)	11/28/07	0.54	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST4-11/28/07	0748027-03	Northwest Area (street-level)	11/28/07	0.52	Mercury	EPA 324/1631	BRL	11/30/07	< 29.0	No	No	
TotalHg-ST5-11/28/07	0748027-04	Firehouse #10 (roof level)	11/28/07	0.56	Mercury	EPA 324/1631	BRL	11/30/07	< 27.0	No	No	
TotalHg-ST10-11/28/07	0748027-05	North Side Sidewalk Bridge	11/28/07	0.55	Mercury	EPA 324/1631	BRL	11/30/07	< 27.0	No	No	
TotalHg-ST11-11/28/07	0748027-06	90 Trinity Place (roof level)	11/28/07	0.58	Mercury	EPA 324/1631	BRL	11/30/07	< 26.0	No	No	
TotalHg-ST12-11/28/07	0748027-07	110 Greenwich Street (roof level)	11/28/07	0.54	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST13-11/28/07	0748027-08	Marriott Hotel, 38th Floor (roof level)	11/28/07	0.53	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST14-11/28/07	0748027-09	West Face - South end at corner (scaffolding level)	11/28/07	0.53	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST15-11/28/07	0748027-10	South Face - East end at corner (scaffolding level)	11/28/07	0.54	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST16-11/28/07	0748027-11	East Face - North end at corner (scaffolding level)	11/28/07	0.58	Mercury	EPA 324/1631	BRL	11/30/07	< 26.0	No	No	
TotalHg-ST17-11/28/07	0748027-12	North Face - West end at corner (scaffolding level)	11/28/07	0.54	Mercury	EPA 324/1631	BRL	11/30/07	< 28.0	No	No	
TotalHg-ST1-11/29/07	0748033-01	Southwest Area (sidewalk bridge level)	11/29/07	0.57	Mercury	EPA 324/1631	BRL	12/1/07	< 26.0	No	No	
TotalHg-ST2-11/29/07	0748033-02	Southeast Area (sidewalk bridge level)	11/29/07	0.59	Mercury	EPA 324/1631	BRL	12/1/07	< 25.0	No	No	
TotalHg-ST4-11/29/07	0748033-03	Northwest Area (street-level)	11/29/07	0.57	Mercury	EPA 324/1631	BRL	12/1/07	< 26.0	No	No	
TotalHg-ST5-11/29/07	0748033-04	Firehouse #10 (roof level)	11/29/07	0.53	Mercury	EPA 324/1631	BRL	12/1/07	< 28.0	No	No	
TotalHg-ST10-11/29/07	0748033-05	North Side Sidewalk Bridge	11/29/07	0.58	Mercury	EPA 324/1631	BRL	12/1/07	< 26.0	No	No	
TotalHg-ST11-11/29/07	0748033-06	90 Trinity Place (roof level)	11/29/07	0.54	Mercury	EPA 324/1631	BRL	12/1/07	< 28.0	No	No	
TotalHg-ST12-11/29/07	0748033-07	110 Greenwich Street (roof level)	11/29/07	0.55	Mercury	EPA 324/1631	BRL	12/1/07	< 27.0	No	No	
TotalHg-ST13-11/29/07	0748033-08	Marriott Hotel, 38th Floor (roof level)	11/29/07	0.58	Mercury	EPA 324/1631	BRL	12/1/07	< 26.0	No	No	
TotalHg-ST14-11/29/07	0748033-09	West Face - South end at corner (scaffolding level)	11/29/07	0.49	Mercury	EPA 324/1631	BRL	12/1/07	< 31.0	No	No	Note 1
TotalHg-ST15-11/29/07	0748033-10	South Face - East end at corner (scaffolding level)	11/29/07	0.59	Mercury	EPA 324/1631	BRL	12/1/07	< 25.0	No	No	
TotalHg-ST16-11/29/07	0748033-11	East Face - North end at corner (scaffolding level)	11/29/07	0.60	Mercury	EPA 324/1631	BRL	12/1/07	< 25.0	No	No	
TotalHg-ST17-11/29/07	0748033-12	North Face - West end at corner (scaffolding level)	11/29/07	0.52	Mercury	EPA 324/1631	BRL	12/1/07	< 29.0	No	No	
TotalHg-ST1-11/30/07	0749001-01	Southwest Area (sidewalk bridge level)	11/30/07	0.58	Mercury	EPA 324/1631	BRL	12/3/07	< 26.0	No	No	
TotalHg-ST2-11/30/07	0749001-02	Southeast Area (sidewalk bridge level)	11/30/07	0.60	Mercury	EPA 324/1631	BRL	12/3/07	< 25.0	No	No	
TotalHg-ST4-11/30/07	0749001-03	Northwest Area (street-level)	11/30/07	0.55	Mercury	EPA 324/1631	BRL	12/3/07	< 27.0	No	No	
TotalHg-ST5-11/30/07	0749001-04	Firehouse #10 (roof level)	11/30/07	0.57	Mercury	EPA 324/1631	BRL	12/3/07	< 26.0	No	No	
TotalHg-ST10-11/30/07	0749001-05	North Side Sidewalk Bridge	11/30/07	0.58	Mercury	EPA 324/1631	BRL	12/3/07	< 26.0	No	No	
TotalHg-ST11-11/30/07	0749001-06	90 Trinity Place (roof level)	11/30/07	0.61	Mercury	EPA 324/1631	BRL	12/3/07	< 25.0	No	No	
TotalHg-ST12-11/30/07	0749001-07	110 Greenwich Street (roof level)	11/30/07	0.54	Mercury	EPA 324/1631	BRL	12/3/07	< 28.0	No	No	
TotalHg-ST13-11/30/07	0749001-08	Marriott Hotel, 38th Floor (roof level)	11/30/07	0.62	Mercury	EPA 324/1631	BRL	12/3/07	< 24.0	No	No	
TotalHg-ST14-11/30/07	0749001-09	West Face - South end at corner (scaffolding level)	11/30/07	0.54	Mercury	EPA 324/1631	BRL	12/3/07	< 28.0	No	No	
TotalHg-ST15-11/30/07	0749001-10	South Face - East end at corner (scaffolding level)	11/30/07	0.53	Mercury	EPA 324/1631	BRL	12/3/07	< 28.0	No	No	
TotalHg-ST16-11/30/07	0749001-11	East Face - North end at corner (scaffolding level)	11/30/07	0.55	Mercury	EPA 324/1631	BRL	12/3/07	< 27.0	No	No	
TotalHg-ST17-11/30/07	0749001-12	North Face - West end at corner (scaffolding level)	11/30/07	0.59	Mercury	EPA 324/1631	BRL	12/3/07	< 25.0	No	No	
TotalHg-ST1-12/1/07	0749003-01	90 Trinity Place (roof level)	12/1/07	0.60	Mercury	EPA 324/1631	BRL	12/4/07	< 25.0	No	No	
TotalHg-ST2-12/1/07	0749003-02	110 Greenwich Street (roof level)	12/1/07	0.57	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST4-12/1/07	0749003-03	Northwest Area (street-level)	12/1/07	0.53	Mercury	EPA 324/1631	BRL	12/4/07	< 28.0	No	No	
TotalHg-ST5-12/1/07	0749003-04	Firehouse #10 (roof level)	12/1/07	0.53	Mercury	EPA 324/1631	BRL	12/4/07	< 28.0	No	No	
TotalHg-ST10-12/1/07	0749003-05	North Side Sidewalk Bridge	12/1/07	0.61	Mercury	EPA 324/1631	BRL	12/4/07	< 25.0	No	No	
TotalHg-ST11-12/1/07	0749003-06	90 Trinity Place (roof level)	12/1/07	0.53	Mercury	EPA 324/1631	BRL	12/4/07	< 28.0	No	No	
TotalHg-ST12-12/1/07	0749003-07	110 Greenwich Street (roof level)	12/1/07	0.57	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST13-12/1/07	0749003-08	Marriott Hotel, 38th Floor (roof level)	12/1/07	0.58	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST14-12/1/07	0749003-09	West Face - South end at corner (scaffolding level)	12/1/07	1.11	Mercury	EPA 324/1631	BRL	12/4/07	< 14.0	No	No	Note 2
TotalHg-ST15-12/1/07	0749003-10	South Face - East end at corner (scaffolding level)	12/1/07	1.15	Mercury	EPA 324/1631	BRL	12/4/07	< 13.0	No	No	Note 2
TotalHg-ST16-12/1/07	0749003-11	East Face - North end at corner (scaffolding level)	12/1/07	1.13	Mercury	EPA 324/1631	BRL	12/4/07	< 13.0	No	No	Note 2
TotalHg-ST17-12/1/07	0749003-12	North Face - West end at corner (scaffolding level)	12/1/07	1.11	Mercury	EPA 324/1631	BRL	12/4/07	< 14.0	No	No	Note 2
TotalHg-ST1-12/2/07	0749004-01	Southwest Area (sidewalk bridge level)	12/2/07	0.54	Mercury	EPA 324/1631	BRL	12/4/07	< 28.0	No	No	
TotalHg-ST2-12/2/07	0749004-02	Southeast Area (sidewalk bridge level)	12/2/07	0.58	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST4-12/2/07	0749004-03	Northwest Area (street-level)	12/2/07	0.58	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST5-12/2/07	0749004-04	Firehouse #10 (roof level)	12/2/07	0.57	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST10-12/2/07	0749004-05	North Side Sidewalk Bridge	12/2/07	0.56	Mercury	EPA 324/1631	BRL	12/4/07	< 27.0	No	No	
TotalHg-ST11-12/2/07	0749004-06	90 Trinity Place (roof level)	12/2/07	0.55	Mercury	EPA 324/1631	BRL	12/4/07	< 27.0	No	No	
TotalHg-ST12-12/2/07	0749004-07	110 Greenwich Street (roof level)	12/2/07	0.56	Mercury	EPA 324/1631	BRL	12/4/07	< 27.0	No	No	
TotalHg-ST13-12/2/07	0749004-08	Marriott Hotel, 38th Floor (roof level)	12/2/07	0.57	Mercury	EPA 324/1631	BRL	12/4/07	< 26.0	No	No	
TotalHg-ST14-12/3/07	0749011-01	Southwest Area (sidewalk bridge level)	12/3/07	0.59	Mercury	EPA 324/1631	BRL	12/5/07	< 25.0	No	No	
TotalHg-ST2-12/3/07	0749011-02	Southeast Area (sidewalk bridge level)	12/3/07	0.50	Mercury	EPA 324/1631	BRL	12/5/07	< 30.0	No	No	Note 3
TotalHg-ST4-12/3/07	0749011-03	Northwest Area (street-level)	12/3/07	0.52	Mercury	EPA 324/1631	BRL	12/5/07	< 29.0	No	No	
TotalHg-ST5-12/3/07	0749011-04	Firehouse #10 (roof level)	12/3/07	0.56	Mercury	EPA 324/1631	BRL	12/5/07	< 27.0	No	No	
TotalHg-ST10-12/3/07	0749011-05	North Side Sidewalk Bridge	12/3/07	0.51	Mercury	EPA 324/1631	BRL	12/5/07	< 29.0	No	No	
TotalHg-ST11-12/3/07	0749011-06	90 Trinity Place (roof level)	12/3/07	0.56	Mercury	EPA 324/1631	BRL	12/5/07	< 27.0	No	No	
TotalHg-ST12-12/3/07	0749011-07	110 Greenwich Street (roof level)	12/3/07	0.55	Mercury	EPA 324/1631	BRL	12/5/07	< 27.0	No	No	
TotalHg-ST13-12/3/07	0749011-08	Marriott Hotel, 38th Floor (roof level)	12/3/07	0.52	Mercury	EPA 324/1631	BRL	12/5/07	< 29.0	No	No	
TotalHg-ST14-12/3/07	0749011-09	West Face - South end at corner (scaffolding level)	12/3/07	0.55	Mercury	EPA 324/1631	BRL	12/5/07	< 27.0	No	No	
TotalHg-ST15-12/3/07	0749011-10	South Face - East end at corner (scaffolding level)	12/3/07	0.59	Mercury	EPA 324/1631	BRL	12/5/07	< 25.0	No	No	
TotalHg-ST16-12/3/07	0749011-11	East Face - North end at corner (scaffolding level)	1									