

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-12/10/08	0850041-01	Southwest Area (sidewalk bridge level)	12/10/2008	0.61	Mercury	EPA 324/1631	BRL	12/12/2008	< 25.0	No	No	
TotalHg-ST2-12/10/08	0850041-02	Southeast Area (sidewalk bridge level)	12/10/2008	0.57	Mercury	EPA 324/1631	BRL	12/12/2008	< 26.0	No	No	
TotalHg-ST4-12/10/08	0850041-03	Northwest Area (street-level)	12/10/2008	0.61	Mercury	EPA 324/1631	BRL	12/12/2008	< 25.0	No	No	
TotalHg-ST5-12/10/08	0850041-04	Firehouse #10 (roof level)	12/10/2008	0.56	Mercury	EPA 324/1631	BRL	12/12/2008	< 27.0	No	No	
TotalHg-ST10-12/10/08	0850041-05	North Side Sidewalk Bridge	12/10/2008	0.56	Mercury	EPA 324/1631	BRL	12/12/2008	< 27.0	No	No	
TotalHg-ST11-12/10/08	0850041-06	90 Trinity Place (roof level)	12/10/2008	0.57	Mercury	EPA 324/1631	BRL	12/12/2008	< 26.0	No	No	
TotalHg-ST12-12/10/08	0850041-07	110 Greenwich Street (roof level)	12/10/2008	0.56	Mercury	EPA 324/1631	BRL	12/12/2008	< 27.0	No	No	
TotalHg-ST13-12/10/08	0850041-08	Marriott Hotel, 38th Floor (roof level)	12/10/2008	0.57	Mercury	EPA 324/1631	BRL	12/12/2008	< 26.0	No	No	
TotalHg-ST14-12/10/08	0850041-09	West Face - South end at corner (scaffolding level)	12/10/2008	0.57	Mercury	EPA 324/1631	BRL	12/12/2008	< 26.0	No	No	
TotalHg-ST15-12/10/08	0850041-10	South Face - East end at corner (scaffolding level)	12/10/2008	0.57	Mercury	EPA 324/1631	BRL	12/12/2008	< 26.0	No	No	
TotalHg-ST16-12/10/08	0850041-11	East Face - North end at corner (scaffolding level)	12/10/2008	0.54	Mercury	EPA 324/1631	BRL	12/12/2008	< 28.0	No	No	
TotalHg-ST17-12/10/08	0850041-12	North Face - West end at corner (scaffolding level)	12/10/2008	0.56	Mercury	EPA 324/1631	BRL	12/12/2008	< 27.0	No	No	
TotalHg-ST1-12/11/08	0850047-01	Southwest Area (sidewalk bridge level)	12/11/2008	0.53	Mercury	EPA 324/1631	BRL	12/13/2008	< 28.0	No	No	
TotalHg-ST2-12/11/08	0850047-02	Southeast Area (sidewalk bridge level)	12/11/2008	0.59	Mercury	EPA 324/1631	BRL	12/13/2008	< 25.0	No	No	
TotalHg-ST4-12/11/08	0850047-03	Northwest Area (street-level)	12/11/2008	0.58	Mercury	EPA 324/1631	BRL	12/13/2008	< 26.0	No	No	
TotalHg-ST5-12/11/08	0850047-04	Firehouse #10 (roof level)	12/11/2008	0.58	Mercury	EPA 324/1631	BRL	12/13/2008	< 26.0	No	No	
TotalHg-ST10-12/11/08	0850047-05	North Side Sidewalk Bridge	12/11/2008	0.63	Mercury	EPA 324/1631	BRL	12/13/2008	< 24.0	No	No	
TotalHg-ST11-12/11/08	0850047-06	90 Trinity Place (roof level)	12/11/2008	0.56	Mercury	EPA 324/1631	BRL	12/13/2008	< 27.0	No	No	
TotalHg-ST12-12/11/08	0850047-07	110 Greenwich Street (roof level)	12/11/2008	0.54	Mercury	EPA 324/1631	BRL	12/13/2008	< 28.0	No	No	
TotalHg-ST13-12/11/08	0850047-08	Marriott Hotel, 38th Floor (roof level)	12/11/2008	0.56	Mercury	EPA 324/1631	BRL	12/13/2008	< 27.0	No	No	
TotalHg-ST14-12/11/08	0850047-09	West Face - South end at corner (scaffolding level)	12/11/2008	0.58	Mercury	EPA 324/1631	BRL	12/13/2008	< 26.0	No	No	
TotalHg-ST15-12/11/08	0850047-10	South Face - East end at corner (scaffolding level)	12/11/2008	0.54	Mercury	EPA 324/1631	BRL	12/13/2008	< 28.0	No	No	
TotalHg-ST16-12/11/08	0850047-11	East Face - North end at corner (scaffolding level)	12/11/2008	0.54	Mercury	EPA 324/1631	BRL	12/13/2008	< 28.0	No	No	
TotalHg-ST17-12/11/08	0850047-12	North Face - West end at corner (scaffolding level)	12/11/2008	0.59	Mercury	EPA 324/1631	BRL	12/13/2008	< 25.0	No	No	
TotalHg-ST1-12/12/08	0851001-01	Southwest Area (sidewalk bridge level)	12/12/2008	0.59	Mercury	EPA 324/1631	BRL	12/15/2008	< 25.0	No	No	
TotalHg-ST2-12/12/08	0851001-02	Southeast Area (sidewalk bridge level)	12/12/2008	0.59	Mercury	EPA 324/1631	BRL	12/15/2008	< 25.0	No	No	
TotalHg-ST4-12/12/08	0851001-03	Northwest Area (street-level)	12/12/2008	0.59	Mercury	EPA 324/1631	BRL	12/15/2008	< 25.0	No	No	
TotalHg-ST5-12/12/08	0851001-04	Firehouse #10 (roof level)	12/12/2008	0.57	Mercury	EPA 324/1631	BRL	12/15/2008	< 26.0	No	No	
TotalHg-ST10-12/12/08	0851001-05	North Side Sidewalk Bridge	12/12/2008	0.54	Mercury	EPA 324/1631	BRL	12/15/2008	< 28.0	No	No	
TotalHg-ST11-12/12/08	0851001-06	90 Trinity Place (roof level)	12/12/2008	0.59	Mercury	EPA 324/1631	BRL	12/15/2008	< 25.0	No	No	
TotalHg-ST12-12/12/08	0851001-07	110 Greenwich Street (roof level)	12/12/2008	0.56	Mercury	EPA 324/1631	BRL	12/15/2008	< 27.0	No	No	
TotalHg-ST13-12/12/08	0851001-08	Marriott Hotel, 38th Floor (roof level)	12/12/2008	0.55	Mercury	EPA 324/1631	BRL	12/15/2008	< 27.0	No	No	
TotalHg-ST14-12/12/08	0851001-09	West Face - South end at corner (scaffolding level)	12/12/2008	0.55	Mercury	EPA 324/1631	BRL	12/15/2008	< 27.0	No	No	
TotalHg-ST15-12/12/08	0851001-10	South Face - East end at corner (scaffolding level)	12/12/2008	0.53	Mercury	EPA 324/1631	BRL	12/15/2008	< 28.0	No	No	
TotalHg-ST16-12/12/08	0851001-11	East Face - North end at corner (scaffolding level)	12/12/2008	0.54	Mercury	EPA 324/1631	BRL	12/15/2008	< 28.0	No	No	
TotalHg-ST17-12/12/08	0851001-12	North Face - West end at corner (scaffolding level)	12/12/2008	0.55	Mercury	EPA 324/1631	BRL	12/15/2008	< 27.0	No	No	