

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-12/16/05	05BR1920-1	Southwest Area (sidewalk bridge level)	12/16/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST2-12/16/05	05BR1920-2	Southeast Area (sidewalk bridge level)	12/16/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST4-12/16/05	05BR1920-3	Northwest Area (street-level)	12/16/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST5-12/16/05	05BR1920-4	Firehouse #10 (roof level)	12/16/05	0.56	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST10-12/16/05	05BR1920-5	North Side Sidewalk Bridge	12/16/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST11-12/16/05	05BR1920-6	90 Trinity Place (roof level)	12/16/05	0.54	Mercury	EPA 324/1631	BRL	12/21/05	< 28.0	No	No	
TotalHg-ST12-12/16/05	05BR1920-7	110 Greenwich Street (roof level)	12/16/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST13-12/16/05	05BR1920-8	Marriott Hotel, 38th Floor (roof level)	12/16/05	0.54	Mercury	EPA 324/1631	BRL	12/21/05	< 28.0	No	No	
TotalHg-ST14-12/16/05	05BR1920-9	West Face - South end at corner (scaffolding level)	12/16/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST15-12/16/05	05BR1920-10	South Face - East end at corner (scaffolding level)	12/16/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST16-12/16/05	05BR1920-11	East Face - North end at corner (scaffolding level)	12/16/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST17-12/16/05	05BR1920-12	North Face - West end at corner (scaffolding level)	12/16/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST1-12/17/05	05BR1921-1	Southwest Area (sidewalk bridge level)	12/17/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST2-12/17/05	05BR1921-2	Southeast Area (sidewalk bridge level)	12/17/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST4-12/17/05	05BR1921-3	Northwest Area (street-level)	12/17/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST5-12/17/05	05BR1921-4	Firehouse #10 (roof level)	12/17/05	0.59	Mercury	EPA 324/1631	BRL	12/21/05	< 25.0	No	No	
TotalHg-ST10-12/17/05	05BR1921-5	North Side Sidewalk Bridge	12/17/05	0.56	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST11-12/17/05	05BR1921-6	90 Trinity Place (roof level)	12/17/05	0.59	Mercury	EPA 324/1631	BRL	12/21/05	< 25.0	No	No	
TotalHg-ST12-12/17/05	05BR1921-7	110 Greenwich Street (roof level)	12/17/05	0.61	Mercury	EPA 324/1631	BRL	12/21/05	< 25.0	No	No	
TotalHg-ST13-12/17/05	05BR1921-8	Marriott Hotel, 38th Floor (roof level)	12/17/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST14-12/17/05	05BR1921-9	West Face - South end at corner (scaffolding level)	12/17/05	0.59	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST15-12/17/05	05BR1921-10	South Face - East end at corner (scaffolding level)	12/17/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST16-12/17/05	05BR1921-11	East Face - North end at corner (scaffolding level)	12/17/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST1-12/18/05	05BR1922-1	Southwest Area (sidewalk bridge level)	12/18/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST2-12/18/05	05BR1922-2	Southeast Area (sidewalk bridge level)	12/18/05	0.54	Mercury	EPA 324/1631	BRL	12/21/05	< 28.0	No	No	
TotalHg-ST4-12/18/05	05BR1922-3	Northwest Area (street-level)	12/18/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST5-12/18/05	05BR1922-4	Firehouse #10 (roof level)	12/18/05	0.62	Mercury	EPA 324/1631	BRL	12/21/05	< 24.0	No	No	
TotalHg-ST10-12/18/05	05BR1922-5	North Side Sidewalk Bridge	12/18/05	0.57	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST11-12/18/05	05BR1922-6	90 Trinity Place (roof level)	12/18/05	0.58	Mercury	EPA 324/1631	BRL	12/21/05	< 26.0	No	No	
TotalHg-ST12-12/18/05	05BR1922-7	110 Greenwich Street (roof level)	12/18/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST13-12/18/05	05BR1922-8	Marriott Hotel, 38th Floor (roof level)	12/18/05	0.61	Mercury	EPA 324/1631	BRL	12/21/05	< 25.0	No	No	
TotalHg-ST14-12/18/05	05BR1922-9	West Face - South end at corner (scaffolding level)	12/18/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST17-12/18/05	05BR1922-10	North Face - West end at corner (scaffolding level)	12/18/05	0.55	Mercury	EPA 324/1631	BRL	12/21/05	< 27.0	No	No	
TotalHg-ST1-12/19/05	05BR1925-1	Southwest Area (sidewalk bridge level)	12/19/05	0.59	Mercury	EPA 324/1631	BRL	12/22/05	< 25.0	No	No	
TotalHg-ST2-12/19/05	05BR1925-2	Southeast Area (sidewalk bridge level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST4-12/19/05	05BR1925-3	Northwest Area (street-level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST5-12/19/05	05BR1925-4	Firehouse #10 (roof level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST10-12/19/05	05BR1925-5	North Side Sidewalk Bridge	12/19/05	0.59	Mercury	EPA 324/1631	BRL	12/22/05	< 25.0	No	No	
TotalHg-ST11-12/19/05	05BR1925-6	90 Trinity Place (roof level)	12/19/05	0.57	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST12-12/19/05	05BR1925-7	110 Greenwich Street (roof level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST13-12/19/05	05BR1925-8	Marriott Hotel, 38th Floor (roof level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST14-12/19/05	05BR1925-9	West Face - South end at corner (scaffolding level)	12/19/05	0.58	Mercury	EPA 324/1631	BRL	12/22/05	< 26.0	No	No	
TotalHg-ST17-12/19/05	05BR1925-10	North Face - West end at corner (scaffolding level)	12/19/05	0.59	Mercury	EPA 324/1631	BRL	12/22/05	< 25.0	No	No	

Note:

1. Mercury sample at Station 17 (North Face - West end at corner [scaffolding level]) on December 17, 2005 was not available for analysis on account of pump failure.
2. Mercury samples at Station 15 (South Face - East end at corner [scaffolding level]) and Station 16 (East Face - North end at corner [scaffolding level]) on December 18 and 19, 2005 were not available for analysis on account of pump failure.