

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-12/24/05	05BR1960-1	Southwest Area (sidewalk bridge level)	12/24/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST2-12/24/05	05BR1960-2	Southeast Area (sidewalk bridge level)	12/24/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST4-12/24/05	05BR1960-3	Northwest Area (street-level)	12/24/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST5-12/24/05	05BR1960-4	Firehouse #10 (roof level)	12/24/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST10-12/24/05	05BR1960-5	North Side Sidewalk Bridge	12/24/05	0.51	Mercury	EPA 324/1631	BRL	12/28/05	< 29.0	No	No	
TotalHg-ST11-12/24/05	05BR1960-6	90 Trinity Place (roof level)	12/24/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST12-12/24/05	05BR1960-7	110 Greenwich Street (roof level)	12/24/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST13-12/24/05	05BR1960-8	Marriott Hotel, 38th Floor (roof level)	12/24/05	0.63	Mercury	EPA 324/1631	BRL	12/28/05	< 24.0	No	No	
TotalHg-ST14-12/24/05	05BR1960-9	West Face - South end at corner (scaffolding level)	12/24/05	0.58	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST15-12/24/05	05BR1960-10	South Face - East end at corner (scaffolding level)	12/24/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST16-12/24/05	05BR1960-11	East Face - North end at corner (scaffolding level)	12/24/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST17-12/24/05	05BR1960-12	North Face - West end at corner (scaffolding level)	12/24/05	0.58	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST1-12/25/05	05BR1961-1	Southwest Area (sidewalk bridge level)	12/25/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST2-12/25/05	05BR1961-2	Southeast Area (sidewalk bridge level)	12/25/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST4-12/25/05	05BR1961-3	Northwest Area (street-level)	12/25/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST5-12/25/05	05BR1961-4	Firehouse #10 (roof level)	12/25/05	0.51	Mercury	EPA 324/1631	BRL	12/28/05	< 29.0	No	No	
TotalHg-ST10-12/25/05	05BR1961-5	North Side Sidewalk Bridge	12/25/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST11-12/25/05	05BR1961-6	90 Trinity Place (roof level)	12/25/05	0.54	Mercury	EPA 324/1631	BRL	12/28/05	< 28.0	No	No	
TotalHg-ST12-12/25/05	05BR1961-7	110 Greenwich Street (roof level)	12/25/05	0.51	Mercury	EPA 324/1631	BRL	12/28/05	< 29.0	No	No	
TotalHg-ST13-12/25/05	05BR1961-8	Marriott Hotel, 38th Floor (roof level)	12/25/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST14-12/25/05	05BR1961-9	West Face - South end at corner (scaffolding level)	12/25/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST15-12/25/05	05BR1961-10	South Face - East end at corner (scaffolding level)	12/25/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST16-12/25/05	05BR1961-11	East Face - North end at corner (scaffolding level)	12/25/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST17-12/25/05	05BR1961-12	North Face - West end at corner (scaffolding level)	12/25/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST1-12/26/05	05BR1962-1	Southwest Area (sidewalk bridge level)	12/26/05	0.58	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST2-12/26/05	05BR1962-2	Southeast Area (sidewalk bridge level)	12/26/05	0.58	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST4-12/26/05	05BR1962-3	Northwest Area (street-level)	12/26/05	0.59	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST5-12/26/05	05BR1962-4	Firehouse #10 (roof level)	12/26/05	0.59	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST10-12/26/05	05BR1962-5	North Side Sidewalk Bridge	12/26/05	0.59	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST11-12/26/05	05BR1962-6	90 Trinity Place (roof level)	12/26/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST12-12/26/05	05BR1962-7	110 Greenwich Street (roof level)	12/26/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST13-12/26/05	05BR1962-8	Marriott Hotel, 38th Floor (roof level)	12/26/05	0.59	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST14-12/26/05	05BR1962-9	West Face - South end at corner (scaffolding level)	12/26/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST15-12/26/05	05BR1962-10	South Face - East end at corner (scaffolding level)	12/26/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST16-12/26/05	05BR1962-11	East Face - North end at corner (scaffolding level)	12/26/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST17-12/26/05	05BR1962-12	North Face - West end at corner (scaffolding level)	12/26/05	0.60	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST1-12/27/05	05BR1969-1	Southwest Area (sidewalk bridge level)	12/27/05	0.55	Mercury	EPA 324/1631	BRL	12/29/05	< 27.0	No	No	
TotalHg-ST2-12/27/05	05BR1969-2	Southeast Area (sidewalk bridge level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST4-12/27/05	05BR1969-3	Northwest Area (street-level)	12/27/05	0.56	Mercury	EPA 324/1631	BRL	12/29/05	< 27.0	No	No	
TotalHg-ST5-12/27/05	05BR1969-4	Firehouse #10 (roof level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST10-12/27/05	05BR1969-5	North Side Sidewalk Bridge	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST11-12/27/05	05BR1969-6	90 Trinity Place (roof level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST12-12/27/05	05BR1969-7	110 Greenwich Street (roof level)	12/27/05	0.53	Mercury	EPA 324/1631	BRL	12/29/05	< 28.0	No	No	
TotalHg-ST13-12/27/05	05BR1969-8	Marriott Hotel, 38th Floor (roof level)	12/27/05	0.56	Mercury	EPA 324/1631	BRL	12/29/05	< 27.0	No	No	
TotalHg-ST14-12/27/05	05BR1969-9	West Face - South end at corner (scaffolding level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST15-12/27/05	05BR1969-10	South Face - East end at corner (scaffolding level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST16-12/27/05	05BR1969-11	East Face - North end at corner (scaffolding level)	12/27/05	0.58	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST17-12/27/05	05BR1969-12	North Face - West end at corner (scaffolding level)	12/27/05	0.57	Mercury	EPA 324/1631	BRL	12/29/05	< 26.0	No	No	
TotalHg-ST1-12/28/05	05BR1975-1	Southwest Area (sidewalk bridge level)	12/28/05	0.59	Mercury	EPA 324/1631	BRL	12/30/05	< 25.0	No	No	
TotalHg-ST2-12/28/05	05BR1975-2	Southeast Area (sidewalk bridge level)	12/28/05	0.65	Mercury	EPA 324/1631	BRL	12/30/05	< 23.0	No	No	
TotalHg-ST4-12/28/05	05BR1975-3	Northwest Area (street-level)	12/28/05	0.71	Mercury	EPA 324/1631	BRL	12/30/05	< 21.0	No	No	
TotalHg-ST5-12/28/05	05BR1975-4	Firehouse #10 (roof level)	12/28/05	0.59	Mercury	EPA 324/1631	BRL	12/30/05	< 25.0	No	No	
TotalHg-ST10-12/28/05	05BR1975-5	North Side Sidewalk Bridge	12/28/05	0.55	Mercury	EPA 324/1631	BRL	12/30/05	< 27.0	No	No	
TotalHg-ST11-12/28/05	05BR1975-6	90 Trinity Place (roof level)	12/28/05	0.59	Mercury	EPA 324/1631	BRL	12/30/05	< 25.0	No	No	
TotalHg-ST12-12/28/05	05BR1975-7	110 Greenwich Street (roof level)	12/28/05	0.59	Mercury	EPA 324/1631	BRL	12/30/05	< 25.0	No	No	
TotalHg-ST13-12/28/05	05BR1975-8	Marriott Hotel, 38th Floor (roof level)	12/28/05	0.59	Mercury	EPA 324/1631	BRL	12/30/05	< 25.0	No	No	
TotalHg-ST14-12/28/05	05BR1975-9	West Face - South end at corner (scaffolding level)	12/28/05	0.57	Mercury	EPA 324/1631	BRL	12/30/05	< 26.0	No	No	
TotalHg-ST15-12/28/05	05BR1975-10	South Face - East end at corner (scaffolding level)	12/28/05	0.64	Mercury	EPA 324/1631	BRL	12/30/05	< 23.0	No	No	
TotalHg-ST16-12/28/05	05BR1975-11	East Face - North end at corner (scaffolding level)	12/28/05	0.65	Mercury	EPA 324/1631	BRL	12/30/05	< 23.0	No	No	
TotalHg-ST17-12/28/05	05BR1975-12	North Face - West end at corner (scaffolding level)	12/28/05	0.58	Mercury	EPA 324/1631	BRL	12/30/05	< 26.0	No	No	