

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-12/29/06	07BR0003-01	Southwest Area (sidewalk bridge level)	12/29/06	0.56	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST2-12/29/06	07BR0003-02	Southeast Area (sidewalk bridge level)	12/29/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST4-12/29/06	07BR0003-03	Northwest Area (street-level)	12/29/06	0.55	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST5-12/29/06	07BR0003-04	Firehouse #10 (roof level)	12/29/06	0.56	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST10-12/29/06	07BR0003-05	North Side Sidewalk Bridge	12/29/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST11-12/29/06	07BR0003-06	90 Trinity Place (roof level)	12/29/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST12-12/29/06	07BR0003-07	110 Greenwich Street (roof level)	12/29/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST13-12/29/06	07BR0003-08	Marriott Hotel, 38th Floor (roof level)	12/29/06	0.56	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST14-12/29/06	07BR0003-09	West Face - South end at corner (scaffolding level)	12/29/06	0.52	Mercury	EPA 324/1631	BRL	1/3/07	< 29.0	No	No	
TotalHg-ST15-12/29/06	07BR0003-10	South Face - East end at corner (scaffolding level)	12/29/06	0.50	Mercury	EPA 324/1631	BRL	1/3/07	< 30.0	No	No	
TotalHg-ST16-12/29/06	07BR0003-11	East Face - North end at corner (scaffolding level)	12/29/06	0.51	Mercury	EPA 324/1631	BRL	1/3/07	< 29.0	No	No	
TotalHg-ST17-12/29/06	07BR0003-12	North Face - West end at corner (scaffolding level)	12/29/06	0.52	Mercury	EPA 324/1631	BRL	1/3/07	< 29.0	No	No	
TotalHg-ST1-12/30/06	07BR0004-01	Southwest Area (sidewalk bridge level)	12/30/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST2-12/30/06	07BR0004-02	Southeast Area (sidewalk bridge level)	12/30/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST4-12/30/06	07BR0004-03	Northwest Area (street-level)	12/30/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST5-12/30/06	07BR0004-04	Firehouse #10 (roof level)	12/30/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST10-12/30/06	07BR0004-05	North Side Sidewalk Bridge	12/30/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST11-12/30/06	07BR0004-06	90 Trinity Place (roof level)	12/30/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST12-12/30/06	07BR0004-07	110 Greenwich Street (roof level)	12/30/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST13-12/30/06	07BR0004-08	Marriott Hotel, 38th Floor (roof level)	12/30/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST14-12/30/06	07BR0004-09	West Face - South end at corner (scaffolding level)	12/30/06	0.55	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST15-12/30/06	07BR0004-10	South Face - East end at corner (scaffolding level)	12/30/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST16-12/30/06	07BR0004-11	East Face - North end at corner (scaffolding level)	12/30/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST17-12/30/06	07BR0004-12	North Face - West end at corner (scaffolding level)	12/30/06	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST1-12/31/06	07BR0005-01	Southwest Area (sidewalk bridge level)	12/31/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST2-12/31/06	07BR0005-02	Southeast Area (sidewalk bridge level)	12/31/06	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST4-12/31/06	07BR0005-03	Northwest Area (street-level)	12/31/06	0.56	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST5-12/31/06	07BR0005-04	Firehouse #10 (roof level)	12/31/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST10-12/31/06	07BR0005-05	North Side Sidewalk Bridge	12/31/06	0.63	Mercury	EPA 324/1631	BRL	1/3/07	< 24.0	No	No	
TotalHg-ST11-12/31/06	07BR0005-06	90 Trinity Place (roof level)	12/31/06	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST12-12/31/06	07BR0005-07	110 Greenwich Street (roof level)	12/31/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST13-12/31/06	07BR0005-08	Marriott Hotel, 38th Floor (roof level)	12/31/06	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST14-12/31/06	07BR0005-09	West Face - South end at corner (scaffolding level)	12/31/06	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST15-12/31/06	07BR0005-10	South Face - East end at corner (scaffolding level)	12/31/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST16-12/31/06	07BR0005-11	East Face - North end at corner (scaffolding level)	12/31/06	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST17-12/31/06	07BR0005-12	North Face - West end at corner (scaffolding level)	12/31/06	0.59	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST1-1/1/07	07BR0006-01	Southwest Area (sidewalk bridge level)	1/1/07	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST2-1/1/07	07BR0006-02	Southeast Area (sidewalk bridge level)	1/1/07	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST4-1/1/07	07BR0006-03	Northwest Area (street-level)	1/1/07	0.62	Mercury	EPA 324/1631	BRL	1/3/07	< 24.0	No	No	
TotalHg-ST5-1/1/07	07BR0006-04	Firehouse #10 (roof level)	1/1/07	0.54	Mercury	EPA 324/1631	BRL	1/3/07	< 28.0	No	No	
TotalHg-ST10-1/1/07	07BR0006-05	North Side Sidewalk Bridge	1/1/07	0.56	Mercury	EPA 324/1631	BRL	1/3/07	< 27.0	No	No	
TotalHg-ST11-1/1/07	07BR0006-06	90 Trinity Place (roof level)	1/1/07	0.54	Mercury	EPA 324/1631	BRL	1/3/07	< 28.0	No	No	
TotalHg-ST12-1/1/07	07BR0006-07	110 Greenwich Street (roof level)	1/1/07	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST13-1/1/07	07BR0006-08	West Face - South end at corner (scaffolding level)	1/1/07	0.57	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST14-1/1/07	07BR0006-09	West Face - South end at corner (scaffolding level)	1/1/07	0.62	Mercury	EPA 324/1631	BRL	1/3/07	< 24.0	No	No	
TotalHg-ST15-1/1/07	07BR0006-10	South Face - East end at corner (scaffolding level)	1/1/07	0.60	Mercury	EPA 324/1631	BRL	1/3/07	< 25.0	No	No	
TotalHg-ST16-1/1/07	07BR0006-11	East Face - North end at corner (scaffolding level)	1/1/07	0.63	Mercury	EPA 324/1631	BRL	1/3/07	< 24.0	No	No	
TotalHg-ST17-1/1/07	07BR0006-12	North Face - West end at corner (scaffolding level)	1/1/07	0.58	Mercury	EPA 324/1631	BRL	1/3/07	< 26.0	No	No	
TotalHg-ST1-1/2/07	07BR0012-01	Southwest Area (sidewalk bridge level)	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST2-1/2/07	07BR0012-02	Southeast Area (sidewalk bridge level)	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST4-1/2/07	07BR0012-03	Northwest Area (street-level)	1/2/07	0.58	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST5-1/2/07	07BR0012-04	Firehouse #10 (roof level)	1/2/07	0.53	Mercury	EPA 324/1631	BRL	1/4/07	< 28.0	No	No	
TotalHg-ST10-1/2/07	07BR0012-05	North Side Sidewalk Bridge	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST11-1/2/07	07BR0012-06	90 Trinity Place (roof level)	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST12-1/2/07	07BR0012-07	110 Greenwich Street (roof level)	1/2/07	0.58	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST13-1/2/07	07BR0012-08	Marriott Hotel, 38th Floor (roof level)	1/2/07	0.59	Mercury	EPA 324/1631	BRL	1/4/07	< 25.0	No	No	
TotalHg-ST14-1/2/07	07BR0012-09	West Face - South end at corner (scaffolding level)	1/2/07	0.54	Mercury	EPA 324/1631	BRL	1/4/07	< 28.0	No	No	
TotalHg-ST15-1/2/07	07BR0012-10	South Face - East end at corner (scaffolding level)	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST16-1/2/07	07BR0012-11	East Face - North end at corner (scaffolding level)	1/2/07	0.57	Mercury	EPA 324/1631	BRL	1/4/07	< 26.0	No	No	
TotalHg-ST17-1/2/07	07BR0012-12	North Face - West end at corner (scaffolding level)	1/2/07	0.59	Mercury	EPA 324/1631	BRL	1/4/07	< 25.0	No	No	