

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									5,000	5,000	20	40	600	100,000	1,500	500	200	16,000	Air Quality	Exceeds EPA	Comments
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Levels	Site Specific	Comments
METALS-ST11-1/5/07	G7A090157001	Southwest Area (sidewalk bridge level)	1/5/07	1643.4	Metals	6020	STL-SAC	1/9/07	< 1.5	< 73.0	< 0.73	< 0.73	< 7.3	216	6.3	8.7	5.0	41.0	No	No	
METALS-ST2-1/5/07	G7A090157002	Southeast Area (sidewalk bridge level)	1/5/07	1671	Metals	6020	STL-SAC	1/9/07	1.5	< 71.8	< 0.72	< 0.72	< 7.2	311	6.1	7.9	4.7	39.4	No	No	
METALS-ST4-1/5/07	G7A090157003	Northwest Area (street-level)	1/5/07	1665.7	Metals	6020	STL-SAC	1/9/07	1.6	< 72.0	< 0.72	< 0.72	< 7.2	58.0	8.8	9.0	5.0	93.0	No	No	
METALS-ST5-1/5/07	G7A090157004	Firehouse #10 (roof level)	1/5/07	1672	Metals	6020	STL-SAC	1/9/07	1.9	< 71.8	< 0.72	< 0.72	< 7.2	128	9.6	35.7	6.2	54.0	No	No	
METALS-ST10-1/5/07	G7A090157005	North Side Sidewalk Bridge	1/5/07	1758.8	Metals	6020	STL-SAC	1/9/07	1.9	< 68.2	< 0.68	< 0.68	< 6.8	68.6	6.0	68.6	6.0	53.4	No	No	
METALS-ST100-1/5/07	G7A090157013	Station 10 Field Duplicate	1/5/07	1759.9	Metals	6020	STL-SAC	1/9/07	1.8	< 68.3	< 0.68	< 0.68	< 6.8	137	8.9	21.0	6.5	55.0	No	No	
METALS-ST11-1/5/07	G7A090157006	90 Trinity Place (roof level)	1/5/07	1765.9	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.0	< 0.68	< 0.68	< 6.8	147	7.1	7.4	4.8	34.1	No	No	
METALS-ST12-1/5/07	G7A090157007	110 Greenwich Street (roof level)	1/5/07	1692.7	Metals	6020	STL-SAC	1/9/07	< 1.4	< 70.9	< 0.71	< 0.71	< 7.1	149	8.0	8.2	4.8	40.2	No	No	
METALS-ST13-1/5/07	G7A090157008	Marriot Hotel, 38th Floor (roof level)	1/5/07	1761.4	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.1	< 0.68	< 0.68	< 6.8	122	6.0	7.1	5.2	35.4	No	No	
METALS-ST14-1/5/07	G7A090157009	West Face - South end at corner (scaffolding level)	1/5/07	1640.9	Metals	6020	STL-SAC	1/9/07	< 1.5	< 73.1	< 0.73	< 0.73	< 7.3	11.2	< 0.73	< 3.6	< 3.6	< 14.6	No	No	
METALS-ST15-1/5/07	G7A090157010	South Face - East end at corner (scaffolding level)	1/5/07	1663.5	Metals	6020	STL-SAC	1/9/07	< 1.4	< 72.1	< 0.72	< 0.72	< 7.2	54.2	2.9	< 3.6	< 3.6	22.8	No	No	
METALS-ST16-1/5/07	G7A090157011	East Face - North end at corner (scaffolding level)	1/5/07	1672.6	Metals	6020	STL-SAC	1/9/07	< 1.4	< 71.7	< 0.72	< 0.72	< 7.2	126	2.9	< 3.6	< 3.6	22.4	No	No	
METALS-ST17-1/5/07	G7A090157012	North Face - West end at corner (scaffolding level)	1/5/07	1630.6	Metals	6020	STL-SAC	1/9/07	< 1.5	< 0.74	< 0.74	< 0.74	< 7.4	196	3.2	< 3.7	< 3.7	24.9	No	No	
METALS-ST11-1/6/07	G7A090155001	Southwest Area (sidewalk bridge level)	1/6/07	1751.6	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.5	< 0.68	< 0.68	< 6.8	121	7.7	6.4	< 3.4	44.5	No	No	
METALS-ST2-1/6/07	G7A090155002	Southeast Area (sidewalk bridge level)	1/6/07	1776.4	Metals	6020	STL-SAC	1/9/07	< 1.4	< 67.6	< 0.68	< 0.68	< 6.8	162	18.4	11.2	3.6	42.0	No	No	
METALS-ST4-1/6/07	G7A090155003	Northwest Area (street-level)	1/6/07	1789.4	Metals	6020	STL-SAC	1/9/07	< 1.3	< 67.1	< 0.67	< 0.67	< 6.7	110	30.7	7.1	< 3.4	42.2	No	No	
METALS-ST5-1/6/07	G7A090155004	Firehouse #10 (roof level)	1/6/07	1790.1	Metals	6020	STL-SAC	1/9/07	< 1.3	< 67.0	< 0.67	< 0.67	< 6.7	92.6	11.7	22.1	4.1	50.5	No	No	
METALS-ST10-1/6/07	G7A090155005	North Side Sidewalk Bridge	1/6/07	1781.9	Metals	6020	STL-SAC	1/9/07	< 1.3	< 67.3	< 0.67	< 0.67	< 6.7	84.1	8.8	10.0	< 3.4	57.4	No	No	
METALS-ST11-1/6/07	G7A090155006	90 Trinity Place (roof level)	1/6/07	1753	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.4	< 0.68	< 0.68	< 6.8	91.2	5.1	5.9	3.4	27.7	No	No	
METALS-ST12-1/6/07	G7A090155007	110 Greenwich Street (roof level)	1/6/07	1766.2	Metals	6020	STL-SAC	1/9/07	< 1.4	< 67.9	< 0.68	< 0.68	< 6.8	61.3	4.6	4.9	< 3.4	25.6	No	No	
METALS-ST13-1/6/07	G7A090155008	Marriot Hotel, 38th Floor (roof level)	1/6/07	1692.7	Metals	6020	STL-SAC	1/9/07	< 1.4	< 70.9	< 0.71	< 0.71	< 7.1	72.2	3.3	< 3.5	< 3.5	21.0	No	No	
METALS-ST14-1/6/07	G7A090155009	West Face - South end at corner (scaffolding level)	1/6/07	1764.1	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.0	< 0.68	< 0.68	< 6.8	2.8	< 3.4	24.0	< 3.4	13.6	No	No	
METALS-ST15-1/6/07	G7A090155010	South Face - East end at corner (scaffolding level)	1/6/07	1783.8	Metals	6020	STL-SAC	1/9/07	< 1.3	< 67.3	< 0.67	< 0.67	< 6.7	78.7	3.6	< 3.4	< 3.4	22.2	No	No	
METALS-ST16-1/6/07	G7A090155011	East Face - North end at corner (scaffolding level)	1/6/07	1764.2	Metals	6020	STL-SAC	1/9/07	< 1.4	< 68.0	< 0.68	< 0.68	< 6.8	55.1	5.4	7.4	< 3.4	25.8	No	No	
METALS-ST17-1/6/07	G7A090155012	North Face - West end at corner (scaffolding level)	1/6/07	1777.7	Metals	6020	STL-SAC	1/9/07	< 1.4	< 67.5	< 0.68	< 0.68	< 6.8	49.7	4.9	5.0	< 3.4	26.0	No	No	
METALS-ST1-1/7/07	G7A090154001	Southwest Area (sidewalk bridge level)	1/7/07	1707.3	Metals	6020	STL-SAC	1/9/07	2.1	< 70.3	< 0.70	< 0.70	< 7.0	250	5.0	7.8	8.0	33.2	No	No	
METALS-ST2-1/7/07	G7A090154002	Southeast Area (sidewalk bridge level)	1/7/07	1715.1	Metals	6020	STL-SAC	1/9/07	3.0	< 70.0	< 0.70	< 0.70	< 7.0	220	5.9	19.2	8.7	36.8	No	No	
METALS-ST4-1/7/07	G7A090154003	Northwest Area (street-level)	1/7/07	1747.5	Metals	6020	STL-SAC	1/9/07	2.1	< 68.7	< 0.69	< 0.69	< 6.9	95.7	4.3	9.2	7.8	28.9	No	No	
METALS-ST5-1/7/07	G7A090154004	Firehouse #10 (roof level)	1/7/07	1723	Metals	6020	STL-SAC	1/9/07	2.1	< 69.6	< 0.70	< 0.70	< 7.0	177	4.8	13.4	9.0	33.4	No	No	
METALS-ST10-1/7/07	G7A090154005	North Side Sidewalk Bridge	1/7/07	1704.1	Metals	6020	STL-SAC	1/9/07	2.1	< 70.4	< 0.70	< 0.70	< 7.0	48.7	4.6	12.4	8.3	28.0	No	No	
METALS-ST11-1/7/07	G7A090154006	90 Trinity Place (roof level)	1/7/07	1714.7	Metals	6020	STL-SAC	1/9/07	2.0	< 70.0	< 0.70	< 0.70	< 7.0	161	4.1	7.7	8.6	28.7	No	No	
METALS-ST12-1/7/07	G7A090154007	110 Greenwich Street (roof level)	1/7/07	1776.2	Metals	6020	STL-SAC	1/9/07	1.8	< 67.6	< 0.68	< 0.68	< 6.8	134	4.2	7.5	8.2	27.0	No	No	
METALS-ST13-1/7/07	G7A090154008	Marriot Hotel, 38th Floor (roof level)	1/7/07	1792.4	Metals	6020	STL-SAC	1/9/07	1.4	< 66.9	< 0.67	< 0.67	< 6.7	214	2.8	4.6	6.4	20.4	No	No	
METALS-ST14-1/7/07	G7A090154009	West Face - South end at corner (scaffolding level)	1/7/07	1798.2	Metals	6020	STL-SAC	1/9/07	1.4	< 66.7	< 0.67	< 0.67	< 6.7	55.7	2.8	4.9	6.9	23.5	No	No	
METALS-ST15-1/7/07	G7A090154010	South Face - East end at corner (scaffolding level)	1/7/07	1818	Metals	6020	STL-SAC	1/9/07	1.4	< 66.0	< 0.66	< 0.66	< 6.6	95.5	3.3	5.4	6.5	23.0	No	No	
METALS-ST16-1/7/07	G7A090154011	East Face - North end at corner (scaffolding level)	1/7/07	1847	Metals	6020	STL-SAC	1/9/07	1.4	< 65.0	< 0.65	< 0.65	< 6.5	38.0	2.9	5.5	6.4	22.5	No	No	
METALS-ST17-1/7/07	G7A090154012	North Face - West end at corner (scaffolding level)	1/7/07	1791.5	Metals	6020	STL-SAC	1/9/07	1.5	< 67.0	< 0.67	< 0.67	< 6.7	44.8	2.7	6.2	7.3	20.5	No	No	