

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	200	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-6/1/09	G9F030201001	Southwest Area (sidewalk bridge leve	6/1/09	1754.8	Metals	6020	STL-SAC	6/3/09	3.3	< 68.4	< 0.68	< 0.68	< 6.8	106	15.3	33.9	7.5	123	No	No	
METALS-ST2-6/1/09	G9F030201002	Southeast Area (sidewalk bridge leve	6/1/09	1766.3	Metals	6020	STL-SAC	6/3/09	3.2	< 67.9	< 0.68	< 0.68	7.4	84.2	13.0	38.6	7.4	122	No	No	
METALS-ST4-6/1/09	G9F030201003	Northwest Area (street-level	6/1/09	1759.2	Metals	6020	STL-SAC	6/3/09	3.4	75.4	< 0.68	< 0.68	8.4	227	32.1	50.9	8.8	491	No	No	
METALS-ST6-6/1/09	G9F030201004	Firehouse #10 (roof level	6/1/09	1759.6	Metals	6020	STL-SAC	6/3/09	2.6	74.9	< 0.68	< 0.68	< 6.8	67.0	11.1	33.2	7.9	101	No	No	
METALS-ST10-6/1/09	G9F030201005	North Side Sidewalk Bridg	6/1/09	1804.9	Metals	6020	STL-SAC	6/3/09	2.9	240	< 0.66	< 0.66	8.3	66.4	14.4	71.9	12.0	211	No	No	
METALS-ST11-6/1/09	G9F030201006	90 Trinity Place (roof level	6/1/09	1773	Metals	6020	STL-SAC	6/3/09	2.1	< 67.7	< 0.68	< 0.68	49.6	8.2	16.1	5.4	54.4	No	No		
METALS-ST12-6/1/09	G9F030201007	110 Greenwich Street (roof level	6/1/09	1793.2	Metals	6020	STL-SAC	6/3/09	2.0	< 66.9	< 0.67	< 0.67	30.5	8.4	15.8	5.7	59.2	No	No		
METALS-ST13-6/1/09	G9F030201008	Mariott Hotel, 38th Floor (roof leve	6/1/09	1747.9	Metals	6020	STL-SAC	6/3/09	2.1	< 68.6	< 0.69	< 0.69	88.0	9.3	17.5	6.1	63.9	No	No		
METALS-ST1-6/2/09	G9F040175001	Southwest Area (sidewalk bridge leve	6/2/09	1711	Metals	6020	STL-SAC	6/4/09	3.8	< 70.1	< 0.70	< 0.70	90.2	14.7	44.9	6.8	147	No	No		
METALS-ST2-6/2/09	G9F040175002	Southeast Area (sidewalk bridge leve	6/2/09	1736.5	Metals	6020	STL-SAC	6/4/09	4.2	89.0	< 0.69	< 0.69	10.0	16.6	64.6	7.7	153	No	No		
METALS-ST4-6/2/09	G9F040175003	Northwest Area (street-level	6/2/09	1776.7	Metals	6020	STL-SAC	6/4/09	3.8	92.8	< 0.68	< 0.68	9.9	25.2	46.5	7.2	516	No	No		
METALS-ST5-6/2/09	G9F040175004	Firehouse #10 (roof level	6/2/09	1735.4	Metals	6020	STL-SAC	6/4/09	2.8	111	< 0.69	< 0.69	8.9	71.8	13.3	43.3	7.6	134	No	No	
METALS-ST10-6/2/09	G9F040175005	North Side Sidewalk Bridg	6/2/09	1804.7	Metals	6020	STL-SAC	6/4/09	3.1	222	< 0.66	< 0.66	8.7	115	13.6	57.2	9.9	177	No	No	
METALS-ST11-6/2/09	G9F040175006	90 Trinity Place (roof level	6/2/09	1739.4	Metals	6020	STL-SAC	6/4/09	2.2	< 69.0	< 0.69	< 0.69	< 6.9	65.8	11.7	18.8	5.5	75.1	No	No	
METALS-ST12-6/2/09	G9F040175007	110 Greenwich Street (roof leve	6/2/09	1777.7	Metals	6020	STL-SAC	6/4/09	2.7	< 67.5	< 0.68	< 0.68	37.2	12.0	22.1	5.8	83.6	No	No		
METALS-ST13-6/2/09	G9F040175008	Mariott Hotel, 38th Floor (roof leve	6/2/09	1741.3	Metals	6020	STL-SAC	6/4/09	2.3	< 68.9	< 0.69	< 0.69	< 6.9	158	11.3	17.5	5.3	69.3	No	No	