

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-7/13/09	G9G150133001	Southwest Area (sidewalk bridge leve	7/13/09	1851.9	Metals	6020	STL-SAC	7/15/09	3.1	125	< 0.65	< 0.65	< 6.5	109	21.0	43.3	7.9	145	No	No	
METALS-ST2-7/13/09	G9G150133002	Southeast Area (sidewalk bridge leve	7/13/09	1823.5	Metals	6020	STL-SAC	7/15/09	3.2	117	< 0.66	< 0.66	7.8	135	19.5	46.0	8.2	142	No	No	
METALS-ST4-7/13/09	G9G150133003	Northwest Area (street-level	7/13/09	1822.7	Metals	6020	STL-SAC	7/15/09	1.6	93.6	< 0.66	< 0.66	< 6.6	88.2	18.5	36.0	6.4	143	No	No	
METALS-ST6-7/13/09	G9G150133004	Firehouse #10 (roof level	7/13/09	1795.7	Metals	6020	STL-SAC	7/15/09	1.8	117	< 0.67	< 0.67	< 6.7	96.0	12.8	37.6	7.7	116	No	No	
METALS-ST10-7/13/09	G9G150133005	North Side Sidewalk Bridgr	7/13/09	1796.1	Metals	6020	STL-SAC	7/15/09	2.1	214	< 0.67	< 0.67	7.7	94.1	16.4	66.1	10.4	235	No	No	
METALS-ST11-7/13/09	G9G150133006	90 Trinity Place (roof level	7/13/09	1828.7	Metals	6020	STL-SAC	7/15/09	1.4	< 65.6	< 0.66	< 0.66	< 6.6	78.1	11.9	15.6	5.6	51.5	No	No	
METALS-ST12-7/13/09	G9G150133007	110 Greenwich Street (roof level	7/13/09	1826.3	Metals	6020	STL-SAC	7/15/09	1.5	< 65.7	< 0.66	< 0.66	< 6.6	70.2	11.2	18.5	6.0	68.0	No	No	
METALS-ST13-7/13/09	G9G150133008	Mariott Hotel, 38th Floor (roof leve	7/13/09	1800.8	Metals	6020	STL-SAC	7/15/09	1.5	< 66.6	< 0.67	< 0.67	< 6.7	471	11.0	15.3	5.4	49.1	No	No	
METALS-ST11-7/14/09	G9G160122001	Southwest Area (sidewalk bridge leve	7/14/09	1822.4	Metals	6020	STL-SAC	7/16/09	1.8	66.9	< 0.66	< 0.66	< 6.6	113	15.0	34.7	4.2	176	No	No	
METALS-ST2-7/14/09	G9G160122002	Southeast Area (sidewalk bridge leve	7/14/09	1804.9	Metals	6020	STL-SAC	7/16/09	2.2	77.5	< 0.66	< 0.66	8.8	102	15.7	45.5	5.3	156	No	No	
METALS-ST4-7/14/09	G9G160122003	Northwest Area (street-level	7/14/09	1843.7	Metals	6020	STL-SAC	7/16/09	4.4	97.1	< 0.65	0.83	7.7	90.8	25.4	46.2	4.8	271	No	No	
METALS-ST5-7/14/09	G9G160122004	Firehouse #10 (roof level	7/14/09	1818.2	Metals	6020	STL-SAC	7/16/09	1.4	164	< 0.66	< 0.66	8.2	88.5	10.4	60.5	7.4	174	No	No	
METALS-ST10-7/14/09	G9G160122005	North Side Sidewalk Bridgr	7/14/09	1836.1	Metals	6020	STL-SAC	7/16/09	< 1.3	163	< 0.65	< 0.65	9.1	72.8	12.6	78.5	7.7	318	No	No	
METALS-ST11-7/14/09	G9G160122006	90 Trinity Place (roof level	7/14/09	1787.7	Metals	6020	STL-SAC	7/16/09	< 1.3	< 67.1	< 0.67	< 0.67	< 6.7	63.5	7.8	20.9	< 3.4	73.3	No	No	
METALS-ST12-7/14/09	G9G160122007	110 Greenwich Street (roof level	7/14/09	1806.2	Metals	6020	STL-SAC	7/16/09	< 1.3	< 66.4	< 0.66	< 0.66	45.9	7.2		18.6	< 3.3	69.6	No	No	
METALS-ST13-7/14/09	G9G160122008	Mariott Hotel, 38th Floor (roof leve	7/14/09	1816.5	Metals	6020	STL-SAC	7/16/09	< 1.3	< 66.1	< 0.66	< 0.66	< 6.6	448	6.9	17.0	< 3.3	70.0	No	No	