

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-8/3/09	G9H050127001	Southwest Area (sidewalk bridge leve	8/3/09	1736	Metals	6020	STL-SAC	8/5/09	6.5	76.3	< 0.69	< 0.69	7.8	106	21.4	57.4	13.4	230	No	No	
METALS-ST2-8/3/09	G9H050127002	Southeast Area (sidewalk bridge leve	8/3/09	1747.8	Metals	6020	STL-SAC	8/5/09	6.5	100.0	< 0.69	< 0.69	10.3	111	18.3	60.9	13.6	173	No	No	
METALS-ST14-8/3/09	G9H050127003	Northwest Area (street-level	8/3/09	1808.9	Metals	6020	STL-SAC	8/5/09	5.7	70.7	< 0.66	< 0.66	9.2	76.4	29.0	58.9	11.6	361	No	No	
METALS-ST5-8/3/09	G9H050127004	Firehouse #10 (roof level	8/3/09	1820.2	Metals	6020	STL-SAC	8/5/09	4.6	72.5	< 0.66	< 0.66	7.2	70.7	11.9	42.1	12.5	105	No	No	
METALS-ST10-8/3/09	G9H050127005	North Side Sidewalk Bridgr	8/3/09	1777.6	Metals	6020	STL-SAC	8/5/09	5.2	153	< 0.68	< 0.68	10.2	260	15.1	77.9	14.5	230	No	No	
METALS-ST11-8/3/09	G9H050127006	90 Trinity Place (roof level	8/3/09	1797	Metals	6020	STL-SAC	8/5/09	3.9	< 66.8	< 0.67	< 0.67	55.3	9.5	17.4	9.7	70.6	No	No		
METALS-ST12-8/3/09	G9H050127007	110 Greenwich Street (roof level	8/3/09	1813.3	Metals	6020	STL-SAC	8/5/09	4.6	< 66.2	< 0.66	< 0.66	62.6	10.2	15.8	9.8	74.6	No	No		
METALS-ST13-8/3/09	G9H050127008	Mariott Hotel, 38th Floor (roof leve	8/3/09	1787.7	Metals	6020	STL-SAC	8/5/09	4.2	< 67.1	< 0.67	< 0.67	80.0	7.9	14.2	61.3	10.4	No	No		
METALS-ST1-8/4/09	G9H060130001	Southwest Area (sidewalk bridge leve	8/4/09	1789.6	Metals	6020	STL-SAC	8/6/09	4.4	< 67.0	< 0.67	< 0.67	268	20.4	30.4	11.5	103	No	No		
METALS-ST2-8/4/09	G9H060130002	Southeast Area (sidewalk bridge leve	8/4/09	1782.9	Metals	6020	STL-SAC	8/6/09	4.2	77.2	< 0.67	< 0.67	9.1	223	15.1	53.9	12.8	170	No	No	
METALS-ST4-8/4/09	G9H060130003	Northwest Area (street-level	8/4/09	1801.1	Metals	6020	STL-SAC	8/6/09	5.6	< 66.6	< 0.67	< 0.67	14.9	306	42.0	57.2	13.8	660	No	No	
METALS-ST5-8/4/09	G9H060130004	Firehouse #10 (roof level	8/4/09	1795.6	Metals	6020	STL-SAC	8/6/09	3.4	< 66.8	< 0.67	< 0.67	66.3	117	12.1	39.0	12.5	157	No	No	
METALS-ST10-8/4/09	G9H060130005	North Side Sidewalk Bridgr	8/4/09	1787	Metals	6020	STL-SAC	8/6/09	3.2	97.9	< 0.67	< 0.67	9.3	313	12.3	67.7	14.6	392	No	No	
METALS-ST100-8/4/09	G9H060130009	Station 10 Field Duplicatn	8/4/09	1793.7	Metals	6020	STL-SAC	8/6/09	3.2	92.0	< 0.67	< 0.67	9.9	145	12.1	60.9	15.6	310	No	No	
METALS-ST11-8/4/09	G9H060130006	90 Trinity Place (roof level	8/4/09	1785.6	Metals	6020	STL-SAC	8/6/09	3.0	< 67.2	< 0.67	< 0.67	6.7	73.8	9.1	14.1	10.2	65.8	No	No	
METALS-ST12-8/4/09	G9H060130007	110 Greenwich Street (roof level	8/4/09	1778.6	Metals	6020	STL-SAC	8/6/09	2.9	< 67.5	< 0.67	< 0.67	86.1	11.9	13.1	10.0	74.2	No	No		
METALS-ST13-8/4/09	G9H060130008	Mariott Hotel, 38th Floor (roof leve	8/4/09	1791.3	Metals	6020	STL-SAC	8/6/09	2.4	< 67.0	< 0.67	< 0.67	6.7	105	8.4	11.0	9.9	45.2	No	No	