

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-8/27/09	G9H290181001	Southwest Area (sidewalk bridge leve	8/27/09	1833.4	Metals	6020	STL-SAC	8/29/09	3.8	99.4	< 0.65	< 0.65	6.7	74.6	25.2	41.2	8.0	258	No	No	
METALS-ST2-8/27/09	G9H290181002	Southeast Area (sidewalk bridge leve	8/27/09	1802.6	Metals	6020	STL-SAC	8/29/09	3.7	97.6	< 0.66	< 0.66	8.9	95.1	20.6	50.2	8.4	224	No	No	
METALS-ST14-8/27/09	G9H290181003	Northwest Area (street-level	8/27/09	1786.5	Metals	6020	STL-SAC	8/29/09	2.7	72.4	< 0.67	< 0.67	74.7	15.3	34.1	7.5	178	No	No		
METALS-ST6-8/27/09	G9H290181004	Firehouse #10 (roof level	8/27/09	1763.8	Metals	6020	STL-SAC	8/29/09	2.1	69.4	< 0.68	< 0.68	69.2	11.2	34.4	7.1	144	No	No		
METALS-ST10-8/27/09	G9H290181005	North Side Sidewalk Bridgr	8/27/09	1801.9	Metals	6020	STL-SAC	8/29/09	2.4	114	< 0.66	< 0.66	7.1	59.1	11.9	53.4	9.0	276	No	No	
METALS-ST11-8/27/09	G9H290181006	90 Trinity Place (roof level	8/27/09	1823.1	Metals	6020	STL-SAC	8/29/09	1.6	< 65.8	< 0.66	< 0.66	< 6.6	54.7	8.8	20.6	5.6	74.3	No	No	
METALS-ST12-8/27/09	G9H290181007	110 Greenwich Street (roof level	8/27/09	1823.9	Metals	6020	STL-SAC	8/29/09	2.0	< 65.8	< 0.66	< 0.66	< 6.6	62.6	9.9	22.4	5.5	105	No	No	
METALS-ST13-8/27/09	G9H290181008	Mariott Hotel, 38th Floor (roof leve	8/27/09	1807.5	Metals	6020	STL-SAC	8/29/09	2.0	< 66.4	< 0.66	< 0.66	< 6.6	121	9.5	17.3	5.8	72.4	No	No	
METALS-ST1-8/28/09	G9H310138001	Southwest Area (sidewalk bridge leve	8/28/09	1786.4	Metals	6020	STL-SAC	8/31/09	3.7	< 67.2	< 0.67	< 0.67	< 6.7	93.9	6.3	19.4	4.0	134	No	No	
METALS-ST2-8/28/09	G9H310138002	Southeast Area (sidewalk bridge leve	8/28/09	1803.9	Metals	6020	STL-SAC	8/31/09	3.1	< 66.5	< 0.66	< 0.66	< 6.6	177	6.5	20.4	4.1	138	No	No	
METALS-ST4-8/28/09	G9H310138003	Northwest Area (street-level	8/28/09	1844.8	Metals	6020	STL-SAC	8/31/09	3.3	< 65.0	< 0.65	< 0.65	< 6.5	213	5.7	23.3	4.7	144	No	No	
METALS-ST5-8/28/09	G9H310138004	Firehouse #10 (roof level	8/28/09	1840.8	Metals	6020	STL-SAC	8/31/09	3.0	< 65.2	< 0.65	< 0.65	< 6.5	85.6	6.3	21.7	4.7	107	No	No	
METALS-ST10-8/28/09	G9H310138005	North Side Sidewalk Bridgr	8/28/09	1847.7	Metals	6020	STL-SAC	8/31/09	2.9	< 64.9	< 0.65	< 0.65	< 6.5	135	5.6	29.6	5.1	341	No	No	
METALS-ST100-8/28/09	G9H310138009	Station 10 Field Duplicatn	8/28/09	1819.7	Metals	6020	STL-SAC	8/31/09	2.8	< 65.9	< 0.66	< 0.66	< 6.6	205	6.8	27.6	5.3	264	No	No	
METALS-ST11-8/28/09	G9H310138006	90 Trinity Place (roof level	8/28/09	1829.1	Metals	6020	STL-SAC	8/31/09	2.0	< 65.6	< 0.66	< 0.66	< 6.6	86.9	4.2	10.0	< 3.3	42.2	No	No	
METALS-ST12-8/28/09	G9H310138007	110 Greenwich Street (roof level	8/28/09	1823.4	Metals	6020	STL-SAC	8/31/09	1.7	< 65.8	< 0.66	< 0.66	< 6.6	51.2	3.7	9.6	< 3.3	47.8	No	No	
METALS-ST13-8/28/09	G9H310138008	Mariott Hotel, 38th Floor (roof leve	8/28/09	1834.5	Metals	6020	STL-SAC	8/31/09	2.0	< 65.4	< 0.65	< 0.65	< 6.5	129	4.0	12.6	< 3.3	49.8	No	No	