

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
									14,000	5,000	200	400	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST11-10/30/08	G8K010214001	Southwest Area (sidewalk bridge level)	10/30/08	1603.5	Metals	6020	STL-SAC	11/1/08	4.3	< 74.8	< 0.75	< 0.75	< 7.5	265	17.4	30.5	8.5	132	No	No		
METALS-ST2-10/30/08	G8K010214002	Southeast Area (sidewalk bridge level)	10/30/08	1793.8	Metals	6020	STL-SAC	11/1/08	3.9	< 66.9	< 0.67	< 0.67	7.4	142	15.8	46.5	8.8	119	No	No		
METALS-ST4-10/30/08	G8K010214003	Northwest Area (street-level)	10/30/08	1779.6	Metals	6020	STL-SAC	11/1/08	3.0	< 67.4	< 0.67	< 0.67	81.1	12.7	22.4	6.3	92.4	No	No			
METALS-ST5-10/30/08	G8K010214004	Firehouse #10 (roof level)	10/30/08	1797.1	Metals	6020	STL-SAC	11/1/08	3.1	< 66.8	< 0.67	< 0.67	6.7	91.3	8.2	32.8	7.5	80.6	No	No		
METALS-ST10-10/30/08	G8K010214005	North Side Sidewalk Bridge	10/30/08	1769.7	Metals	6020	STL-SAC	11/1/08	3.3	< 67.8	< 0.68	< 0.68	305	6.3	37.3	8.0	94.9	No	No			
METALS-ST11-10/30/08	G8K010214006	90 Trinity Place (roof level)	10/30/08	1790.2	Metals	6020	STL-SAC	11/1/08	2.5	< 67.4	< 0.67	< 0.67	76.0	6.8	19.2	6.5	57.2	No	No			
METALS-ST12-10/30/08	G8K010214007	110 Greenwich Street (roof level)	10/30/08	1794.5	Metals	6020	STL-SAC	11/1/08	2.8	< 66.9	< 0.67	< 0.67	6.7	371	9.0	25.1	7.0	81.1	No	No		
METALS-ST13-10/30/08	G8K010214008	Marrion Hotel, 38th Floor (roof level)	10/30/08	1776.2	Metals	6020	STL-SAC	11/1/08	2.3	< 67.6	< 0.68	< 0.68	84.4	4.8	10.3	6.1	35.2	No	No			
METALS-ST14-10/30/08	G8K010214009	West Face - South end at corner (scaffolding level)	10/30/08	1745.8	Metals	6020	STL-SAC	11/1/08	2.7	< 68.7	< 0.68	< 0.68	73.2	6.7	11.5	6.6	51.5	No	No			
METALS-ST15-10/30/08	G8K010214010	South Face - East end at corner (scaffolding level)	10/30/08	1795.5	Metals	6020	STL-SAC	11/1/08	2.8	< 66.8	< 0.67	< 0.67	197	7.4	19.1	6.9	60.3	No	No			
METALS-ST16-10/30/08	G8K010214011	East Face - North end at corner (scaffolding level)	10/30/08	1809.6	Metals	6020	STL-SAC	11/1/08	3.0	< 66.3	< 0.66	< 0.66	323	8.1	26.0	7.3	73.6	No	No			
METALS-ST17-10/30/08	G8K010214012	North Face - West end at corner (scaffolding level)	10/30/08	1783.9	Metals	6020	STL-SAC	11/1/08	2.9	80.9	< 0.67	< 0.67	6.7	248	8.2	21.1	6.6	86.7	No	No		
METALS-ST1-10/31/08	G8K030144001	Southwest Area (sidewalk bridge level)	10/31/08	1769.2	Metals	6020	STL-SAC	11/3/08	5.8	< 67.8	< 0.68	< 0.68	235	19.6	33.4	13.6	133	No	No			
METALS-ST2-10/31/08	G8K030144002	Southeast Area (sidewalk bridge level)	10/31/08	1794.9	Metals	6020	STL-SAC	11/3/08	5.0	< 66.8	< 0.67	< 0.67	198	15.7	45.5	13.3	185	No	No			
METALS-ST4-10/31/08	G8K030144003	Northwest Area (street-level)	10/31/08	1773.9	Metals	6020	STL-SAC	11/3/08	4.5	< 67.6	< 0.68	< 0.68	107	53.1	39.3	12.4	239	No	No			
METALS-ST5-10/31/08	G8K030144004	Firehouse #10 (roof level)	10/31/08	1797.8	Metals	6020	STL-SAC	11/3/08	5.1	67.8	< 0.67	< 0.67	7.6	103	19.3	15.6	116	No	No			
METALS-ST10-10/31/08	G8K030144005	North Side Sidewalk Bridge	10/31/08	1768.8	Metals	6020	STL-SAC	11/3/08	4.5	< 67.8	< 0.68	< 0.68	6.8	370	19.8	63.1	124	No	No			
METALS-ST11-10/31/08	G8K030144006	90 Trinity Place (roof level)	10/31/08	1793.1	Metals	6020	STL-SAC	11/3/08	3.8	< 66.9	< 0.67	< 0.67	75.3	6.7	18.7	11.7	66.7	No	No			
METALS-ST12-10/31/08	G8K030144007	110 Greenwich Street (roof level)	10/31/08	1795.7	Metals	6020	STL-SAC	11/3/08	3.9	< 66.8	< 0.67	< 0.67	87.9	13.9	19.2	11.7	76.6	No	No			
METALS-ST13-10/31/08	G8K030144008	Marrion Hotel, 38th Floor (roof level)	10/31/08	1777.7	Metals	6020	STL-SAC	11/3/08	2.8	< 67.5	< 0.68	< 0.68	63.9	10.8	15.0	10.8	47.4	No	No			
METALS-ST14-10/31/08	G8K030144009	West Face - South end at corner (scaffolding level)	10/31/08	1657	Metals	6020	STL-SAC	11/3/08	3.2	< 72.4	< 0.72	< 0.72	35.8	10.6	15.0	12.3	50.0	No	No			
METALS-ST15-10/31/08	G8K030144010	South Face - East end at corner (scaffolding level)	10/31/08	1705.6	Metals	6020	STL-SAC	11/3/08	3.3	< 70.4	< 0.70	< 0.70	164	11.6	22.6	12.0	83.3	No	No			
METALS-ST16-10/31/08	G8K030144011	East Face - North end at corner (scaffolding level)	10/31/08	1661	Metals	6020	STL-SAC	11/3/08	3.6	< 72.2	< 0.72	< 0.72	265	12.0	25.3	11.2	69.2	No	No			
METALS-ST17-10/31/08	G8K030144012	North Face - West end at corner (scaffolding level)	10/31/08	1696.4	Metals	6020	STL-SAC	11/3/08	3.8	< 70.7	< 0.71	< 0.71	219	13.1	33.2	12.6	82.6	No	No			