

SUMMARY OF AIR SAMPLING RESULTS AT THE MONITORING STATIONS

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality Levels	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
1	ASBESTOS-ST5-8/18/07	Firehouse #10 (roof level)	8/18/07	< 11.00	6	< 0.00087	6	No	No
	ASBESTOS-ST10-8/18/07	North Side Sidewalk Bridge	8/18/07	< 13.00		< 0.00088		No	No
	ASBESTOS-ST12-8/18/07	110 Greenwich Street (roof level)	8/18/07	< 11.00		< 0.00086		No	No
	ASBESTOS-ST13-8/18/07	Marriott Hotel, 38th Floor (roof level)	8/18/07	< 11.00		< 0.00087		No	No
	ASBESTOS-ST1-8/18/07	Southwest Area (sidewalk bridge level)	8/18/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST2-8/18/07	Southeast Area (sidewalk bridge level)	8/18/07	< 13.00		< 0.00082		No	No
2	ASBESTOS-ST4-8/19/07	Northwest Area (street-level)	8/19/07	< 13.00	7	< 0.00087	7	No	No
	ASBESTOS-ST5-8/19/07	Firehouse #10 (roof level)	8/19/07	< 13.00		< 0.00077		No	No
	ASBESTOS-ST10-8/19/07	North Side Sidewalk Bridge	8/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-8/19/07	90 Trinity Place (roof level)	8/19/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST12-8/19/07	110 Greenwich Street (roof level)	8/19/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-8/19/07	Marriott Hotel, 38th Floor (roof level)	8/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST17-8/19/07	North Face - West end at corner (scaffolding level)	8/19/07	< 8.50		< 0.00008		No	No
3	ASBESTOS-ST5-8/20/07	Firehouse #10 (roof level)	8/20/07	< 15.00	6	< 0.00087	6	No	No
	ASBESTOS-ST10-8/20/07	North Side Sidewalk Bridge	8/20/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-8/20/07	90 Trinity Place (roof level)	8/20/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST12-8/20/07	110 Greenwich Street (roof level)	8/20/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-8/20/07	Marriott Hotel, 38th Floor (roof level)	8/20/07	< 15.00		< 0.00089		No	No
	ASBESTOS-ST2-8/20/07	Southeast Area (sidewalk bridge level)	8/20/07	< 9.60		< 0.00008		No	No
4	ASBESTOS-ST5-8/21/07	Firehouse #10 (roof level)	8/21/07	< 13.00	5	< 0.00081	5	No	No
	ASBESTOS-ST10-8/21/07	North Side Sidewalk Bridge	8/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-8/21/07	90 Trinity Place (roof level)	8/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-8/21/07	110 Greenwich Street (roof level)	8/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-8/21/07	Marriott Hotel, 38th Floor (roof level)	8/21/07	< 13.00		< 0.00082		No	No
5	ASBESTOS-ST5-8/22/07	Firehouse #10 (roof level)	8/22/07	15.00	5	< 0.00081	5	No	No
	ASBESTOS-ST10-8/22/07	North Side Sidewalk Bridge	8/22/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST11-8/22/07	90 Trinity Place (roof level)	8/22/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-8/22/07	110 Greenwich Street (roof level)	8/22/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST13-8/22/07	Marriott Hotel, 38th Floor (roof level)	8/22/07	< 15.00		< 0.00081		No	No
6	ASBESTOS-ST4-8/23/07	Northwest Area (street-level)	8/23/07	< 13.00	6	< 0.00088	6	No	No
	ASBESTOS-ST5-8/23/07	Firehouse #10 (roof level)	8/23/07	< 15.00		< 0.00080		No	No
	ASBESTOS-ST10-8/23/07	North Side Sidewalk Bridge	8/23/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST11-8/23/07	90 Trinity Place (roof level)	8/23/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST12-8/23/07	110 Greenwich Street (roof level)	8/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-8/23/07	Marriott Hotel, 38th Floor (roof level)	8/23/07	< 13.00		< 0.00082		No	No
7	ASBESTOS-ST5-8/24/07	Firehouse #10 (roof level)	8/24/07	< 13.00	7	< 0.00081	7	No	No
	ASBESTOS-ST10-8/24/07	North Side Sidewalk Bridge	8/24/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-8/24/07	90 Trinity Place (roof level)	8/24/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-8/24/07	110 Greenwich Street (roof level)	8/24/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST13-8/24/07	Marriott Hotel, 38th Floor (roof level)	8/24/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST100-8/24/07	Station 10 Field Duplicate	8/24/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-8/24/07	Northwest Area (street-level)	8/24/07	< 11.00		< 0.00079		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
8	ASBESTOS-ST5-8/25/07	Firehouse #10 (roof level)	8/25/07	< 13.00	5	< 0.00081	5	No	No
	ASBESTOS-ST10-8/25/07	North Side Sidewalk Bridge	8/25/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-8/25/07	90 Trinity Place (roof level)	8/25/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-8/25/07	110 Greenwich Street (roof level)	8/25/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST13-8/25/07	Marriott Hotel, 38th Floor (roof level)	8/25/07	< 13.00		< 0.00081		No	No
9	ASBESTOS-ST5-8/26/07	Firehouse #10 (roof level)	8/26/07	< 13.00	5	< 0.00082	5	No	No
	ASBESTOS-ST10-8/26/07	North Side Sidewalk Bridge	8/26/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-8/26/07	90 Trinity Place (roof level)	8/26/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST12-8/26/07	110 Greenwich Street (roof level)	8/26/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-8/26/07	Marriott Hotel, 38th Floor (roof level)	8/26/07	< 13.00		< 0.00082		No	No
10	ASBESTOS-ST5-8/27/07	Firehouse #10 (roof level)	8/27/07	< 11.00	5	< 0.00082	5	No	No
	ASBESTOS-ST10-8/27/07	North Side Sidewalk Bridge	8/27/07	< 11.00		< 0.00081		No	No
	ASBESTOS-ST11-8/27/07	90 Trinity Place (roof level)	8/27/07	< 11.00		< 0.00080		No	No
	ASBESTOS-ST12-8/27/07	110 Greenwich Street (roof level)	8/27/07	< 11.00		< 0.00081		No	No
	ASBESTOS-ST13-8/27/07	Marriott Hotel, 38th Floor (roof level)	8/27/07	< 11.00		< 0.00082		No	No
11	ASBESTOS-ST1-8/28/07	Southwest Area (sidewalk bridge level)	8/28/07	< 9.60	12	< 0.00088	12	No	No
	ASBESTOS-ST2-8/28/07	Southeast Area (sidewalk bridge level)	8/28/07	< 9.60		< 0.00089		No	No
	ASBESTOS-ST4-8/28/07	Northwest Area (street-level)	8/28/07	< 9.60		< 0.00089		No	No
	ASBESTOS-ST5-8/28/07	Firehouse #10 (roof level)	8/28/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-8/28/07	North Side Sidewalk Bridge	8/28/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-8/28/07	90 Trinity Place (roof level)	8/28/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST12-8/28/07	110 Greenwich Street (roof level)	8/28/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-8/28/07	Marriott Hotel, 38th Floor (roof level)	8/28/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST14-8/28/07	West Face - South end at corner (scaffolding level)	8/28/07	< 13.00		< 0.00080		No	No
12	ASBESTOS-ST1-8/29/07	Southwest Area (sidewalk bridge level)	8/29/07	< 13.00	12	< 0.00081	12	No	No
	ASBESTOS-ST2-8/29/07	Southeast Area (sidewalk bridge level)	8/29/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-8/29/07	Northwest Area (street-level)	8/29/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-8/29/07	Firehouse #10 (roof level)	8/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-8/29/07	North Side Sidewalk Bridge	8/29/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST11-8/29/07	90 Trinity Place (roof level)	8/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-8/29/07	110 Greenwich Street (roof level)	8/29/07	< 15.00		< 0.00087		No	No
	ASBESTOS-ST13-8/29/07	Marriott Hotel, 38th Floor (roof level)	8/29/07	< 15.00		< 0.00088		No	No
	ASBESTOS-ST14-8/29/07	West Face - South end at corner (scaffolding level)	8/29/07	< 13.00		< 0.00081		No	No
13	ASBESTOS-ST1-8/30/07	Southwest Area (sidewalk bridge level)	8/30/07	< 13.00	12	< 0.00081	12	No	No
	ASBESTOS-ST2-8/30/07	Southeast Area (sidewalk bridge level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-8/30/07	Northwest Area (street-level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-8/30/07	Firehouse #10 (roof level)	8/30/07	< 13.00		< 0.00078		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
14	ASBESTOS-ST10-8/30/07	North Side Sidewalk Bridge	8/30/07	< 13.00	12	< 0.00083	12	No	No
	ASBESTOS-ST11-8/30/07	90 Trinity Place (roof level)	8/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-8/30/07	110 Greenwich Street (roof level)	8/30/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST13-8/30/07	Marriott Hotel, 38th Floor (roof level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-8/30/07	West Face - South end at corner (scaffolding level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-8/30/07	South Face - East end at corner (scaffolding level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-8/30/07	East Face - North end at corner (scaffolding level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-8/30/07	North Face - West end at corner (scaffolding level)	8/30/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST1-8/31/07	Southwest Area (sidewalk bridge level)	8/31/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST2-8/31/07	Southeast Area (sidewalk bridge level)	8/31/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-8/31/07	Northwest Area (street-level)	8/31/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-8/31/07	Firehouse #10 (roof level)	8/31/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-8/31/07	North Side Sidewalk Bridge	8/31/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-8/31/07	90 Trinity Place (roof level)	8/31/07	< 13.00		< 0.00083		No	No
15	ASBESTOS-ST12-8/31/07	110 Greenwich Street (roof level)	8/31/07	< 13.00	< 0.00082	No	No		
	ASBESTOS-ST13-8/31/07	Marriott Hotel, 38th Floor (roof level)	8/31/07	< 13.00	< 0.00082	No	No		
	ASBESTOS-ST14-8/31/07	West Face - South end at corner (scaffolding level)	8/31/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST15-8/31/07	South Face - East end at corner (scaffolding level)	8/31/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST16-8/31/07	East Face - North end at corner (scaffolding level)	8/31/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST17-8/31/07	North Face - West end at corner (scaffolding level)	8/31/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST1-9/1/07	Southwest Area (sidewalk bridge level)	9/1/07	< 13.00	< 0.00083	No	No		
	ASBESTOS-ST2-9/1/07	Southeast Area (sidewalk bridge level)	9/1/07	13.00	< 0.00082	No	No		
	ASBESTOS-ST4-9/1/07	Northwest Area (street-level)	9/1/07	< 13.00	< 0.00082	No	No		
	ASBESTOS-ST5-9/1/07	Firehouse #10 (roof level)	9/1/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST10-9/1/07	North Side Sidewalk Bridge	9/1/07	< 13.00	< 0.00081	No	No		
	ASBESTOS-ST11-9/1/07	90 Trinity Place (roof level)	9/1/07	< 13.00	< 0.00080	No	No		
	ASBESTOS-ST12-9/1/07	110 Greenwich Street (roof level)	9/1/07	< 13.00	< 0.00082	No	No		
	ASBESTOS-ST13-9/1/07	Marriott Hotel, 38th Floor (roof level)	9/1/07	< 13.00	< 0.00082	No	No		
ASBESTOS-ST14-9/1/07	West Face - South end at corner (scaffolding level)	9/1/07	< 13.00	< 0.00081	No	No			
ASBESTOS-ST15-9/1/07	South Face - East end at corner (scaffolding level)	9/1/07	< 13.00	< 0.00081	No	No			
ASBESTOS-ST16-9/1/07	East Face - North end at corner (scaffolding level)	9/1/07	< 13.00	< 0.00081	No	No			
ASBESTOS-ST17-9/1/07	North Face - West end at corner (scaffolding level)	9/1/07	< 13.00	< 0.00082	No	No			
16	030730211-0001	Southwest Area (sidewalk bridge level)	9/2/07	< 13.00	< 0.00081	No	No		
	030730211-0002	Southeast Area (sidewalk bridge level)	9/2/07	< 13.00	< 0.00080	No	No		
	030730211-0003	Northwest Area (street-level)	9/2/07	< 13.00	< 0.00080	No	No		
	030730211-0004	Firehouse #10 (roof level)	9/2/07	< 13.00	< 0.00081	No	No		
	030730211-0005	North Side Sidewalk Bridge	9/2/07	< 13.00	< 0.00081	No	No		
	030730211-0006	90 Trinity Place (roof level)	9/2/07	< 13.00	< 0.00083	No	No		
	030730211-0007	110 Greenwich Street (roof level)	9/2/07	< 13.00	< 0.00081	No	No		
	030730211-0008	Marriott Hotel, 38th Floor (roof level)	9/2/07	< 13.00	< 0.00082	No	No		
	030730211-0009	West Face - South end at corner (scaffolding level)	9/2/07	< 13.00	< 0.00082	No	No		
	030730211-0010	South Face - East end at corner (scaffolding level)	9/2/07	< 13.00	< 0.00083	No	No		
	030730211-0011	East Face - North end at corner (scaffolding level)	9/2/07	< 13.00	< 0.00081	No	No		

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
17	030730211-0012	North Face - West end at corner (scaffolding level)	9/2/07	< 13.00	12	< 0.00081	12	No	No
	030730213-0001	Southwest Area (sidewalk bridge level)	9/3/07	< 15.00		< 0.00081		No	No
	030730213-0002	Southeast Area (sidewalk bridge level)	9/3/07	< 13.00		< 0.00081		No	No
	030730213-0003	Northwest Area (street-level)	9/3/07	< 13.00		< 0.00082		No	No
	030730213-0004	Firehouse #10 (roof level)	9/3/07	< 13.00		< 0.00082		No	No
	030730213-0005	North Side Sidewalk Bridge	9/3/07	< 13.00		< 0.00082		No	No
	030730213-0006	90 Trinity Place (roof level)	9/3/07	< 15.00		< 0.00078		No	No
	030730213-0007	110 Greenwich Street (roof level)	9/3/07	< 15.00		< 0.00081		No	No
	030730213-0008	Marriott Hotel, 38th Floor (roof level)	9/3/07	< 15.00		< 0.00080		No	No
	030730213-0009	West Face - South end at corner (scaffolding level)	9/3/07	< 15.00		< 0.00081		No	No
	030730213-0010	South Face - East end at corner (scaffolding level)	9/3/07	< 13.00		< 0.00082		No	No
	030730213-0011	East Face - North end at corner (scaffolding level)	9/3/07	< 15.00		< 0.00081		No	No
030730213-0012	North Face - West end at corner (scaffolding level)	9/3/07	< 15.00	12	< 0.00081	12	No	No	
18	030730334-0001	Southwest Area (sidewalk bridge level)	9/4/07	26.00		< 0.00082		No	No
	030730334-0002	Southeast Area (sidewalk bridge level)	9/4/07	< 13.00		< 0.00083		No	No
	030730334-0003	Northwest Area (street-level)	9/4/07	< 13.00		< 0.00082		No	No
	030730334-0004	Firehouse #10 (roof level)	9/4/07	< 13.00		< 0.00081		No	No
	030730334-0005	North Side Sidewalk Bridge	9/4/07	< 13.00		< 0.00082		No	No
	030730334-0013	Station 10 Field Duplicate	9/4/07	< 15.00		< 0.00082		No	No
	030730334-0006	90 Trinity Place (roof level)	9/4/07	< 13.00		< 0.00081		No	No
	030730334-0007	110 Greenwich Street (roof level)	9/4/07	< 13.00		< 0.00080		No	No
	030730334-0008	Marriott Hotel, 38th Floor (roof level)	9/4/07	< 13.00		< 0.00081		No	No
	030730334-0009	West Face - South end at corner (scaffolding level)	9/4/07	< 15.00		< 0.00081		No	No
	030730334-0010	South Face - East end at corner (scaffolding level)	9/4/07	< 13.00		< 0.00082		No	No
	030730334-0011	East Face - North end at corner (scaffolding level)	9/4/07	< 13.00		< 0.00081		No	No
030730334-0012	North Face - West end at corner (scaffolding level)	9/4/07	< 13.00	12	< 0.00082	12	No	No	
19	030730438-0001	Southwest Area (sidewalk bridge level)	9/5/07	< 13.00		< 0.00079		No	No
	030730438-0002	Southeast Area (sidewalk bridge level)	9/5/07	< 13.00		< 0.00084		No	No
	030730438-0003	Northwest Area (street-level)	9/5/07	< 13.00		< 0.00081		No	No
	030730438-0004	Firehouse #10 (roof level)	9/5/07	< 13.00		< 0.00078		No	No
	030730438-0005	North Side Sidewalk Bridge	9/5/07	< 13.00		< 0.00078		No	No
	030730438-0006	90 Trinity Place (roof level)	9/5/07	< 13.00		< 0.00082		No	No
	030730438-0007	110 Greenwich Street (roof level)	9/5/07	< 13.00		< 0.00080		No	No
	030730438-0008	Marriott Hotel, 38th Floor (roof level)	9/5/07	< 13.00		< 0.00081		No	No
	030730438-0009	West Face - South end at corner (scaffolding level)	9/5/07	< 13.00		< 0.00081		No	No
	030730438-0010	South Face - East end at corner (scaffolding level)	9/5/07	< 13.00		0.00081		No	No
	030730438-0011	East Face - North end at corner (scaffolding level)	9/5/07	< 13.00		< 0.00081		No	No
	030730438-0012	North Face - West end at corner (scaffolding level)	9/5/07	< 13.00	12	< 0.00080	12	No	No
20	030730575-0001	Southwest Area (sidewalk bridge level)	9/6/07	< 13.00		< 0.00081		No	No
	030730575-0002	Southeast Area (sidewalk bridge level)	9/6/07	< 13.00		< 0.00081		No	No
	030730575-0003	Northwest Area (street-level)	9/6/07	< 13.00		< 0.00080		No	No
	030730575-0004	Firehouse #10 (roof level)	9/6/07	< 13.00		< 0.00082		No	No
	030730575-0005	North Side Sidewalk Bridge	9/6/07	< 13.00		< 0.00080		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	030730575-0006	90 Trinity Place (roof level)	9/6/07	< 13.00		< 0.00083		No	No
	030730575-0007	110 Greenwich Street (roof level)	9/6/07	< 13.00		< 0.00080		No	No
	030730575-0008	Marriott Hotel, 38th Floor (roof level)	9/6/07	< 13.00		< 0.00081		No	No
	030730575-0009	West Face - South end at corner (scaffolding level)	9/6/07	< 13.00		< 0.00081		No	No
	030730575-0010	South Face - East end at corner (scaffolding level)	9/6/07	< 13.00		< 0.00080		No	No
	030730575-0011	East Face - North end at corner (scaffolding level)	9/6/07	< 13.00		< 0.00081		No	No
	030730575-0012	North Face - West end at corner (scaffolding level)	9/6/07	< 13.00	12	< 0.00081	12	No	No
21	030730704-0001	Southwest Area (sidewalk bridge level)	9/7/07	< 13.00		< 0.00080		No	No
	030730704-0002	Southeast Area (sidewalk bridge level)	9/7/07	< 13.00		< 0.00083		No	No
	030730704-0003	Northwest Area (street-level)	9/7/07	< 13.00		< 0.00082		No	No
	030730704-0004	Firehouse #10 (roof level)	9/7/07	< 13.00		< 0.00081		No	No
	030730704-0005	North Side Sidewalk Bridge	9/7/07	< 13.00		< 0.00080		No	No
	030730704-0006	90 Trinity Place (roof level)	9/7/07	< 13.00		< 0.00083		No	No
	030730704-0007	110 Greenwich Street (roof level)	9/7/07	< 13.00		< 0.00081		No	No
	030730704-0008	Marriott Hotel, 38th Floor (roof level)	9/7/07	< 13.00		< 0.00081		No	No
	030730704-0009	West Face - South end at corner (scaffolding level)	9/7/07	< 13.00		< 0.00080		No	No
	030730704-0010	South Face - East end at corner (scaffolding level)	9/7/07	< 13.00		< 0.00080		No	No
	030730704-0011	East Face - North end at corner (scaffolding level)	9/7/07	< 13.00		< 0.00081		No	No
	030730704-0012	North Face - West end at corner (scaffolding level)	9/7/07	< 13.00	12	< 0.00082	12	No	No
22	030730838-0001	Southwest Area (sidewalk bridge level)	9/8/07	< 13.00		< 0.00082		No	No
	030730838-0002	Southeast Area (sidewalk bridge level)	9/8/07	< 13.00		< 0.00082		No	No
	030730838-0003	Northwest Area (street-level)	9/8/07	< 13.00		< 0.00082		No	No
	030730838-0004	Firehouse #10 (roof level)	9/8/07	< 13.00		< 0.00081		No	No
	030730838-0005	North Side Sidewalk Bridge	9/8/07	< 13.00		< 0.00082		No	No
	030730838-0006	90 Trinity Place (roof level)	9/8/07	< 13.00		< 0.00084		No	No
	030730838-0007	110 Greenwich Street (roof level)	9/8/07	< 13.00		< 0.00081		No	No
	030730838-0008	Marriott Hotel, 38th Floor (roof level)	9/8/07	< 15.00		< 0.00081		No	No
	030730838-0009	West Face - South end at corner (scaffolding level)	9/8/07	< 13.00		< 0.00081		No	No
	030730838-0010	South Face - East end at corner (scaffolding level)	9/8/07	< 15.00		< 0.00081		No	No
	030730838-0011	East Face - North end at corner (scaffolding level)	9/8/07	< 13.00		< 0.00082		No	No
	030730838-0012	North Face - West end at corner (scaffolding level)	9/8/07	< 13.00	12	< 0.00082	12	No	No
23	030730842-0001	Southwest Area (sidewalk bridge level)	9/9/07	< 13.00		< 0.00082		No	No
	030730842-0002	Southeast Area (sidewalk bridge level)	9/9/07	< 13.00		< 0.00082		No	No
	030730842-0003	Northwest Area (street-level)	9/9/07	< 13.00		< 0.00082		No	No
	030730842-0004	Firehouse #10 (roof level)	9/9/07	< 13.00		< 0.00081		No	No
	030730842-0005	North Side Sidewalk Bridge	9/9/07	< 13.00		< 0.00082		No	No
	030730842-0006	90 Trinity Place (roof level)	9/9/07	< 13.00		< 0.00084		No	No
	030730842-0007	110 Greenwich Street (roof level)	9/9/07	< 13.00		< 0.00081		No	No
	030730842-0008	Marriott Hotel, 38th Floor (roof level)	9/9/07	< 13.00		< 0.00081		No	No
	030730842-0009	West Face - South end at corner (scaffolding level)	9/9/07	< 13.00		< 0.00081		No	No
	030730842-0010	South Face - East end at corner (scaffolding level)	9/9/07	< 13.00		< 0.00081		No	No
	030730842-0011	East Face - North end at corner (scaffolding level)	9/9/07	< 13.00		< 0.00082		No	No
	030730842-0012	North Face - West end at corner (scaffolding level)	9/9/07	< 13.00	12	< 0.00082	12	No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
24	ASBESTOS-ST1-9/10/07	Southwest Area (sidewalk bridge level)	9/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST2-9/10/07	Southeast Area (sidewalk bridge level)	9/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-9/10/07	Northwest Area (street-level)	9/10/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST11-9/10/07	90 Trinity Place (roof level)	9/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-9/10/07	110 Greenwich Street (roof level)	9/10/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST13-9/10/07	Marriott Hotel, 38th Floor (roof level)	9/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-9/10/07	West Face - South end at corner (scaffolding level)	9/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-9/10/07	South Face - East end at corner (scaffolding level)	9/10/07	< 13.00		< 0.00082		No	No
25	ASBESTOS-ST16-9/10/07	East Face - North end at corner (scaffolding level)	9/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-9/10/04	North Face - West end at corner (scaffolding level)	9/10/07	< 13.00	10	< 0.00080	10	No	No
	ASBESTOS-ST1-9/11/07	Southwest Area (sidewalk bridge level)	9/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST2-9/11/07	Southeast Area (sidewalk bridge level)	9/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-9/11/07	Northwest Area (street-level)	9/11/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST5-9/11/07	Firehouse #10 (roof level)	9/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST10-9/11/07	North Side Sidewalk Bridge	9/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-9/11/07	90 Trinity Place (roof level)	9/11/07	< 13.00		< 0.00087		No	No
26	ASBESTOS-ST12-9/11/07	110 Greenwich Street (roof level)	9/11/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST13-9/11/07	Marriott Hotel, 38th Floor (roof level)	9/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-9/11/07	West Face - South end at corner (scaffolding level)	9/11/07	< 13.00		< 0.00087		No	No
	ASBESTOS-ST15-9/11/07	South Face - East end at corner (scaffolding level)	9/11/07	< 13.00		< 0.00087		No	No
	ASBESTOS-ST16-9/11/07	East Face - North end at corner (scaffolding level)	9/11/07	< 15.00		< 0.00088		No	No
	ASBESTOS-ST17-9/11/07	North Face - West end at corner (scaffolding level)	9/11/07	< 15.00	12	< 0.00087	12	No	No
	ASBESTOS-ST1-9/12/07	Southwest Area (sidewalk bridge level)	9/12/07	< 13.00		< 0.00087		No	No
	ASBESTOS-ST2-9/12/07	Southeast Area (sidewalk bridge level)	9/12/07	< 13.00		< 0.00083		No	No
27	ASBESTOS-ST4-9/12/07	Northwest Area (street-level)	9/12/07	< 13.00		< 0.00086		No	No
	ASBESTOS-ST5-9/12/07	Firehouse #10 (roof level)	9/12/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST10-9/12/07	North Side Sidewalk Bridge	9/12/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST100-9/12/07	Station 10 Field Duplicate	9/12/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST11-9/12/07	90 Trinity Place (roof level)	9/12/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-9/12/07	110 Greenwich Street (roof level)	9/12/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST13-9/12/07	Marriott Hotel, 38th Floor (roof level)	9/12/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-9/12/07	West Face - South end at corner (scaffolding level)	9/12/07	< 11.00		< 0.00087		No	No
27	ASBESTOS-ST15-9/12/07	South Face - East end at corner (scaffolding level)	9/12/07	< 11.00		< 0.00088		No	No
	ASBESTOS-ST16-9/12/07	East Face - North end at corner (scaffolding level)	9/12/07	< 11.00		< 0.00086		No	No
	ASBESTOS-ST17-9/12/07	North Face - West end at corner (scaffolding level)	9/12/07	< 11.00	13	< 0.00089	13	No	No
	ASBESTOS-ST1-9/13/07	Southwest Area (sidewalk bridge level)	9/13/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST2-9/13/07	Southeast Area (sidewalk bridge level)	9/13/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-9/13/07	Northwest Area (street-level)	9/13/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-9/13/07	Firehouse #10 (roof level)	9/13/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST10-9/13/07	North Side Sidewalk Bridge	9/13/07	< 13.00		< 0.00083		No	No
ASBESTOS-ST11-9/13/07	90 Trinity Place (roof level)	9/13/07	< 13.00		< 0.00081		No	No	
ASBESTOS-ST12-9/13/07	110 Greenwich Street (roof level)	9/13/07	< 13.00		< 0.00082		No	No	
ASBESTOS-ST13-9/13/07	Marriott Hotel, 38th Floor (roof level)	9/13/07	< 13.00		< 0.00081		No	No	

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-ST14-9/13/07	West Face - South end at corner (scaffolding level)	9/13/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-9/13/07	South Face - East end at corner (scaffolding level)	9/13/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-9/13/07	East Face - North end at corner (scaffolding level)	9/13/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST17-9/13/07	North Face - West end at corner (scaffolding level)	9/13/07	< 13.00	12	< 0.00082	12	No	No
28	030731398-0001	Southwest Area (sidewalk bridge level)	9/14/07	< 13.00		< 0.00089		No	No
	030731398-0002	Southeast Area (sidewalk bridge level)	9/14/07	< 13.00		< 0.00089		No	No
	030731398-0003	Northwest Area (street-level)	9/14/07	< 15.00		< 0.00088		No	No
	030731398-0004	Firehouse #10 (roof level)	9/14/07	< 15.00		< 0.00088		No	No
	030731398-0005	North Side Sidewalk Bridge	9/14/07	< 15.00		< 0.00089		No	No
	030731398-0006	90 Trinity Place (roof level)	9/14/07	< 13.00		< 0.00083		No	No
	030731398-0007	110 Greenwich Street (roof level)	9/14/07	< 13.00		< 0.00084		No	No
	030731398-0008	Marriott Hotel, 38th Floor (roof level)	9/14/07	< 15.00		< 0.00088		No	No
	030731398-0009	West Face - South end at corner (scaffolding level)	9/14/07	< 15.00		< 0.00087		No	No
	030731398-0010	South Face - East end at corner (scaffolding level)	9/14/07	< 13.00		< 0.00089		No	No
	030731398-0011	East Face - North end at corner (scaffolding level)	9/14/07	< 13.00		< 0.00089		No	No
	030731398-0012	North Face - West end at corner (scaffolding level)	9/14/07	< 13.00	12	< 0.00089	12	No	No
29	030731402-0001	Southwest Area (sidewalk bridge level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0002	Southeast Area (sidewalk bridge level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0003	Northwest Area (street-level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0004	Firehouse #10 (roof level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0005	North Side Sidewalk Bridge	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0006	90 Trinity Place (roof level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0007	110 Greenwich Street (roof level)	9/15/07	< 13.00		< 0.00082		No	No
	030731402-0008	Marriott Hotel, 38th Floor (roof level)	9/15/07	< 13.00		< 0.00081		No	No
	030731402-0009	West Face - South end at corner (scaffolding level)	9/15/07	< 13.00		< 0.00082		No	No
	030731402-0010	South Face - East end at corner (scaffolding level)	9/15/07	< 13.00		< 0.00082		No	No
	030731402-0011	East Face - North end at corner (scaffolding level)	9/15/07	< 13.00		< 0.00083		No	No
	030731402-0012	North Face - West end at corner (scaffolding level)	9/15/07	< 13.00	12	< 0.00081	12	No	No
30	030731399-0001	Southwest Area (sidewalk bridge level)	9/16/07	< 13.00		< 0.00087		No	No
	030731399-0002	Southeast Area (sidewalk bridge level)	9/16/07	< 13.00		< 0.00080		No	No
	030731399-0003	Northwest Area (street-level)	9/16/07	< 13.00		< 0.00082		No	No
	030731399-0004	Firehouse #10 (roof level)	9/16/07	< 13.00		< 0.00082		No	No
	030731399-0005	North Side Sidewalk Bridge	9/16/07	< 13.00		< 0.00084		No	No
	030731399-0006	90 Trinity Place (roof level)	9/16/07	< 13.00		< 0.00078		No	No
	030731399-0007	110 Greenwich Street (roof level)	9/16/07	< 13.00		< 0.00084		No	No
	030731399-0008	Marriott Hotel, 38th Floor (roof level)	9/16/07	< 13.00		< 0.00082		No	No
	030731399-0009	West Face - South end at corner (scaffolding level)	9/16/07	< 13.00		< 0.00083		No	No
	030731399-0010	South Face - East end at corner (scaffolding level)	9/16/07	< 13.00		< 0.00082		No	No
	030731399-0011	East Face - North end at corner (scaffolding level)	9/16/07	< 13.00		< 0.00081		No	No
	030731399-0012	North Face - West end at corner (scaffolding level)	9/16/07	< 13.00	12	< 0.00083	12	No	No
31	030731498-0001	Southwest Area (sidewalk bridge level)	9/17/07	< 13.00		< 0.00084		No	No
	030731498-0002	Southeast Area (sidewalk bridge level)	9/17/07	< 13.00		< 0.00083		No	No
	030731498-0003	Northwest Area (street-level)	9/17/07	< 13.00		< 0.00084		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	030731498-0004	Firehouse #10 (roof level)	9/17/07	< 13.00		< 0.00082		No	No
	030731498-0005	North Side Sidewalk Bridge	9/17/07	< 13.00		< 0.00083		No	No
	030731498-0006	90 Trinity Place (roof level)	9/17/07	< 13.00		< 0.00080		No	No
	030731498-0007	110 Greenwich Street (roof level)	9/17/07	< 13.00		< 0.00078		No	No
	030731498-0008	Marriott Hotel, 38th Floor (roof level)	9/17/07	< 13.00		< 0.00081		No	No
	030731498-0009	West Face - South end at corner (scaffolding level)	9/17/07	< 13.00		< 0.00081		No	No
	030731498-0010	South Face - East end at corner (scaffolding level)	9/17/07	< 13.00		< 0.00083		No	No
	030731498-0011	East Face - North end at corner (scaffolding level)	9/17/07	< 13.00		< 0.00083		No	No
	030731498-0012	North Face - West end at corner (scaffolding level)	9/17/07	< 13.00	12	< 0.00081	12	No	No
32	030731581-0001	Southwest Area (sidewalk bridge level)	9/18/07	< 13.00		< 0.00081		No	No
	030731581-0002	Southeast Area (sidewalk bridge level)	9/18/07	< 13.00		< 0.00081		No	No
	030731581-0003	Northwest Area (street-level)	9/18/07	< 13.00		< 0.00081		No	No
	030731581-0004	Firehouse #10 (roof level)	9/18/07	< 13.00		< 0.00083		No	No
	030731581-0005	North Side Sidewalk Bridge	9/18/07	< 13.00		< 0.00079		No	No
	030731581-0006	90 Trinity Place (roof level)	9/18/07	< 13.00		< 0.00079		No	No
	030731581-0007	110 Greenwich Street (roof level)	9/18/07	< 13.00		< 0.00079		No	No
	030731581-0008	Marriott Hotel, 38th Floor (roof level)	9/18/07	< 13.00		< 0.00087		No	No
	030731581-0009	West Face - South end at corner (scaffolding level)	9/18/07	< 13.00		< 0.00081		No	No
	030731581-0010	South Face - East end at corner (scaffolding level)	9/18/07	< 13.00		< 0.00083		No	No
	030731581-0011	East Face - North end at corner (scaffolding level)	9/18/07	< 13.00		< 0.00081		No	No
	030731581-0012	North Face - West end at corner (scaffolding level)	9/18/07	< 13.00	12	< 0.00082	12	No	No
33	030731711-0001	Southwest Area (sidewalk bridge level)	9/19/07	< 13.00		< 0.00080		No	No
	030731711-0002	Southeast Area (sidewalk bridge level)	9/19/07	< 13.00		< 0.00082		No	No
	030731711-0003	Northwest Area (street-level)	9/19/07	< 13.00		< 0.00083		No	No
	030731711-0004	Firehouse #10 (roof level)	9/19/07	< 13.00		< 0.00081		No	No
	030731711-0005	North Side Sidewalk Bridge	9/19/07	< 13.00		< 0.00083		No	No
	030731711-0006	90 Trinity Place (roof level)	9/19/07	< 13.00		< 0.00083		No	No
	030731711-0007	110 Greenwich Street (roof level)	9/19/07	< 13.00		< 0.00083		No	No
	030731711-0008	Marriott Hotel, 38th Floor (roof level)	9/19/07	< 13.00		< 0.00082		No	No
	030731711-0009	West Face - South end at corner (scaffolding level)	9/19/07	< 13.00		< 0.00081		No	No
	030731711-0010	South Face - East end at corner (scaffolding level)	9/19/07	< 13.00		< 0.00085		No	No
	030731711-0011	East Face - North end at corner (scaffolding level)	9/19/07	< 13.00		< 0.00080		No	No
	030731711-0012	North Face - West end at corner (scaffolding level)	9/19/07	< 13.00	12	< 0.00081	12	No	No
34	030731825-0001	Southwest Area (sidewalk bridge level)	9/20/07	< 13.00		< 0.00081		No	No
	030731825-0002	Southeast Area (sidewalk bridge level)	9/20/07	< 13.00		< 0.00081		No	No
	030731825-0003	Northwest Area (street-level)	9/20/07	< 13.00		< 0.00082		No	No
	030731825-0004	Firehouse #10 (roof level)	9/20/07	< 13.00		< 0.00081		No	No
	030731825-0005	North Side Sidewalk Bridge	9/20/07	< 13.00		< 0.00083		No	No
	030731825-0013	Station 10 Field Duplicate	9/20/07	< 13.00		< 0.00082		No	No
	030731825-0006	90 Trinity Place (roof level)	9/20/07	< 13.00		< 0.00080		No	No
	030731825-0007	110 Greenwich Street (roof level)	9/20/07	< 13.00		< 0.00084		No	No
	030731825-0008	Marriott Hotel, 38th Floor (roof level)	9/20/07	< 13.00		< 0.00080		No	No
	030731825-0009	West Face - South end at corner (scaffolding level)	9/20/07	< 13.00		< 0.00081		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	030731825-0010	South Face - East end at corner (scaffolding level)	9/20/07	< 13.00		< 0.00081		No	No
	030731825-0011	East Face - North end at corner (scaffolding level)	9/20/07	< 13.00		< 0.00082		No	No
	030731825-0012	North Face - West end at corner (scaffolding level)	9/20/07	< 13.00	12	< 0.00081	12	No	No
35	ASBESTOS-ST1-9/21/07	Southwest Area (sidewalk bridge level)	9/21/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST2-9/21/07	Southeast Area (sidewalk bridge level)	9/21/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-9/21/07	Northwest Area (street-level)	9/21/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST5-9/21/07	Firehouse #10 (roof level)	9/21/07	< 13.00		< 0.00069		No	No
	ASBESTOS-ST10-9/21/07	North Side Sidewalk Bridge	9/21/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST11-9/21/07	90 Trinity Place (roof level)	9/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-9/21/07	110 Greenwich Street (roof level)	9/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-9/21/07	Marriott Hotel, 38th Floor (roof level)	9/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-9/21/07	West Face - South end at corner (scaffolding level)	9/21/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST15-9/21/07	South Face - East end at corner (scaffolding level)	9/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-9/21/07	East Face - North end at corner (scaffolding level)	9/21/07	< 13.00		< 0.00081		No	No
	36	ASBESTOS-ST17-9/21/07	North Face - West end at corner (scaffolding level)	9/21/07	< 13.00	12	< 0.00082	12	No
ASBESTOS-ST1-9/22/07		Southwest Area (sidewalk bridge level)	9/22/07	< 13.00		< 0.00081		No	No
ASBESTOS-ST2-9/22/07		Southeast Area (sidewalk bridge level)	9/22/07	< 13.00		< 0.00082		No	No
ASBESTOS-ST4-9/22/07		Northwest Area (street-level)	9/22/07	< 13.00		< 0.00083		No	No
ASBESTOS-ST5-9/22/07		Firehouse #10 (roof level)	9/22/07	< 13.00		< 0.00081		No	No
ASBESTOS-ST10-9/22/07		North Side Sidewalk Bridge	9/22/07	< 13.00		< 0.00081		No	No
ASBESTOS-ST11-9/22/07		90 Trinity Place (roof level)	9/22/07	< 13.00		< 0.00083		No	No
ASBESTOS-ST12-9/22/07		110 Greenwich Street (roof level)	9/22/07	< 13.00		< 0.00083		No	No
ASBESTOS-ST13-9/22/07		Marriott Hotel, 38th Floor (roof level)	9/22/07	< 13.00		< 0.00082		No	No
ASBESTOS-ST14-9/22/07		West Face - South end at corner (scaffolding level)	9/22/07	< 15.00		< 0.00087		No	No
ASBESTOS-ST15-9/22/07		South Face - East end at corner (scaffolding level)	9/22/07	< 15.00		< 0.00088		No	No
ASBESTOS-ST16-9/22/07		East Face - North end at corner (scaffolding level)	9/22/07	< 15.00		< 0.00088		No	No
37	ASBESTOS-ST17-9/22/07	North Face - West end at corner (scaffolding level)	9/22/07	< 15.00	12	< 0.00088	12	No	No
	ASBESTOS-ST1-9/23/07	Southwest Area (sidewalk bridge level)	9/23/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST2-9/23/07	Southeast Area (sidewalk bridge level)	9/23/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-9/23/07	Northwest Area (street-level)	9/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-9/23/07	Firehouse #10 (roof level)	9/23/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST10-9/23/07	North Side Sidewalk Bridge	9/23/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST11-9/23/07	90 Trinity Place (roof level)	9/23/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-9/23/07	110 Greenwich Street (roof level)	9/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-9/23/07	Marriott Hotel, 38th Floor (roof level)	9/23/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-9/23/07	West Face - South end at corner (scaffolding level)	9/23/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-9/23/07	South Face - East end at corner (scaffolding level)	9/23/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-9/23/07	East Face - North end at corner (scaffolding level)	9/23/07	< 13.00		< 0.00081		No	No
38	ASBESTOS-ST17-9/23/07	North Face - West end at corner (scaffolding level)	9/23/07	< 13.00	12	< 0.00081	12	No	No
	ASBESTOS-ST1-9/27/07	Southwest Area (sidewalk bridge level)	9/27/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST2-9/27/07	Southeast Area (sidewalk bridge level)	9/27/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-9/27/07	Northwest Area (street-level)	9/27/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-9/27/07	Firehouse #10 (roof level)	9/27/07	< 13.00		< 0.00082		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA		
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific		
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels		
39	ASBESTOS-ST10-9/27/07	North Side Sidewalk Bridge	9/27/07	< 13.00	12	< 0.00083	12	No	No		
	ASBESTOS-ST11-9/27/07	90 Trinity Place (roof level)	9/27/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST12-9/27/07	110 Greenwich Street (roof level)	9/27/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST13-9/27/07	Marriott Hotel, 38th Floor (roof level)	9/27/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST14-9/27/07	West Face - South end at corner (scaffolding level)	9/27/07	< 13.00		< 0.00083		No	No		
	ASBESTOS-ST15-9/27/07	South Face - East end at corner (scaffolding level)	9/27/07	< 13.00		< 0.00081		No	No		
	ASBESTOS-ST16-9/27/07	East Face - North end at corner (scaffolding level)	9/27/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST17-9/27/07	North Face - West end at corner (scaffolding level)	9/27/07	< 13.00		< 0.00083		No	No		
	ASBESTOS-ST1-9/28/07	Southwest Area (sidewalk bridge level)	9/28/07	< 13.00		12		< 0.00081	12	No	No
	ASBESTOS-ST2-9/28/07	Southeast Area (sidewalk bridge level)	9/28/07	< 13.00				< 0.00082		No	No
	ASBESTOS-ST4-9/28/07	Northwest Area (street-level)	9/28/07	< 13.00				< 0.00082		No	No
	ASBESTOS-ST5-9/28/07	Firehouse #10 (roof level)	9/28/07	< 13.00				< 0.00081		No	No
ASBESTOS-ST10-9/28/07	North Side Sidewalk Bridge	9/28/07	< 13.00	< 0.00082	No		No				
ASBESTOS-ST100-9/28/07	Station 10 Field Duplicate	9/28/07	< 13.00	< 0.00083	No		No				
ASBESTOS-ST12-9/28/07	110 Greenwich Street (roof level)	9/28/07	< 13.00	< 0.00083	No		No				
ASBESTOS-ST13-9/28/07	Marriott Hotel, 38th Floor (roof level)	9/28/07	< 13.00	< 0.00082	No		No				
ASBESTOS-ST14-9/28/07	West Face - South end at corner (scaffolding level)	9/28/07	< 13.00	< 0.00083	No		No				
ASBESTOS-ST15-9/28/07	South Face - East end at corner (scaffolding level)	9/28/07	< 13.00	< 0.00081	No		No				
ASBESTOS-ST16-9/28/07	East Face - North end at corner (scaffolding level)	9/28/07	< 13.00	< 0.00082	No		No				
ASBESTOS-ST17-9/28/07	North Face - West end at corner (scaffolding level)	9/28/07	< 13.00	< 0.00083	No		No				
40	ASBESTOS-ST1-9/29/07	Southwest Area (sidewalk bridge level)	9/29/07	< 13.00	11	< 0.00089	11	No	No		
	ASBESTOS-ST2-9/29/07	Southeast Area (sidewalk bridge level)	9/29/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST4-9/29/07	Northwest Area (street-level)	9/29/07	< 13.00		< 0.00085		No	No		
	ASBESTOS-ST5-9/29/07	Firehouse #10 (roof level)	9/29/07	< 13.00		< 0.00082		No	No		
	ASBESTOS-ST10-9/29/07	North Side Sidewalk Bridge	9/29/07	< 13.00		< 0.00084		No	No		
	ASBESTOS-ST12-9/29/07	110 Greenwich Street (roof level)	9/29/07	< 15.00		< 0.00088		No	No		
	ASBESTOS-ST13-9/29/07	Marriott Hotel, 38th Floor (roof level)	9/29/07	< 13.00		< 0.00089		No	No		
	ASBESTOS-ST14-9/29/07	West Face - South end at corner (scaffolding level)	9/29/07	< 13.00		< 0.00083		No	No		
	ASBESTOS-ST15-9/29/07	South Face - East end at corner (scaffolding level)	9/29/07	< 13.00		< 0.00089		No	No		
	ASBESTOS-ST16-9/29/07	East Face - North end at corner (scaffolding level)	9/29/07	< 15.00		< 0.00089		No	No		
	ASBESTOS-ST17-9/29/07	North Face - West end at corner (scaffolding level)	9/29/07	< 15.00		< 0.00085		No	No		
	41	ASBESTOS-ST1-9/30/07	Southwest Area (sidewalk bridge level)	9/30/07		< 15.00		11	< 0.00087	11	No
ASBESTOS-ST2-9/30/07		Southeast Area (sidewalk bridge level)	9/30/07	< 15.00	< 0.00089	No	No				
ASBESTOS-ST4-9/30/07		Northwest Area (street-level)	9/30/07	< 15.00	< 0.00088	No	No				
ASBESTOS-ST5-9/30/07		Firehouse #10 (roof level)	9/30/07	< 15.00	< 0.00085	No	No				
ASBESTOS-ST10-9/30/07		North Side Sidewalk Bridge	9/30/07	< 15.00	< 0.00087	No	No				
ASBESTOS-ST12-9/30/07		110 Greenwich Street (roof level)	9/30/07	< 15.00	< 0.00088	No	No				
ASBESTOS-ST13-9/30/07		Marriott Hotel, 38th Floor (roof level)	9/30/07	< 15.00	< 0.00088	No	No				
ASBESTOS-ST14-9/30/07		West Face - South end at corner (scaffolding level)	9/30/07	< 13.00	< 0.00089	No	No				
ASBESTOS-ST15-9/30/07		South Face - East end at corner (scaffolding level)	9/30/07	< 13.00	< 0.00089	No	No				
ASBESTOS-ST16-9/30/07		East Face - North end at corner (scaffolding level)	9/30/07	< 15.00	< 0.00088	No	No				
ASBESTOS-ST17-9/30/07		North Face - West end at corner (scaffolding level)	9/30/07	< 13.00	< 0.00085	No	No				
42		ASBESTOS-ST1-10/1/07	Southwest Area (sidewalk bridge level)	10/1/07	< 15.00		< 0.00088				No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
43	ASBESTOS-ST2-10/1/07	Southeast Area (sidewalk bridge level)	10/1/07	< 13.00	12	< 0.00089	12	No	No
	ASBESTOS-ST4-10/1/07	Northwest Area (street-level)	10/1/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST5-10/1/07	Firehouse #10 (roof level)	10/1/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST10-10/1/07	North Side Sidewalk Bridge	10/1/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST11-10/1/07	90 Trinity Place (roof level)	10/1/07	< 13.00		< 0.00089		No	No
	ASBESTOS-ST12-10/1/07	110 Greenwich Street (roof level)	10/1/07	< 15.00		< 0.00089		No	No
	ASBESTOS-ST13-10/1/07	Marriott Hotel, 38th Floor (roof level)	10/1/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST14-10/1/07	West Face - South end at corner (scaffolding level)	10/1/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST15-10/1/07	South Face - East end at corner (scaffolding level)	10/1/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST16-10/1/07	East Face - North end at corner (scaffolding level)	10/1/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST17-10/1/07	North Face - West end at corner (scaffolding level)	10/1/07	< 15.00		< 0.00089		No	No
	43	ASBESTOS-ST1-10/2/07	Southwest Area (sidewalk bridge level)	10/2/07		< 13.00		12	< 0.00061
ASBESTOS-ST2-10/2/07		Southeast Area (sidewalk bridge level)	10/2/07	< 13.00	< 0.00085	No	No		
ASBESTOS-ST4-10/2/07		Northwest Area (street-level)	10/2/07	< 13.00	< 0.00078	No	No		
ASBESTOS-ST5-10/2/07		Firehouse #10 (roof level)	10/2/07	< 13.00	< 0.00080	No	No		
ASBESTOS-ST10-10/2/07		North Side Sidewalk Bridge	10/2/07	< 13.00	< 0.00086	No	No		
ASBESTOS-ST11-10/2/07		90 Trinity Place (roof level)	10/2/07	< 13.00	< 0.00082	No	No		
ASBESTOS-ST12-10/2/07		110 Greenwich Street (roof level)	10/2/07	< 13.00	< 0.00082	No	No		
ASBESTOS-ST13-10/2/07		Marriott Hotel, 38th Floor (roof level)	10/2/07	< 13.00	< 0.00080	No	No		
ASBESTOS-ST14-10/2/07		West Face - South end at corner (scaffolding level)	10/2/07	< 13.00	< 0.00080	No	No		
ASBESTOS-ST15-10/2/07		South Face - East end at corner (scaffolding level)	10/2/07	< 13.00	< 0.00080	No	No		
ASBESTOS-ST16-10/2/07		East Face - North end at corner (scaffolding level)	10/2/07	< 13.00	< 0.00081	No	No		
ASBESTOS-ST17-10/2/07		North Face - West end at corner (scaffolding level)	10/2/07	< 13.00	< 0.00083	No	No		
44	ASBESTOS-ST1-10/3/07	Southwest Area (sidewalk bridge level)	10/3/07	< 13.00	12	< 0.00079	12	No	No
	ASBESTOS-ST2-10/3/07	Southeast Area (sidewalk bridge level)	10/3/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/3/07	Northwest Area (street-level)	10/3/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST5-10/3/07	Firehouse #10 (roof level)	10/3/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST10-10/3/07	North Side Sidewalk Bridge	10/3/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST11-10/3/07	90 Trinity Place (roof level)	10/3/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/3/07	110 Greenwich Street (roof level)	10/3/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/3/07	Marriott Hotel, 38th Floor (roof level)	10/3/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST14-10/3/07	West Face - South end at corner (scaffolding level)	10/3/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-10/3/07	South Face - East end at corner (scaffolding level)	10/3/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/3/07	East Face - North end at corner (scaffolding level)	10/3/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST17-10/3/07	North Face - West end at corner (scaffolding level)	10/3/07	< 13.00		< 0.00079		No	No
45	ASBESTOS-ST1-10/04/07	Southwest Area (sidewalk bridge level)	10/4/07	< 15.00	12	< 0.00085	12	No	No
	ASBESTOS-ST2-10/04/07	Southeast Area (sidewalk bridge level)	10/4/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/04/07	Northwest Area (street-level)	10/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST5-10/04/07	Firehouse #10 (roof level)	10/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-10/04/07	North Side Sidewalk Bridge	10/4/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-10/04/07	90 Trinity Place (roof level)	10/4/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-10/04/07	110 Greenwich Street (roof level)	10/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/04/07	Marriott Hotel, 38th Floor (roof level)	10/4/07	< 13.00		< 0.00080		No	No
ASBESTOS-ST14-10/04/07	West Face - South end at corner (scaffolding level)	10/4/07	< 13.00	< 0.00080	No	No			

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA			
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific			
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels			
46	ASBESTOS-ST15-10/04/07	South Face - East end at corner (scaffolding level)	10/4/07	< 13.00	12	< 0.00082	12	No	No			
	ASBESTOS-ST16-10/04/07	East Face - North end at corner (scaffolding level)	10/4/07	< 13.00		< 0.00081		No	No			
	ASBESTOS-ST17-10/04/07	North Face - West end at corner (scaffolding level)	10/4/07	< 13.00		< 0.00083		No	No			
	ASBESTOS-ST1-10/5/07	Southwest Area (sidewalk bridge level)	10/5/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST2-10/5/07	Southeast Area (sidewalk bridge level)	10/5/07	< 13.00		< 0.00081		No	No			
	ASBESTOS-ST4-10/5/07	Northwest Area (street-level)	10/5/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST5-10/5/07	Firehouse #10 (roof level)	10/5/07	< 13.00		< 0.00078		No	No			
	ASBESTOS-ST10-10/5/07	North Side Sidewalk Bridge	10/5/07	< 13.00		< 0.00083		No	No			
	ASBESTOS-ST11-10/5/07	90 Trinity Place (roof level)	10/5/07	< 13.00		< 0.00080		No	No			
	ASBESTOS-ST12-10/5/07	110 Greenwich Street (roof level)	10/5/07	< 13.00		< 0.00085		No	No			
	ASBESTOS-ST13-10/5/07	Marriott Hotel, 38th Floor (roof level)	10/5/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST14-10/5/07	West Face - South end at corner (scaffolding level)	10/5/07	< 13.00		< 0.00080		No	No			
	ASBESTOS-ST15-10/5/07	South Face - East end at corner (scaffolding level)	10/5/07	< 13.00		< 0.00083		No	No			
	ASBESTOS-ST16-10/5/07	East Face - North end at corner (scaffolding level)	10/5/07	< 13.00		< 0.00081		No	No			
47	ASBESTOS-ST17-10/5/07	North Face - West end at corner (scaffolding level)	10/5/07	< 13.00	12	< 0.00081	12	No	No			
	ASBESTOS-ST1-10/06/07	Southwest Area (sidewalk bridge level)	10/6/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST2-10/06/07	Southeast Area (sidewalk bridge level)	10/6/07	< 13.00		< 0.00081		No	No			
	ASBESTOS-ST4-10/06/07	Northwest Area (street-level)	10/6/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST5-10/06/07	Firehouse #10 (roof level)	10/6/07	< 13.00		< 0.00081		No	No			
	ASBESTOS-ST10-10/06/07	North Side Sidewalk Bridge	10/6/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST11-10/06/07	90 Trinity Place (roof level)	10/6/07	< 13.00		< 0.00084		No	No			
	ASBESTOS-ST12-10/06/07	110 Greenwich Street (roof level)	10/6/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST13-10/06/07	Marriott Hotel, 38th Floor (roof level)	10/6/07	< 13.00		< 0.00081		No	No			
	ASBESTOS-ST14-10/06/07	West Face - South end at corner (scaffolding level)	10/6/07	< 13.00		< 0.00082		No	No			
	ASBESTOS-ST15-10/06/07	South Face - East end at corner (scaffolding level)	10/6/07	< 13.00		< 0.00083		No	No			
	ASBESTOS-ST16-10/06/07	East Face - North end at corner (scaffolding level)	10/6/07	< 13.00		< 0.00085		No	No			
	ASBESTOS-ST17-10/06/07	North Face - West end at corner (scaffolding level)	10/6/07	< 13.00		< 0.00082		No	No			
	48	ASBESTOS-ST1-10/07/07	Southwest Area (sidewalk bridge level)	10/7/07		< 15.00		12	< 0.00079	12	No	No
ASBESTOS-ST2-10/07/07		Southeast Area (sidewalk bridge level)	10/7/07	< 13.00	< 0.00082	No	No					
ASBESTOS-ST4-10/07/07		Northwest Area (street-level)	10/7/07	< 15.00	< 0.00079	No	No					
ASBESTOS-ST5-10/07/07		Firehouse #10 (roof level)	10/7/07	< 15.00	< 0.00080	No	No					
ASBESTOS-ST10-10/07/07		North Side Sidewalk Bridge	10/7/07	< 15.00	< 0.00080	No	No					
ASBESTOS-ST11-10/07/07		90 Trinity Place (roof level)	10/7/07	< 13.00	< 0.00082	No	No					
ASBESTOS-ST12-10/07/07		110 Greenwich Street (roof level)	10/7/07	< 13.00	< 0.00082	No	No					
ASBESTOS-ST13-10/07/07		Marriott Hotel, 38th Floor (roof level)	10/7/07	< 13.00	< 0.00082	No	No					
ASBESTOS-ST14-10/07/07		West Face - South end at corner (scaffolding level)	10/7/07	< 13.00	< 0.00083	No	No					
ASBESTOS-ST15-10/07/07		South Face - East end at corner (scaffolding level)	10/7/07	< 13.00	< 0.00082	No	No					
ASBESTOS-ST16-10/07/07		East Face - North end at corner (scaffolding level)	10/7/07	< 15.00	< 0.00080	No	No					
ASBESTOS-ST17-10/07/07		North Face - West end at corner (scaffolding level)	10/7/07	< 13.00	< 0.00082	No	No					
49		ASBESTOS-ST1-10/8/07	Southwest Area (sidewalk bridge level)	10/8/07	< 13.00		< 0.00074				No	No
		ASBESTOS-ST2-10/8/07	Southeast Area (sidewalk bridge level)	10/8/07	< 13.00		< 0.00082				No	No
	ASBESTOS-ST4-10/8/07	Northwest Area (street-level)	10/8/07	< 13.00	< 0.00082		No	No				
	ASBESTOS-ST5-10/8/07	Firehouse #10 (roof level)	10/8/07	< 13.00	< 0.00085		No	No				
	ASBESTOS-ST10-10/8/07	North Side Sidewalk Bridge	10/8/07	< 13.00	< 0.00081		No	No				

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-ST11-10/8/07	90 Trinity Place (roof level)	10/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/8/07	110 Greenwich Street (roof level)	10/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/8/07	Marriott Hotel, 38th Floor (roof level)	10/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-10/8/07	West Face - South end at corner (scaffolding level)	10/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-10/8/07	South Face - East end at corner (scaffolding level)	10/8/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST16-10/8/07	East Face - North end at corner (scaffolding level)	10/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-10/8/07	North Face - West end at corner (scaffolding level)	10/8/07	< 13.00	12	< 0.00082	12	No	No
50	ASBESTOS-ST1-10/9/07	Southwest Area (sidewalk bridge level)	10/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST2-10/9/07	Southeast Area (sidewalk bridge level)	10/9/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/9/07	Northwest Area (street-level)	10/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/9/07	Firehouse #10 (roof level)	10/9/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST10-10/9/07	North Side Sidewalk Bridge	10/9/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST100-10/9/07	Station 10 Field Duplicate	10/9/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST11-10/9/07	90 Trinity Place (roof level)	10/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST12-10/9/07	110 Greenwich Street (roof level)	10/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-10/9/07	Marriott Hotel, 38th Floor (roof level)	10/9/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST14-10/9/07	West Face - South end at corner (scaffolding level)	10/9/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST15-10/9/07	South Face - East end at corner (scaffolding level)	10/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/9/07	East Face - North end at corner (scaffolding level)	10/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-10/9/07	North Face - West end at corner (scaffolding level)	10/9/07	< 13.00	13	< 0.00082	13	No	No
51	ASBESTOS-ST1-10/10/07	Southwest Area (sidewalk bridge level)	10/10/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST2-10/10/07	Southeast Area (sidewalk bridge level)	10/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/10/07	Northwest Area (street-level)	10/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-10/10/07	Firehouse #10 (roof level)	10/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST10-10/10/07	North Side Sidewalk Bridge	10/10/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-10/10/07	90 Trinity Place (roof level)	10/10/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/10/07	110 Greenwich Street (roof level)	10/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-10/10/07	Marriott Hotel, 38th Floor (roof level)	10/10/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST14-10/10/07	West Face - South end at corner (scaffolding level)	10/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-10/10/07	South Face - East end at corner (scaffolding level)	10/10/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST16-10/10/07	East Face - North end at corner (scaffolding level)	10/10/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-10/10/07	North Face - West end at corner (scaffolding level)	10/10/07	< 13.00	12	< 0.00083	12	No	No
52	ASBESTOS-ST1-10/11/07	Southwest Area (sidewalk bridge level)	10/11/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/11/07	Northwest Area (street-level)	10/11/07	< 13.00		< 0.00088		No	No
	ASBESTOS-ST5-10/11/07	Firehouse #10 (roof level)	10/11/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST10-10/11/07	North Side Sidewalk Bridge	10/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-10/11/07	90 Trinity Place (roof level)	10/11/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/11/07	110 Greenwich Street (roof level)	10/11/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-10/11/07	West Face - South end at corner (scaffolding level)	10/11/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-10/11/07	South Face - East end at corner (scaffolding level)	10/11/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-10/11/07	East Face - North end at corner (scaffolding level)	10/11/07	< 13.00		< 0.00082		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA	
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific	
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels	
53	ASBESTOS-ST17-10/11/07	North Face - West end at corner (scaffolding level)	10/11/07	< 13.00	10	< 0.00084	10	No	No	
	ASBSETOS-ST1-10/12/07	Southwest Area (sidewalk bridge level)	10/12/07	< 13.00		< 0.00082		No	No	
	ASBSETOS-ST2-10/12/07	Southeast Area (sidewalk bridge level)	10/12/07	< 13.00		< 0.00087		No	No	
	ASBSETOS-ST4-10/12/07	Northwest Area (street-level)	10/12/07	< 13.00		< 0.00085		No	No	
	ASBSETOS-ST5-10/12/07	Firehouse #10 (roof level)	10/12/07	< 13.00		< 0.00078		No	No	
	ASBSETOS-ST10-10/12/07	North Side Sidewalk Bridge	10/12/07	< 13.00		< 0.00086		No	No	
	ASBSETOS-ST11-10/12/07	90 Trinity Place (roof level)	10/12/07	< 13.00		< 0.00082		No	No	
	ASBSETOS-ST12-10/12/07	110 Greenwich Street (roof level)	10/12/07	< 13.00		< 0.00082		No	No	
	ASBSETOS-ST13-10/12/07	Marriott Hotel, 38th Floor (roof level)	10/12/07	< 13.00		< 0.00083		No	No	
	ASBSETOS-ST14-10/12/07	West Face - South end at corner (scaffolding level)	10/12/07	< 13.00		< 0.00082		No	No	
	ASBSETOS-ST15-10/12/07	South Face - East end at corner (scaffolding level)	10/12/07	< 13.00		< 0.00082		No	No	
	ASBSETOS-ST16-10/12/07	East Face - North end at corner (scaffolding level)	10/12/07	< 13.00		< 0.00081		No	No	
	ASBSETOS-ST17-10/12/07	North Face - West end at corner (scaffolding level)	10/12/07	< 13.00	12	< 0.00083	12	No	No	
54	ASBESTOS-ST1-10/13/07	Southwest Area (sidewalk bridge level)	10/13/07	< 13.00		< 0.00084		No	No	
	ASBESTOS-ST2-10/13/07	Southeast Area (sidewalk bridge level)	10/13/07	< 13.00		< 0.00083		No	No	
	ASBESTOS-ST4-10/13/07	Northwest Area (street-level)	10/13/07	< 13.00		< 0.00085		No	No	
	ASBESTOS-ST5-10/13/07	Firehouse #10 (roof level)	10/13/07	< 13.00		< 0.00081		No	No	
	ASBESTOS-ST10-10/13/07	North Side Sidewalk Bridge	10/13/07	< 13.00		< 0.00081		No	No	
	ASBESTOS-ST11-10/13/07	90 Trinity Place (roof level)	10/13/07	< 13.00		< 0.00079		No	No	
	ASBESTOS-ST12-10/13/07	110 Greenwich Street (roof level)	10/13/07	< 13.00		< 0.00081		No	No	
	ASBESTOS-ST13-10/13/07	Marriott Hotel, 38th Floor (roof level)	10/13/07	< 13.00		< 0.00082		No	No	
	ASBESTOS-ST14-10/13/07	West Face - South end at corner (scaffolding level)	10/13/07	< 13.00		< 0.00078		No	No	
	ASBESTOS-ST15-10/13/07	South Face - East end at corner (scaffolding level)	10/13/07	< 13.00		< 0.00089		No	No	
	ASBESTOS-ST16-10/13/07	East Face - North end at corner (scaffolding level)	10/13/07	< 13.00		< 0.00081		No	No	
	ASBESTOS-ST17-10/13/07	North Face - West end at corner (scaffolding level)	10/13/07	< 13.00	12	< 0.00080	12	No	No	
	55	ASBSETOS-ST1-10/14/07	Southwest Area (sidewalk bridge level)	10/14/07	< 13.00		< 0.00080		No	No
ASBSETOS-ST2-10/14/07		Southeast Area (sidewalk bridge level)	10/14/07	< 13.00		< 0.00074		No	No	
ASBSETOS-ST4-10/14/07		Northwest Area (street-level)	10/14/07	< 13.00		< 0.00080		No	No	
ASBSETOS-ST5-10/14/07		Firehouse #10 (roof level)	10/14/07	< 13.00		< 0.00084		No	No	
ASBSETOS-ST10-10/14/07		North Side Sidewalk Bridge	10/14/07	< 13.00		< 0.00077		No	No	
ASBSETOS-ST11-10/14/07		90 Trinity Place (roof level)	10/14/07	< 13.00		< 0.00085		No	No	
ASBSETOS-ST12-10/14/07		110 Greenwich Street (roof level)	10/14/07	< 13.00		< 0.00082		No	No	
ASBSETOS-ST13-10/14/07		Marriott Hotel, 38th Floor (roof level)	10/14/07	< 13.00		< 0.00081		No	No	
ASBSETOS-ST14-10/14/07		West Face - South end at corner (scaffolding level)	10/14/07	< 13.00		< 0.00082		No	No	
ASBSETOS-ST15-10/14/07		South Face - East end at corner (scaffolding level)	10/14/07	< 13.00		< 0.00082		No	No	
ASBSETOS-ST17-10/14/07		North Face - West end at corner (scaffolding level)	10/14/07	< 13.00	11	< 0.00082	11	No	No	
56		ASBESTOS-ST1-10/15/07	Southwest Area (sidewalk bridge level)	10/15/07	< 13.00		< 0.00086		No	No
		ASBESTOS-ST2-10/15/07	Southeast Area (sidewalk bridge level)	10/15/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/15/07	Northwest Area (street-level)	10/15/07	< 13.00		< 0.00077		No	No	
	ASBESTOS-ST5-10/15/07	Firehouse #10 (roof level)	10/15/07	< 13.00		< 0.00084		No	No	
	ASBESTOS-ST10-10/15/07	North Side Sidewalk Bridge	10/15/07	< 13.00		< 0.00079		No	No	

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-ST11-10/15/07	90 Trinity Place (roof level)	10/15/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-10/15/07	110 Greenwich Street (roof level)	10/15/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST13-10/15/07	Marriott Hotel, 38th Floor (roof level)	10/15/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-10/15/07	West Face - South end at corner (scaffolding level)	10/15/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-10/15/07	South Face - East end at corner (scaffolding level)	10/15/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST17-10/15/07	North Face - West end at corner (scaffolding level)	10/15/07	< 13.00	11	< 0.00081	11	No	No
57	ASBESTOS-ST1-10/16/07	Southwest Area (sidewalk bridge level)	10/16/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST2-10/16/07	Southeast Area (sidewalk bridge level)	10/16/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST4-10/16/07	Northwest Area (street-level)	10/16/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST5-10/16/07	Firehouse #10 (roof level)	10/16/07	< 15.00		< 0.00080		No	No
	ASBESTOS-ST10-10/16/07	North Side Sidewalk Bridge	10/16/07	< 15.00		< 0.00085		No	No
	ASBESTOS-ST11-10/16/07	90 Trinity Place (roof level)	10/16/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-10/16/07	110 Greenwich Street (roof level)	10/16/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/16/07	Marriott Hotel, 38th Floor (roof level)	10/16/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-10/16/07	West Face - South end at corner (scaffolding level)	10/16/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-10/16/07	South Face - East end at corner (scaffolding level)	10/16/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/16/07	East Face - North end at corner (scaffolding level)	10/16/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST17-10/16/07	North Face - West end at corner (scaffolding level)	10/16/07	< 13.00	12	< 0.00082	12	No	No
58	ASBESTOS-ST1-10/17/07	Southwest Area (sidewalk bridge level)	10/17/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST2-10/17/07	Southeast Area (sidewalk bridge level)	10/17/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-10/17/07	Northwest Area (street-level)	10/17/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST5-10/17/07	Firehouse #10 (roof level)	10/17/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST10-10/17/07	North Side Sidewalk Bridge	10/17/07	< 13.00		< 0.00076		No	No
	ASBESTOS-ST100-10/17/07	Station 10 Field Duplicate	10/17/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST11-10/17/07	90 Trinity Place (roof level)	10/17/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST12-10/17/07	110 Greenwich Street (roof level)	10/17/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/17/07	Marriott Hotel, 38th Floor (roof level)	10/17/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST14-10/17/07	West Face - South end at corner (scaffolding level)	10/17/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-10/17/07	South Face - East end at corner (scaffolding level)	10/17/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/17/07	East Face - North end at corner (scaffolding level)	10/17/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST17-10/17/07	North Face - West end at corner (scaffolding level)	10/17/07	< 13.00	13	< 0.00082	13	No	No
59	ASBESTOS-S11-10/18/07	Southwest Area (sidewalk bridge level)	10/18/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S12-10/18/07	Southeast Area (sidewalk bridge level)	10/18/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S14-10/18/07	Northwest Area (street-level)	10/18/07	< 13.00		< 0.00078		No	No
	ASBESTOS-S15-10/18/07	Firehouse #10 (roof level)	10/18/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S110-10/18/07	North Side Sidewalk Bridge	10/18/07	< 13.00		< 0.00077		No	No
	ASBESTOS-S111-10/18/07	90 Trinity Place (roof level)	10/18/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S112-10/18/07	110 Greenwich Street (roof level)	10/18/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S113-10/18/07	Marriott Hotel, 38th Floor (roof level)	10/18/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S114-10/18/07	West Face - South end at corner (scaffolding level)	10/18/07	< 13.00		< 0.00078		No	No
	ASBESTOS-S115-10/18/07	South Face - East end at corner (scaffolding level)	10/18/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S116-10/18/07	East Face - North end at corner (scaffolding level)	10/18/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S117-10/18/07	North Face - West end at corner (scaffolding level)	10/18/07	< 13.00	12	< 0.00084	12	No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCME Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
60	ASBESTOS-ST1-10/19/07	Southwest Area (sidewalk bridge level)	10/19/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST2-10/19/07	Southeast Area (sidewalk bridge level)	10/19/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST4-10/19/07	Northwest Area (street-level)	10/19/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST5-10/19/07	Firehouse #10 (roof level)	10/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-10/19/07	North Side Sidewalk Bridge	10/19/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST11-10/19/07	90 Trinity Place (roof level)	10/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/19/07	110 Greenwich Street (roof level)	10/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/19/07	Marriott Hotel, 38th Floor (roof level)	10/19/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST15-10/19/07	South Face - East end at corner (scaffolding level)	10/19/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/19/07	East Face - North end at corner (scaffolding level)	10/19/07	< 13.00	10	< 0.00082	10	No	No
61	ASBESTOS-ST1-10/20/07	Southwest Area (sidewalk bridge level)	10/20/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST2-10/20/07	Southeast Area (sidewalk bridge level)	10/20/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-10/20/07	Northwest Area (street-level)	10/20/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/20/07	Firehouse #10 (roof level)	10/20/07	< 15.00		< 0.00080		No	No
	ASBESTOS-ST10-10/20/07	North Side Sidewalk Bridge	10/20/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-10/20/07	90 Trinity Place (roof level)	10/20/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/20/07	110 Greenwich Street (roof level)	10/20/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/20/07	Marriott Hotel, 38th Floor (roof level)	10/20/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-10/20/07	West Face - South end at corner (scaffolding level)	10/20/07	< 13.00		< 0.00088		No	No
	ASBESTOS-ST15-10/20/07	South Face - East end at corner (scaffolding level)	10/20/07	< 13.00		< 0.00082		No	No
62	ASBESTOS-ST16-10/20/07	East Face - North end at corner (scaffolding level)	10/20/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-10/20/07	North Face - West end at corner (scaffolding level)	10/20/07	< 13.00	12	< 0.00082	12	No	No
	ASBESTOS-ST1-10/21/07	Southwest Area (sidewalk bridge level)	10/21/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST2-10/21/07	Southeast Area (sidewalk bridge level)	10/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-10/21/07	Northwest Area (street-level)	10/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/21/07	Firehouse #10 (roof level)	10/21/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST10-10/21/07	North Side Sidewalk Bridge	10/21/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-10/21/07	90 Trinity Place (roof level)	10/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/21/07	110 Greenwich Street (roof level)	10/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-10/21/07	Marriott Hotel, 38th Floor (roof level)	10/21/07	< 13.00		< 0.00084		No	No
63	ASBESTOS-ST14-10/21/07	West Face - South end at corner (scaffolding level)	10/21/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-10/21/07	South Face - East end at corner (scaffolding level)	10/21/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST16-10/21/07	East Face - North end at corner (scaffolding level)	10/21/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST17-10/21/07	North Face - West end at corner (scaffolding level)	10/21/07	< 13.00	12	< 0.00081	12	No	No
	ASBESTOS-ST1-10/22/07	Southwest Area (sidewalk bridge level)	10/22/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST2-10/22/07	Southeast Area (sidewalk bridge level)	10/22/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-10/22/07	Northwest Area (street-level)	10/22/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/22/07	Firehouse #10 (roof level)	10/22/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST10-10/22/07	North Side Sidewalk Bridge	10/22/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-10/22/07	90 Trinity Place (roof level)	10/22/07	< 13.00		< 0.00079		No	No
64	ASBESTOS-ST12-10/22/07	110 Greenwich Street (roof level)	10/22/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST13-10/22/07	Marriott Hotel, 38th Floor (roof level)	10/22/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-10/22/07	West Face - South end at corner (scaffolding level)	10/22/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST15-10/22/07	South Face - East end at corner (scaffolding level)	10/22/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-10/22/07	East Face - North end at corner (scaffolding level)	10/22/07	< 13.00		< 0.00077		No	No
	ASBESTOS-ST17-10/22/07	North Face - West end at corner (scaffolding level)	10/22/07	< 13.00	12	< 0.00081	12	No	No
	ASBESTOS-ST1-10/23/07	Southwest Area (sidewalk bridge level)	10/23/07	< 13.00		< 0.00089		No	No
	ASBESTOS-ST2-10/23/07	Southeast Area (sidewalk bridge level)	10/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/23/07	Northwest Area (street-level)	10/23/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/23/07	Firehouse #10 (roof level)	10/23/07	< 15.00		< 0.00085		No	No
ASBESTOS-ST10-10/23/07	North Side Sidewalk Bridge	10/23/07	< 13.00		< 0.00082		No	No	

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCME Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-S11-10/23/07	90 Trinity Place (roof level)	10/23/07	< 15.00		< 0.00089		No	No
	ASBESTOS-S12-10/23/07	110 Greenwich Street (roof level)	10/23/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S13-10/23/07	Marriott Hotel, 38th Floor (roof level)	10/23/07	< 15.00		< 0.00088		No	No
	ASBESTOS-S14-10/23/07	West Face - South end at corner (scaffolding level)	10/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S15-10/23/07	South Face - East end at corner (scaffolding level)	10/23/07	< 13.00		< 0.00085		No	No
	ASBESTOS-S16-10/23/07	East Face - North end at corner (scaffolding level)	10/23/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S17-10/23/07	North Face - West end at corner (scaffolding level)	10/23/07	< 13.00	12	< 0.00085	12	No	No
65	ASBESTOS-S11-10/24/07	Southwest Area (sidewalk bridge level)	10/24/07	< 13.00		< 0.00089		No	No
	ASBESTOS-S12-10/24/07	Southeast Area (sidewalk bridge level)	10/24/07	< 13.00		< 0.00089		No	No
	ASBESTOS-ST4-10/24/07	Northwest Area (street-level)	10/24/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-10/24/07	Firehouse #10 (roof level)	10/24/07	< 13.00		< 0.00089		No	No
	ASBESTOS-ST10-10/24/07	North Side Sidewalk Bridge	10/24/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-10/24/07	90 Trinity Place (roof level)	10/24/07	< 13.00		< 0.00088		No	No
	ASBESTOS-S12-10/24/07	110 Greenwich Street (roof level)	10/24/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S13-10/24/07	Marriott Hotel, 38th Floor (roof level)	10/24/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S14-10/24/07	West Face - South end at corner (scaffolding level)	10/24/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S15-10/24/07	South Face - East end at corner (scaffolding level)	10/24/07	< 13.00		< 0.00084		No	No
	ASBESTOS-S16-10/24/07	East Face - North end at corner (scaffolding level)	10/24/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S17-10/24/07	North Face - West end at corner (scaffolding level)	10/24/07	< 13.00	12	< 0.00087	12	No	No
66	ASBESTOS-S11-10/25/07	Southwest Area (sidewalk bridge level)	10/25/07	< 13.00		< 0.00084		No	No
	ASBESTOS-S12-10/25/07	Southeast Area (sidewalk bridge level)	10/25/07	< 13.00		< 0.00080		No	No
	ASBESTOS-S14-10/25/07	Northwest Area (street-level)	10/25/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S15-10/25/07	Firehouse #10 (roof level)	10/25/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-10/25/07	North Side Sidewalk Bridge	10/25/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST100-10/25/07	Station 10 Field Duplicate	10/25/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S11-10/25/07	90 Trinity Place (roof level)	10/25/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S12-10/25/07	110 Greenwich Street (roof level)	10/25/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S13-10/25/07	Marriott Hotel, 38th Floor (roof level)	10/25/07	< 13.00		< 0.00079		No	No
	ASBESTOS-S14-10/25/07	West Face - South end at corner (scaffolding level)	10/25/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S15-10/25/07	South Face - East end at corner (scaffolding level)	10/25/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S16-10/25/07	East Face - North end at corner (scaffolding level)	10/25/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S17-10/25/07	North Face - West end at corner (scaffolding level)	10/25/07	< 13.00	13	< 0.00083	13	No	No
67	ASBESTOS-S11-10/26/07	Southwest Area (sidewalk bridge level)	10/26/07	< 13.00		< 0.00082		No	No
	ASBESTOS-S12-10/26/07	Southeast Area (sidewalk bridge level)	10/26/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-10/26/07	Northwest Area (street-level)	10/26/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST5-10/26/07	Firehouse #10 (roof level)	10/26/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST10-10/26/07	North Side Sidewalk Bridge	10/26/07	< 13.00		< 0.00081		No	No
	ASBESTOS-S11-10/26/07	90 Trinity Place (roof level)	10/26/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S12-10/26/07	110 Greenwich Street (roof level)	10/26/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S13-10/26/07	Marriott Hotel, 38th Floor (roof level)	10/26/07	< 13.00		< 0.00080		No	No
	ASBESTOS-S14-10/26/07	West Face - South end at corner (scaffolding level)	10/26/07	< 13.00		< 0.00083		No	No
	ASBESTOS-S15-10/26/07	South Face - East end at corner (scaffolding level)	10/26/07	< 13.00		< 0.00079		No	No
	ASBESTOS-S16-10/26/07	East Face - North end at corner (scaffolding level)	10/26/07	< 13.00		< 0.00080		No	No
	ASBESTOS-S17-10/26/07	North Face - West end at corner (scaffolding level)	10/26/07	< 13.00	12	< 0.00081	12	No	No
68	ABSESTOS-S11-10/27/07	Southwest Area (sidewalk bridge level)	10/27/07	< 13.00		< 0.00081		No	No
	ABSESTOS-S12-10/27/07	Southeast Area (sidewalk bridge level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-S14-10/27/07	Northwest Area (street-level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-S15-10/27/07	Firehouse #10 (roof level)	10/27/07	< 13.00		< 0.00081		No	No
	ABSESTOS-ST10-10/27/07	North Side Sidewalk Bridge	10/27/07	< 13.00		< 0.00081		No	No
	ABSESTOS-S11-10/27/07	90 Trinity Place (roof level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-S12-10/27/07	110 Greenwich Street (roof level)	10/27/07	< 13.00		< 0.00082		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
69	ABSESTOS-ST13-10/27/07	Marriott Hotel, 38th Floor (roof level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-ST14-10/27/07	West Face - South end at corner (scaffolding level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-ST15-10/27/07	South Face - East end at corner (scaffolding level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-ST16-10/27/07	East Face - North end at corner (scaffolding level)	10/27/07	< 13.00		< 0.00082		No	No
	ABSESTOS-ST17-10/27/07	North Face - West end at corner (scaffolding level)	10/27/07	< 13.00	12	< 0.00082	12	No	No
	ASBESTOS-ST11-10/28/07	Southwest Area (sidewalk bridge level)	10/28/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-10/28/07	Southeast Area (sidewalk bridge level)	10/28/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-10/28/07	Northwest Area (street-level)	10/28/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-10/28/07	Firehouse #10 (roof level)	10/28/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST10-10/28/07	North Side Sidewalk Bridge	10/28/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-10/28/07	90 Trinity Place (roof level)	10/28/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/28/07	110 Greenwich Street (roof level)	10/28/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-10/28/07	Marriott Hotel, 38th Floor (roof level)	10/28/07	< 13.00		< 0.00088		No	No
	ASBESTOS-ST14-10/28/07	West Face - South end at corner (scaffolding level)	10/28/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-10/28/07	South Face - East end at corner (scaffolding level)	10/28/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST16-10/28/07	East Face - North end at corner (scaffolding level)	10/28/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-10/28/07	North Face - West end at corner (scaffolding level)	10/28/07	< 13.00	12	< 0.00082	12	No	No
70	ASBESTOS-ST1-10/29/07	Southwest Area (sidewalk bridge level)	10/29/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST2-10/29/07	Southeast Area (sidewalk bridge level)	10/29/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-10/29/07	Northwest Area (street-level)	10/29/07	< 15.00		< 0.00088		No	No
	ASBESTOS-ST5-10/29/07	Firehouse #10 (roof level)	10/29/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST10-10/29/07	North Side Sidewalk Bridge	10/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-10/29/07	90 Trinity Place (roof level)	10/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/29/07	110 Greenwich Street (roof level)	10/29/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-10/29/07	Marriott Hotel, 38th Floor (roof level)	10/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-10/29/07	West Face - South end at corner (scaffolding level)	10/29/07	< 13.00		< 0.00078		No	No
	ASBESTOS-ST15-10/29/07	South Face - East end at corner (scaffolding level)	10/29/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-10/29/07	East Face - North end at corner (scaffolding level)	10/29/07	< 13.00		< 0.00082		No	No
ASBESTOS-ST17-10/29/07	North Face - West end at corner (scaffolding level)	10/29/07	< 13.00	12	< 0.00083	12	No	No	
71	ASBESTOS-ST1-10/30/07	Southwest Area (sidewalk bridge level)	10/30/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST2-10/30/07	Southeast Area (sidewalk bridge level)	10/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-10/30/07	Northwest Area (street-level)	10/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST5-10/30/07	Firehouse #10 (roof level)	10/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-10/30/07	North Side Sidewalk Bridge	10/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-10/30/07	90 Trinity Place (roof level)	10/30/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-10/30/07	110 Greenwich Street (roof level)	10/30/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST13-10/30/07	Marriott Hotel, 38th Floor (roof level)	10/30/07	< 15.00		< 0.00085		No	No
	ASBESTOS-ST14-10/30/07	West Face - South end at corner (scaffolding level)	10/30/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST15-10/30/07	South Face - East end at corner (scaffolding level)	10/30/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST16-10/30/07	East Face - North end at corner (scaffolding level)	10/30/07	< 15.00		< 0.00081		No	No
ASBESTOS-ST17-10/30/07	North Face - West end at corner (scaffolding level)	10/30/07	< 15.00	12	< 0.00080	12	No	No	
72	ASBESTOS-ST1-11/1/07	Southwest Area (sidewalk bridge level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST2-11/1/07	Southeast Area (sidewalk bridge level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-11/1/07	Northwest Area (street-level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST5-11/1/07	Firehouse #10 (roof level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-11/1/07	North Side Sidewalk Bridge	11/1/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST11-11/1/07	90 Trinity Place (roof level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/1/07	110 Greenwich Street (roof level)	11/1/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-11/1/07	Marriott Hotel, 38th Floor (roof level)	11/1/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST14-11/1/07	West Face - South end at corner (scaffolding level)	11/1/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/1/07	South Face - East end at corner (scaffolding level)	11/1/07	< 13.00		< 0.00083		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-ST16-11/1/07	East Face - North end at corner (scaffolding level)	11/1/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-11/1/07	North Face - West end at corner (scaffolding level)	11/1/07	< 13.00	12	< 0.00083	12	No	No
73	ASBESTOS-ST11-11/2/07	Southwest Area (sidewalk bridge level)	11/2/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-11/2/07	Southeast Area (sidewalk bridge level)	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/2/07	Firehouse #10 (roof level)	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-11/2/07	North Side Sidewalk Bridge	11/2/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST100-11/2/07	Station 10 Field Duplicate	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST111-11/2/07	90 Trinity Place (roof level)	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/2/07	110 Greenwich Street (roof level)	11/2/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-11/2/07	Marriott Hotel, 38th Floor (roof level)	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-11/2/07	West Face - South end at corner (scaffolding level)	11/2/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/2/07	South Face - East end at corner (scaffolding level)	11/2/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-11/2/07	East Face - North end at corner (scaffolding level)	11/2/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-11/2/07	North Face - West end at corner (scaffolding level)	11/2/07	< 13.00	12	< 0.00081	12	No	No
75	ASBESTOS-ST11-11/3/07	Southwest Area (sidewalk bridge level)	11/3/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST12-11/3/07	Southeast Area (sidewalk bridge level)	11/3/07	< 15.00		< 0.00082		No	No
	ASBESTOS-ST14-11/3/07	Northwest Area (street-level)	11/3/07	< 15.00		< 0.00087		No	No
	ASBESTOS-ST15-11/3/07	Firehouse #10 (roof level)	11/3/07	< 15.00		< 0.00082		No	No
	ASBESTOS-ST10-11/3/07	North Side Sidewalk Bridge	11/3/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST111-11/3/07	90 Trinity Place (roof level)	11/3/07	< 15.00		< 0.00085		No	No
	ASBESTOS-ST12-11/3/07	110 Greenwich Street (roof level)	11/3/07	< 15.00		< 0.00085		No	No
	ASBESTOS-ST13-11/3/07	Marriott Hotel, 38th Floor (roof level)	11/3/07	< 15.00		< 0.00084		No	No
	ASBESTOS-ST14-11/3/07	West Face - South end at corner (scaffolding level)	11/3/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-11/3/07	South Face - East end at corner (scaffolding level)	11/3/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST16-11/3/07	East Face - North end at corner (scaffolding level)	11/3/07	< 15.00		< 0.00085		No	No
	ASBESTOS-ST17-11/3/07	North Face - West end at corner (scaffolding level)	11/3/07	< 15.00	12	< 0.00085	12	No	No
76	ASBESTOS-ST11-11/4/07	Southwest Area (sidewalk bridge level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/4/07	Southeast Area (sidewalk bridge level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-11/4/07	Northwest Area (street-level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/4/07	Firehouse #10 (roof level)	11/4/07	< 15.00		< 0.00078		No	No
	ASBESTOS-ST10-11/4/07	North Side Sidewalk Bridge	11/4/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST111-11/4/07	90 Trinity Place (roof level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/4/07	110 Greenwich Street (roof level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-11/4/07	Marriott Hotel, 38th Floor (roof level)	11/4/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST14-11/4/07	West Face - South end at corner (scaffolding level)	11/4/07	< 15.00		< 0.00080		No	No
	ASBESTOS-ST15-11/4/07	South Face - East end at corner (scaffolding level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-11/4/07	East Face - North end at corner (scaffolding level)	11/4/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST17-11/4/07	North Face - West end at corner (scaffolding level)	11/4/07	< 15.00	12	< 0.00085	12	No	No
77	ASBESTOS-ST1-11/5/07	Southwest Area (sidewalk bridge level)	11/5/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST2-11/5/07	Southeast Area (sidewalk bridge level)	11/5/07	< 13.00		< 0.00079		No	No
	ASBESTOS-ST4-11/5/07	Northwest Area (street-level)	11/5/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST5-11/5/07	Firehouse #10 (roof level)	11/5/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST10-11/5/07	North Side Sidewalk Bridge	11/5/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST111-11/5/07	90 Trinity Place (roof level)	11/5/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST12-11/5/07	110 Greenwich Street (roof level)	11/5/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-11/5/07	Marriott Hotel, 38th Floor (roof level)	11/5/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-11/5/07	West Face - South end at corner (scaffolding level)	11/5/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/5/07	South Face - East end at corner (scaffolding level)	11/5/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-11/5/07	East Face - North end at corner (scaffolding level)	11/5/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-11/5/07	North Face - West end at corner (scaffolding level)	11/5/07	< 13.00	12	< 0.00082	12	No	No
78	ASBESTOS-ST1-11/6/07	Southwest Area (sidewalk bridge level)	11/6/07	< 13.00		< 0.00082		No	No

ROUND NO.	TRC Field Sample No.	Sampling Location	Air Sample Collection Start Date	Asbestos AHERA Concentration (S/mm2)	Total No. of TEM Samples collected & analyzed / round	Asbestos PCME Concentration (f/cm3)	Total No. of PCMe Samples collected & analyzed / round	Exceeds Target	Exceeds EPA
	Target Air Quality Levels			NA		0.0009		Air Quality	Site Specific
	EPA Site Specific Trigger Levels			70		NA		Levels	Trigger Levels
	ASBESTOS-ST2-11/6/07	Southeast Area (sidewalk bridge level)	11/6/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST4-11/6/07	Northwest Area (street-level)	11/6/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST5-11/6/07	Firehouse #10 (roof level)	11/6/07	< 15.00		< 0.00078		No	No
	ASBESTOS-ST10-11/6/07	North Side Sidewalk Bridge	11/6/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-11/6/07	90 Trinity Place (roof level)	11/6/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/6/07	110 Greenwich Street (roof level)	11/6/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-11/6/07	Marriott Hotel, 38th Floor (roof level)	11/6/07	< 15.00		< 0.00081		No	No
	ASBESTOS-ST14-11/6/07	West Face - South end at corner (scaffolding level)	11/6/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST15-11/6/07	South Face - East end at corner (scaffolding level)	11/6/07	< 15.00		< 0.00077		No	No
	ASBESTOS-ST16-11/6/07	East Face - North end at corner (scaffolding level)	11/6/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST17-11/6/07	North Face - West end at corner (scaffolding level)	11/6/07	< 13.00	12	< 0.00083	12	No	No
79	ASBESTOS-ST1-11/7/07	Southwest Area (sidewalk bridge level)	11/7/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST2-11-7-07	Southeast Area (sidewalk bridge level)	11/7/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST4-11/7/07	Northwest Area (street-level)	11/7/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST5-11/7/07	Firehouse #10 (roof level)	11/7/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST10-11/7/07	North Side Sidewalk Bridge	11/7/07	< 13.00		< 0.00084		No	No
	ASBESTOS-ST11-11/7/07	90 Trinity Place (roof level)	11/7/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST13-11/7/07	Marriott Hotel, 38th Floor (roof level)	11/7/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-11/7/07	West Face - South end at corner (scaffolding level)	11/7/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST15-11/7/07	South Face - East end at corner (scaffolding level)	11/7/07	< 15.00		< 0.00079		No	No
	ASBESTOS-ST16-11/7/07	East Face - North end at corner (scaffolding level)	11/7/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-11/7/07	North Face - West end at corner (scaffolding level)	11/7/07	< 13.00	11	< 0.00084	11	No	No
80	ASBESTOS-ST1-11/8/07	Southwest Area (sidewalk bridge level)	11/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST2-11/8/07	Southeast Area (sidewalk bridge level)	11/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST4-11/8/07	Northwest Area (street-level)	11/8/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST5-11/8/07	Firehouse #10 (roof level)	11/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST10-11/8/07	North Side Sidewalk Bridge	11/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST11-11/8/07	90 Trinity Place (roof level)	11/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/8/07	110 Greenwich Street (roof level)	11/8/07	< 13.00		< 0.00086		No	No
	ASBESTOS-ST13-11/8/07	Marriott Hotel, 38th Floor (roof level)	11/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST14-11/8/07	West Face - South end at corner (scaffolding level)	11/8/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/8/07	South Face - East end at corner (scaffolding level)	11/8/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST16-11/8/07	East Face - North end at corner (scaffolding level)	11/8/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST17-11/8/07	North Face - West end at corner (scaffolding level)	11/8/07	< 13.00	12	< 0.00081	12	No	No
81	ASBESTOS-ST1-11/9/07	Southwest Area (sidewalk bridge level)	11/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST2-11/9/07	Southeast Area (sidewalk bridge level)	11/9/07	< 13.00		< 0.00085		No	No
	ASBESTOS-ST4-11/9/07	Northwest Area (street-level)	11/9/07	< 13.00		< 0.00080		No	No
	ASBESTOS-ST5-11/9/07	Firehouse #10 (roof level)	11/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST10-11/9/07	North Side Sidewalk Bridge	11/9/07	< 13.00		< 0.00083		No	No
	ASBESTOS-ST11-11/9/07	90 Trinity Place (roof level)	11/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST12-11/9/07	110 Greenwich Street (roof level)	11/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST13-11/9/07	Marriott Hotel, 38th Floor (roof level)	11/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST14-11/9/07	West Face - South end at corner (scaffolding level)	11/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST15-11/9/07	South Face - East end at corner (scaffolding level)	11/9/07	< 13.00		< 0.00082		No	No
	ASBESTOS-ST16-11/9/07	East Face - North end at corner (scaffolding level)	11/9/07	< 13.00		< 0.00081		No	No
	ASBESTOS-ST17-11/9/07	North Face - West end at corner (scaffolding level)	11/9/07	< 13.00	12	< 0.00081	12	No	No
					890		890		

